

Report No. RPT-5103-00

BC Safety Authority – Incident Investigation – Jurisdiction and Role

BC Safety Authority administers the *Safety Standards Act* on behalf of the Province of British Columbia¹. The *Safety Standards Act* and associated Regulations apply to the following products and persons doing regulated work on these products:

(i) amusement devices;

(ii) passenger ropeways and passenger conveyors;

(iii) boilers and boiler systems;

(iv) electrical equipment;

- (v) elevating devices;
- (vi) gas systems and equipment;
- (vii) pressure vessels;
- (viii) pressure piping;
- (ix) refrigeration systems and equipment; and

(x) any other regulated product specified in the regulations.

Incidents involving products or work subject to the *Safety Standards Act* are required to be reported in accordance with Section 36 of the *Act*. BC Safety Authority investigates these incidents in accordance with Section 37 of the *Act* and may appoint persons to assist with an investigation.

The role of BC Safety Authority with respect to the investigation of incidents is to understand relationships between incidents, equipment and work that are subject to the *Safety Standards Act*. It is our aim for these investigations to prevent the recurrence of similar incidents and to initiate improvements toward the management of safety risks with regulated equipment and work. Often, these investigations are conducted in cooperation with other agencies including Fire Officials, WorksafeBC, police or RCMP and the Coroners Service.

This investigation report does not address issues of enforcement action taken under the *Safety Standards Act*. Any regulatory compliance activities arising from this incident will be documented separately. Investigations may or may not result in any enforcement action.

¹ Some municipalities administer portions of the *Safety Standards Act*. The Province of British Columbia delegated partial administration of the *Safety Standards Act* to a number of local governments. The following local governments have administrative responsibility for the electrical technology: City of Burnaby, City of North Vancouver, City of Surrey, City of Vancouver, City of Victoria, Corporation of the District of Maple Ridge, District of North Vancouver, and Municipality of West Vancouver. The following local governments have administrative responsibility for the gas technology: City of Burnaby, City of Kelowna, City of North Vancouver, City of Richmond, City of Vancouver, Corporation of the District of Maple Ridge, and District of North Vancouver. Local governments that administer gas assessments programs for detached dwellings with gas services at a pressure of 14.0 kPa gauge or less with a total connected load for the meter of 120kW or less.

Contents

Incident Synopsis	3
Summary	3
Site Information	6
Overview of Site and Regulated Passenger Ropeway Equipment	6
Description of the Ropeway System	7
History of Incidents Occurring at the Site	9
Environmental Conditions at the Site	10
Location of Incident Along the Chairlift Right of Way	11
Investigation	11
Tensioning System	12
Haul Rope Stretch	18
Rope Catching Device	19
Passenger Carriers	22
Investigation Conclusions	26
Root Cause and Contributing Factors	27
Recommendations	27

Appendices

Appendix A:	Blue Chairlift Specifications	A-1
Appendix B:	Reported Incidents	B-1
Appendix C:	Engineering Specialties Group Investigation Report	C-1
Appendix D:	Timeline	D-1

Incident Synopsis

On March 1, 2014 at approximately 11:00 am a deropement occurred at tower #2 on the Blue Chairlift at Crystal Mountain Resort ski area located approximately 30 kilometers west of the city of Kelowna, British Columbia. A deropement occurs when the wire rope that carries and moves passenger carriers falls off of the tower equipment that supports it.

The deropement caused four passenger carriers to fall to the snow surface injuring four people who required hospitalization. Media reports later identified two additional injured passengers that received bruising resulting from the deropement.

The incident caused extensive damage to five passenger carriers. Haul rope and tower sheave assembly components received minor damage.

Summary

BC Safety Authority dispatched safety officers and the provincial safety manager for passenger ropeways to the ski area to evaluate and determine which chairlift system components, operations practices or passenger behaviors may have contributed to this incident.

BC Safety Authority contracted an independent company, Engineering Specialties Group (ESG), to assist with further on site investigation and data collection. ESG also provided further analysis on all findings and provided technical information where documentation gaps existed for the Blue Chairlift at Crystal Mountain Resorts Ltd (CMRL).

The Blue Chairlift is a fixed-grip double chair lift manufactured by Mueller Lifts and installed in 1967. The Blue Chairlift design carries passengers from the loading station at the bottom, over a span of 815 meters and a geographical elevation gain of 175 meters, to the unload station at the top.

The lift incorporates 85 carriers that are attached to the haul rope via a fixed-grip attachment and spaced at 19 meter intervals.

Tension is required in the haul rope to ensure that the haul rope remains on the sheave assemblies and bull wheel, that the haul rope will not slip during braking, and that passenger movement and loading will not result with unstable and bouncing carriers.

A tensioning system applies tension through the use of a suspended counterweight. Monitoring circuits are used to ensure that elements of the tensioning system are within positional limits to ensure proper tension is always applied to the haul rope. BC Safety Authority investigators found that the counterweight was in contact with the ground resulting in reduced tension within the haul rope. This reduced tension made the system more susceptible to chair swing which was an observed condition by employees during the season and described as being, at times, abnormal and excessive.

On the day of the incident, excessive chair swing caused an empty carrier to contact the leading edge of the rope catching device installed on tower #2. The force and manner of the contact pulled the haul rope off of the sheaves at tower #2 and over the rope catching device, causing the haul rope and carriers to fall to the ground.

BC Safety Authority concludes that the primary cause of the incident was low tension within the haul rope directly caused by the counterweight being in contact with the ground within the counterweight pit.

There were numerous contributing factors to this incident. These factors, discussed later in this report, include:

- improper set up of counterweight and carriage monitoring circuits
- exposure of the counterweight to contamination
- poor understanding relating to the elements of the tensioning system and haul rope dynamics
- shape and design of the rope catching device
- distance between towers #1 and #2 to dampen normal passenger loading dynamics.

BC Safety Authority makes the following recommendations to prevent similar incidents from occurring.

Recommendations to Owners of Passenger Ropeways Utilizing Suspended Counterweights

Recommendation #1:

All tension systems that use a suspended counterweight should incorporate a means for responsible personnel to visually confirm that the counterweight is suspended freely.

Recommendation #2:

All tension systems that use a suspended counterweight within a pit should incorporate a means to shelter the counterweight and the pit from contamination that may interfere with the free suspension of the counterweight.

Recommendation #3:

Conduct annual inspections of the counterweight and the area beneath counterweight to ensure the integrity of the counterweight and required clearances are maintained.

The investigation discovered that the bottom of the counterweight pit on the Blue Chairlift was contaminated with organic material and sections of the concrete counterweight that had broken off. This area is not visible without lifting the counterweight completely out of the pit area due to the tight clearances around it.

Recommendations to Owners and Operators of Passenger Ropeways

Recommendation #4:

Establish a system to train and certify ropeway mechanics to promote their understanding of the system elements necessary for safe operation and how to inspect and maintain those safety elements.

Personnel responsible for maintaining and operating the Blue Chairlift did not communicate an understanding of the relationship between haul rope tension and chair swing. Monitoring systems were not setup correctly to warn that the system was not in a safe state. The knowledge did not appear to be in place to understand visual indicators that could have led persons who understood the consequences of not having proper haul rope tension to make corrections.

Recommendations to Canadian Standards Association

Recommendation #5:

Evaluate the Canadian requirements for the effectiveness of rope catching devices related to capture of the haul rope in the event that it departs from tower sheave assembly equipment.

A study of deropement events reported to BC Safety Authority was published in BC Safety Authority's 2014 Sate of Safety Report. The study suggests that rope catching devices are not performing their intended functions as reliably as expected.

Recommendation to Owners of Passenger Ropeways Manufactured by Mueller Lifts

Recommendation #6:

Owners of existing Mueller passenger ropeways, who have not utilized the previously identified modification to the leading edge of tower and station sheave assemblies, should consult with the manufacturer and a professional engineer to determine if the modification should be implemented to prevent possible deropements.

Recommendation #7:

Owners of existing Mueller passenger ropeways, where an intermediate tower has not been added to the system between the station tower near the loading point and the following tower, should consult with the manufacturer and a professional engineer to determine if the installation of an intermediate tower should be added to decrease carrier swing susceptibility in the system.

Site Information

Overview of Site and Regulated Passenger Ropeway Equipment

Photograph 1 below shows an aerial view of the Crystal Mountain Resort site which consists of three passenger ropeway installations (Green T-Bar, Scenic Ridge and Blue Chair) and the various associated ski runs. All three passenger ropeways were subject to the *Safety Standards Act* on March 1, 2014. The red dotted lines on this photograph represent the passenger ropeway installations.

Other regulated equipment subject to the *Safety Standards Act* on this site, such as electrical and gas installations, are located in the administration and day lodge buildings. None of these installations were involved in the incident.



Photograph 1: Aerial view of the Crystal Mountain Resort Site obtained from <u>Google Maps</u> following the incident. The arrow indicates the Blue Chairlift installation.

BC SAFETY AUTHORITY Report No.: RPT 5103-00

Description of the Ropeway System

The Blue Chairlift is a fixed-grip double chair lift manufactured by Mueller Lifts and installed in 1967. The Blue Chairlift design carries passengers from the loading station at the bottom, over a span of 815 meters and a geographical elevation gain of 175 meters, to the unload station at the top. A total of seven towers with various sheave assembly configurations are used to support the haul rope throughout this circuit. The lift incorporates 85 passenger carriers (double chairs) that are attached to the haul rope via a fixed-grip attachment and spaced at 19 meter intervals. The basic profile of the Blue Chair is illustrated in figure 1 below while basic specifications are identified in Appendix A.

The portal tower, identified as tower #1 in the system, is a negative tower in that it applies a downward force on the haul rope from the sheaves at the exit of the loading station where the rope begins to climb to the next tower. Tower #2 is located 61 meters (200ft) from tower #1 with an elevation gain of approximately 19 meters (62 ft) for the haul rope. The lift system is powered by a 100 horsepower diesel motor located at the bottom drive station. The motor applies rotational power to the bottom bull wheel through a drive system. Speed is manually controlled by the lift operator, located at the bottom loading area. Power can be disconnected from the lift through a system of manual STOP switches or automatic monitoring safety circuits.

Automatic safety circuits monitor a number of system elements to ensure safe operation and configuration. Sheave assemblies incorporate a switch on the entry sheaves that is activated if the haul rope fails to apply weight to the sheave. Position sensors monitor elements of the tensioning system necessary to maintain tension in the haul rope.

Tension is required in the haul rope to ensure that the haul rope remains on the sheave assemblies and bull wheel, that the haul rope will not slip during braking, and that passenger movement and loading will not result with carrier bouncing and instability. To apply tension to the haul rope, the bottom drive station is carriage-mounted on a rail and a counterweight pulls the carriage assembly backwards, resulting with tension in the haul-rope proportional to the weight of the counterweight. This is similar to pulling an elastic band with one finger to increase tension in the elastic. These elements of the tension system are illustrated in figure 2.

Position sensors monitor the location of the carriage to ensure it is located away from the end stops of the rail and to warn that the carriage has travelled beyond its normal operating range. Position sensors monitor the location of the counterweight to ensure it is not in contact with the ground or other structural limits of travel. Should free movement of the carriage or free suspension of the counterweight be impaired, tension would be decreased in the haul rope. If the carriage has travelled beyond its normal operating range, the position sensors may warn operators to investigate if the system is operating within required parameters.



Figure 1: Illustration of the Blue Chairlift – Profile and Top View

Note: Figure 1 was produced from field observations and drawings provided by the manufacturer. Figures are not to scale and intended for illustrative purposes only.



Figure 2: Drive station illustration

History of Incidents at the Site

No previous incidents reported in BC Safety Authority's database are related to deropements on the Blue Chairlift; however, we note occurrences in the years 1990 to 1998 related to swinging carriers.

One incident of note occurred February 20, 1991 where a passenger fell out of his carrier seat between tower #3 and tower #4 and sustained serious non-life threatening injuries. The injured passenger was interviewed and stated that his carrier had struck tower #2 and that was what caused him to come out of the carrier. No physical evidence was found in the investigation to indicate the carrier had struck the tower. The tension system was noted to be functioning at the time.

Reports in the media after the March 1, 2014 deropement identified a former employee of CMRL who claimed to be involved in a deropement incident on the Blue Chairlift in the early 1990s. The employee claimed that he and six other staff were on the chairlift but no one was hurt. A review of reported incidents was unable to locate any data to support this claim although it may have occurred and not been reported to Safety Engineering

Services². Management at CMRL was also asked about this incident reported in the media and they had no knowledge of its occurrence.

There does not appear to be any evidence linking the previous incidents to the one that occurred on March 1, 2014; although the data does indicate a history of carrier swing. A recommendation in the investigation of the February 20, 1991 incident identifies that the installation of a tower between the drive station and tower #2 may improve carrier stability. A listing of all reported incidents involving the Blue Chairlift is contained in Appendix B.

Environmental Conditions at the Site

On March 1, 2014 at 8:30 am, the environmental conditions noted on the Blue Chairlift daily lift log stated the temperature to be -10°C and snowing lightly. At 9:30 am, a second entry on this log noted the temperature to be -10°C and clear. No wind activity was noted on the log and none was reported to be present at the time of the incident.

The closest environment Canada weather station to CMRL with historical hourly weather data is located at the Kelowna Airport. The table below shows that at 11 AM a wind speed of 15 km/h and a temperature of -5°C were recorded.

				BRITI	ISH COLUMB	[A					
Lat	Latitude: 49°57'26.000" N			Longitude: 119°22'40.000"		2'40.000" W	Elevation:		on: 433.	433.10 m	
Climate ID:		1123939		WMO ID	: 71203	71203		TC ID			
Related Data Almanac Averages & Extremes (March 01) Daily Data (March 2014)				Additional Search Options Nearby Stations with Data Advanced Search			Download Data Hourly Data (March 2014) © CSV				
Previous	Day		2	014 🗸 Mar	ch 🔽 1	Go				Next Day	
	Temp °C	Dew Point Temp °C	Rel Hum %	ourly Data R <u>Wind Dir</u> 10's deg	eport for Marc <u>Wind Spd</u> km/h	h 1, 2014 <u>Visibility</u> km	Stn Press	<u>5 Hmdx</u>	Wind Chill	Weathe	
	2	2	2		2	2	2				
TIME											
00:00 <u>*</u>	-2.6	-15.2	38	2	15	16.1	95.86		-8	NA	
00:00 ± 01:00 ±	-2.6 -2.4	-15.2 -15.4	38 37	2	15 21	16.1 16.1	95.86 95.90		-8 -8	NA NA	
00:00 <u>+</u> 01:00 <u>+</u> 02:00 <u>+</u>	-2.6 -2.4 -2.9	-15.2 -15.4 -14.9	38 37 39	2 1 35	15 21 26	16.1 16.1 16.1	95.86 95.90 95.92		-8 -8 -10	NA NA NA	
00:00 <u>*</u> 01:00 <u>*</u> 02:00 <u>*</u> 03:00 <u>*</u>	-2.6 -2.4 -2.9 -3.5	-15.2 -15.4 -14.9 -16.4	38 37 39 37	2 1 35 35	15 21 26 26	16.1 16.1 16.1 16.1	95.86 95.90 95.92 95.89		-8 -8 -10 -11	NA NA NA NA	
00:00 ± 01:00 ± 02:00 ± 03:00 ± 04:00 ±	-2.6 -2.4 -2.9 -3.5 -3.8	-15.2 -15.4 -14.9 -16.4 -17.2	38 37 39 37 35	2 1 35 35 36	15 21 26 26 30	16.1 16.1 16.1 16.1 16.1	95.86 95.90 95.92 95.89 95.91		-8 -8 -10 -11 -11	NA NA NA NA NA	
00:00 ± 01:00 ± 02:00 ± 03:00 ± 04:00 ± 05:00 ±	-2.6 -2.4 -2.9 -3.5 -3.8 -4.1	-15.2 -15.4 -14.9 -16.4 -17.2 -16.5	38 37 39 37 35 38	2 1 35 35 36 34	15 21 26 26 30 30	16.1 16.1 16.1 16.1 16.1 16.1	95.86 95.90 95.92 95.89 95.91 95.93		-8 -8 -10 -11 -11 -12	NA NA NA NA NA NA	
00:00 ± 01:00 ± 02:00 ± 03:00 ± 04:00 ± 05:00 ± 06:00 ±	-2.6 -2.4 -2.9 -3.5 -3.8 -4.1 -4.5	-15.2 -15.4 -14.9 -16.4 -17.2 -16.5 -16.2	38 37 39 37 35 38 40	2 1 35 35 36 34 36	15 21 26 26 30 30 21	16.1 16.1 16.1 16.1 16.1 16.1 16.1	95.86 95.90 95.92 95.89 95.91 95.93 95.93		-8 -8 -10 -11 -11 -12 -11	NA NA NA NA NA NA NA	
00:00 ± 01:00 ± 02:00 ± 03:00 ± 04:00 ± 05:00 ± 06:00 ± 07:00 ±	-2.6 -2.4 -2.9 -3.5 -3.8 -4.1 -4.5 -4.9	-15.2 -15.4 -14.9 -16.4 -17.2 -16.5 -16.2 -16.2	38 37 39 37 35 38 40 41	2 1 35 35 36 34 36 35	15 21 26 26 30 30 21 26	16.1 16.1 16.1 16.1 16.1 16.1 16.1 16.1	95.86 95.90 95.92 95.89 95.91 95.93 95.97 95.97 96.01		-8 -8 -10 -11 -11 -12 -11 -12	NA NA NA NA NA NA NA NA	
00:00 ± 01:00 ± 02:00 ± 03:00 ± 04:00 ± 05:00 ± 06:00 ± 07:00 ± 08:00 ±	-2.6 -2.4 -2.9 -3.5 -3.8 -4.1 -4.5 -4.9 -4.8	-15.2 -15.4 -14.9 -16.4 -17.2 -16.5 -16.2 -16.2 -16.2	38 37 39 37 35 38 40 41 41	2 1 35 35 36 34 36 34 36 35 34	15 21 26 26 30 30 21 26 30	16.1 16.1 16.1 16.1 16.1 16.1 16.1 16.1	95.86 95.90 95.92 95.89 95.91 95.93 95.97 96.01 96.06		-8 -8 -10 -11 -11 -12 -11 -12 -12 -13	NA NA NA NA NA NA NA NA	
00:00 ± 01:00 ± 02:00 ± 03:00 ± 04:00 ± 05:00 ± 05:00 ± 07:00 ± 08:00 ± 09:00 ±	-2.6 -2.4 -2.9 -3.5 -3.8 -4.1 -4.5 -4.9 -4.8 -4.8	-15.2 -15.4 -14.9 -16.4 -17.2 -16.5 -16.2 -16.2 -16.2 -16.2 -15.7	38 37 39 37 35 38 40 41 41 41	2 1 35 35 36 34 36 35 34 35	15 21 26 26 30 30 21 26 30 24	16.1 16.1 16.1 16.1 16.1 16.1 16.1 16.1	95.86 95.90 95.92 95.89 95.91 95.93 95.97 96.01 96.06 96.10		-8 -8 -10 -11 -11 -12 -12 -11 -12 -13 -11	NA NA NA NA NA NA NA NA NA	
00:00 ± 01:00 ± 02:00 ± 03:00 ± 04:00 ± 05:00 ± 06:00 ± 07:00 ± 08:00 ± 09:00 ± 10:00 ±	-2.6 -2.4 -2.9 -3.5 -3.8 -4.1 -4.5 -4.9 -4.8 -4.4 -4.4	-15.2 -15.4 -14.9 -16.4 -17.2 -16.5 -16.2 -16.2 -16.2 -16.2 -15.7 -13.7	38 37 39 37 35 38 40 41 41 41 41 41	2 1 35 35 36 34 36 35 34 35 35	15 21 26 26 30 30 21 26 30 21 26 30 24 13	16.1 16.1 16.1 16.1 16.1 16.1 16.1 16.1	95.86 95.90 95.92 95.93 95.93 95.97 96.01 96.06 96.10 96.15		-8 -8 -10 -11 -11 -12 -11 -12 -13 -13 -11 -9	NA NA NA NA NA NA NA NA NA	
00:00 ± 01:00 ± 02:00 ± 03:00 ± 04:00 ± 05:00 ± 06:00 ± 07:00 ± 09:00 ± 10:00 ± 11:00 ±	-2.6 -2.4 -2.9 -3.5 -3.8 -4.1 -4.5 -4.9 -4.8 -4.4 -4.4 -4.5	-15.2 -15.4 -14.9 -16.4 -17.2 -16.5 -16.2 -16.2 -16.2 -16.2 -15.7 -13.7 -13.7	38 37 39 37 35 38 40 41 41 41 41 41 49 52	2 1 35 35 36 34 36 35 34 35 35 35 36	15 21 26 30 21 26 30 21 26 30 21 26 30 21 25 30 21 25 30 24 13 15	16.1 16.1 16.1 16.1 16.1 16.1 16.1 16.1	95.86 95.90 95.92 95.93 95.91 95.93 95.97 96.01 96.06 96.10 96.15 96.20		-8 -8 -10 -11 -11 -12 -11 -12 -13 -11 -11 -9 -10	NA NA NA NA NA NA NA NA NA NA NA	
00:00 ± 01:00 ± 02:00 ± 03:00 ± 04:00 ± 05:00 ± 07:00 ± 09:00 ± 10:00 ± 11:00 ± 12:00 ±	-2.6 -2.4 -2.9 -3.5 -3.8 -4.1 -4.5 -4.9 -4.8 -4.4 -4.4 -4.5 -5.0	-15.2 -15.4 -14.9 -16.4 -17.2 -16.5 -16.2 -16.2 -16.2 -15.7 -13.7 -12.9 -10.2	38 37 39 37 35 38 40 41 41 41 41 41 52 52	2 1 35 35 36 34 36 35 34 35 35 35 36 6	15 21 26 26 30 30 21 26 30 22 24 13 15 5	16.1 16.1 16.1 16.1 16.1 16.1 16.1 16.1	95.86 95.90 95.92 95.93 95.91 95.93 95.97 96.01 96.06 96.10 96.15 96.20		-8 -9 -10 -11 -11 -12 -11 -12 -13 -13 -11 -9 -10 -7	NA NA NA NA NA NA NA NA NA NA NA	

² Prior to BCSA's creation in 2004, the *Safety Standards Act* was administered by the Safety Engineering Services Division (Government of British Columbia). Incidents occurring before 2004 relating to equipment and work subject to the *Safety Standards Act* would have been reported to Safety Engineering Services.

Location of Incident Along the Chairlift Right of Way

The deropement occurred at tower #2 on the uphill rope side of the tower. The location of this tower in relation to the loading station is shown in figure 3. Tower #2 is 61 meters uphill from the portal tower, identified as tower #1 in the system, which is located just past the passenger loading point at the drive station. The height of tower #2 where the deropement occurred is approximately 10 meters.



Investigation

BCSA employees were dispatched to the site on the day of the incident. BCSA's investigation team was there to evaluate the passenger ropeway system and operation to determine what factors may have led to this incident. Compliance with the applicable regulations was also being assessed during the course of this investigation. Engineering Specialties Group (ESG), a company that specializes in the design, installation and operation of passenger ropeways, was contracted to provide assistance to BC Safety Authority for further on site investigations and an analysis of findings. The findings described below state the condition of the various systems on the passenger ropeway at the time of the investigation. The ESG report, Appendix C, will be relied upon to communicate the analysis of the state of these systems.

Tensioning System

<u>Design</u>

The Blue Chairlift utilizes a gravity counterweight tension system in order to achieve the required tension within the haul rope. A concrete counterweight is suspended such that it applies a force onto the bull wheel, moving the drive station carriage backwards on a set of rails until there is a balance between the tension in the haul rope and the suspended counterweight (see figure 2).

Because of the relatively low height of the bull wheel, the counterweight is suspended within a pit to allow for the geometry and relative movement of the counterweight. In order for the designed amount of tension to remain in the haul rope, the counterweight must be in free suspension at all times during operation.

At the time of the incident, CSA Z98-07 contained the following rules that were applicable to this installation and operation:

4.30.7 Tensioning system or carriage stop

A manually reset device shall stop the ropeway when the tensioning system (a) travels more than 150 mm beyond its normal operating range; and (b) reaches to within 150 mm of the physical limits of its travel.

12.4.1 Daily inspection

A daily inspection shall be conducted before passengers are transported. At a minimum, the inspection shall consist of the following:(b) an inspection to check that the tensioning carriage, counterweights, or other tensioning devices are functional and have adequate travel, with clearance at both ends of travel;

12.5 Tensioning and carriage systems

12.5.1.2

Counterweights shall be in full suspension at all times during operation.

There are two monitoring circuits that were intended to ensure the Blue Chairlift met the above requirements; the counterweight position and drive station carriage position monitoring circuits. These monitoring circuits ensure that the counterweight and the drive station carriage are not able to move into a position that could inhibit the proper function of the tensioning system or damage its components.

The counterweight position monitoring system consisted of a paddle-style limit switch and two actuators mounted to a pulley system that was rigged to the position of the counterweight. If the counterweight moved to a position that was either pre-determined to be too high or too low, the switch would be activated and power to the ropeway system removed.

The drive station carriage monitoring system consisted of an actuator attached to the carriage rail and a limit switch attached to the carriage. If the carriage moved backwards such that the limit switch contacted the actuator, the switch would be activated and power to the ropeway system removed.

Investigation Findings

Only the top of the counterweight is visible during operation. The position of the counterweight relative to the bottom of the pit is not visible as shown in figure 4. The top of the counterweight relative to the ground level was visible to employees at the time of the incident as shown in photographs 2 and 3 below.



Photograph 2: Top of counterweight as viewed on the day of the incident. Note: the arrow indicates ground level.



Photograph 3: Counterweight within pit. Position of counterweight is representative of the day of the incident

The lift mechanic stated that daily inspections for full suspension of the counterweight consisted of putting "my foot on the cable ensuring that the counterweight rocks and moves; ensuring it is not frozen in...that's about it....Sometimes when I can't move the cable with my foot and see the counterweight move I've gone to get a [pry] bar to ensure that it is free moving". The lift mechanic also stated that he had no reason to be concerned that the counterweight may be in contact with the bottom of the pit based upon his evaluations.

Measurements taken of the height of the counterweight, the position of the counterweight in the pit and the depth of the counterweight pit indicated that the counterweight was in contact with the bottom of the counterweight pit.

Upon inspection of the counterweight at the time of the investigation, it was discovered that the lower corner of the concrete block counterweight closest to the drive station carriage on the downhill side of the station was broken off and located at the bottom of the pit. The opposite bottom corner of the counterweight was also found to be missing but that broken section was not at the bottom of the counterweight pit. Material (organic decay, waste) was observed to be contaminating the bottom of the counterweight pit resulting in a build-up of approximately 4 inches in the middle of the counterweight pit as shown in Photograph 6.

The counterweight monitoring system was found to be rigged in such a manner that the limit switch would not be actuated with the counterweight on the bottom of the pit.

The distance between the rear of the drive carriage and its physical limit of travel on the carriage rails was found to be 185 mm. It was observed that with the lift chairs empty, the counterweight could not be lifted off the bottom of the pit without the carriage contacting the rear physical limit of travel. This result indicates that compliance to CSA Z98-07 4.30.7 (b) could not have been achieved during operation.

When asked about the condition of the monitoring circuits for the counterweight and carriage, the lift mechanic indicated that they were regularly checked to ensure that when actuated, they would stop the lift. The lift mechanic did state that the rigging and set-up of the monitoring circuits was not checked to ensure that they were set to actuate at the intended positions of the counterweight or carriage being too close to their limits of travel.

The lift mechanic indicated that the position of the carriage near its rear limit of travel and the typical position of the counterweight *"way down"* in the pit did not present any concern to him as long as the limit switches did not actuate.



Figure 4: Drive station tension system illustration – condition found during investigation Note: Figure 4 was produced from field observations and drawings provided by the manufacturer. Figures are not to scale and are intended for illustrative purposes only



Photograph 4: The Blue Chairlift Drive Station Tension System



Photograph 5: Bottom of counterweight pit at time of incident



Photograph 6: Bottom of Blue Chairlift counterweight pit



Photograph 7: Rear carriage monitoring system switch and actuator

Conclusions

The counterweight was in contact with the bottom of the counterweight pit. It is likely that the method to determine 'free suspension' of the counterweight was resulting with the counterweight pivoting on the broken section and contamination at the bottom of the pit, providing a false indication of 'free suspension'. The condition of the counterweight does not comply with CSA Z98-07 12.5.1.2.

Because of the contact between the counterweight and the bottom of the counterweight pit, it is very unlikely that the counterweight was providing the designed tension to the haul rope. This conclusion is supported by the sag ratios determined in the appended ESG report and the evaluation of the chair swing discussed later in this report.

The counterweight monitoring system was found to be incorrectly rigged such that it could not stop the ropeway system when the counterweight came to within 150mm of the bottom of the counterweight pit. This condition was not compliant to CSA Z98-07 4.30.7 (b) and directly contributed to the lift remaining operational with the counterweight in contact with the bottom of the pit.

While the drive carriage monitoring system was found to be rigged in such a manner that was not compliant to CSA Z98-07 4.30.7 (b), it did not contribute to a reduction of tension in the haul rope as the carriage did not likely reach the physical limits of its travel during operation.

Haul Rope Stretch

<u>Design</u>

The Blue Chairlift tension system is designed to accommodate a certain amount of haul rope stretch. When a haul rope is installed it is shortened to a length that optimizes as much carriage travel as possible to increase the time span to the first required rope shortening. Haul rope stretch is monitored by the tension system carriage monitoring switches that detect the carriage moving out of its normal operating range established during initial and five year loaded dynamic testing cycles. When limit switches are actuated the system is shutdown which prompts the knowledgeable person at the site to investigate. Haul rope stretch is most likely the cause when the effective length of the rear carriage travel has been reduced.

Haul rope stretch, or permanent elongation, is a condition that is caused by several factors. The most common and expected factor occurs within the first year of operation for newly installed haul ropes once the strands of the haul rope have worked their way into the fibre core. This action, caused by the constant radial pressure exerted by the strands on the core and the bending of the rope as it passes around and over sheaves, causes the rope to become thinner and longer. This elongation is an expected condition in fibre core wire ropes that is rectified by performing a shortening and re-splicing procedure so that the limitations of the tension system travel are not exceeded.

Temperature also influences the length of the haul rope and on days of operation with higher temperatures, increased rear carriage travel is typically noted. When significant changes in the rate of rope stretch are noted this can be an indication of internal core degradation, which is a factor used to evaluate haul rope replacement. The degradation of the internal core causes internal contact between rope strands resulting in diameter loss and internal strand wear referred to as knicking.

At the time of the incident, CSA Z98-07 contained the following rules that were applicable to monitoring for rope stretch:

11.13.2 Replacement criteria

The following criteria shall be used in addition to Clause 11.10 to evaluate the necessity for rope replacement:

(f) a significant increase in the lay length;

(g) a significant change in the rate of rope stretch; and

(h) the condition of the main haul rope splices.

12.5 Tensioning and carriage systems

12.5.1.5

The tensioning system setting or range shall be as designed for the number of carriers or the loading conditions.

Note: A change in the number of carriers or the loading conditions can necessitate a change in the tensioning system or range.

12.5.1.6

Tensioning ropes shall be adjusted to provide at least 150 mm of remaining carriage travel when the counterweight reaches its (a) lower limit of travel; and (b) upper limit of travel.

Investigation Findings

The counterweight was lifted during the investigation and the winch in the system was not able to lift it until the carriage was in contact with the rear limits. This indicates excessive haul rope stretch. The haul rope on the Blue Chairlift was new in 1998 and there is no record indicating that the rope was shortened after its installation. The non-destructive rope tests on file for this haul rope show that the diameter was acceptable and no anomalies to indicate internal core degradation were identified. Core degradation would have been evident if significant diameter loss was detected.

Conclusions

The elongation of the haul rope was mostly likely caused by normally expected rope stretch.

The tension system was no longer effective at maintaining correct haul rope tension. This was due to excessive permanent elongation of the haul rope that required the rope to be shortened in order for the tension system to perform its function.

The Rope Catching Device

<u>Design</u>

A rope catching or haul rope retention device is required to be installed on all passenger ropeway tower and station sheave assemblies. Its purpose is to catch the haul rope in the event that it falls off of the sheave assembly that supports it due to uncontrolled horizontal forces acting on the haul rope. The haul rope could leave the sheaves for a number of reasons such as misalignments, excessive wind acting on the system or a mechanical force caused by carrier contact from excessive swing. The current standard requires that this device be located no more than half the sheaves diameter below the haul rope.

On the Blue Chairlift at tower #2, a contoured angle bracket is attached at the entrance, middle and exit sections, shown in figure 5, on the outside of the sheave assembly's frame located approximately half a sheave diameter below the haul rope. This design is common to all Mueller chairlift installations. The Mueller design has a sharp 90° corner at its leading edge in the horizontal plane as shown in photograph 8.



Figure 5: Mueller 10-Sheave assembly illustration. Top view; Side view and Front-side view



Photograph 8: Blue Chairlift Rope Catcher at Tower #2

At the time of the incident, CSA Z98-07 contained the following rules that were applicable to the design of haul rope retention devices:

4.19.10.3 Haul rope retention

Means shall be provided to retain the haul rope to the outside of each sheave and sheave assembly if it leaves its normal running position. Such means shall be located not more than one-half of the sheave diameter vertically from the normal position of the rope.

This passenger ropeway installation was designed and constructed in 1967. The first edition of Z98, the passenger ropeways and passenger conveyors standard, was published in 1968 and identified that "rope catchers" needed to extend two and one-half rope diameters outside the sheave flanges and be installed to prevent vertical displacement of the rope by more than one sheave diameter. Part XI of the *Railway Act* was the applicable regulation for passenger ropeways in British Columbia at that time and it contained no design requirements for rope catching devices. The rope catching devices installed on the Blue Chairlift meet the requirements of the current adopted standard (Z98-07).

Investigation Findings

The 90° corner at the entrance to the sheave assembly was the subject of an instruction issued to Mueller chairlift owners that were in locations susceptible to high wind loading. The instruction allowed owners of these installations to modify the leading edge of the rope catcher so that it was less likely that damage or entrapment of the carrier hanger arm would occur in the event a swinging carrier made contact. A drawing that was provided by the manufacturer to instruct owners on how to perform this modification is shown in figure 6.

This modification was never performed on the Blue Chairlift due to a letter that was issued by Mueller Lifts to CMRL that stated if the hanger arms were replaced with a new design hanger arm with a profile that provided additional clearance then the modification was not necessary. The new design hanger arm was installed on the Blue Chairlift many years prior to this incident but the exact date of completion is not known. Figure 7 compares the profiles of the original and modified hanger arms.



Figure 6: Mueller Drawing Depicting the Rope Catcher Modification



Original Hanger Arm

Modified Hanger Arm

Figure 7: Hanger Arm Comparison

Conclusions

It is suspected that if the rope catcher design had been modified as per the instruction provided by the manufacturer then it is possible that the deropement at tower #2 may not have occurred. Even though the new design of hanger arm with improved clearance was installed, the amount of swing generated in this incident exceeded this additional clearance between the hanger arm and the entrance point to the rope catcher. This conclusion is drawn not only from the above analysis but also the analysis provided in the ESG report.

Passenger Carriers

<u>Design</u>

The blue chair lift incorporates 85 double-seat, fixed-grip attachment passenger carriers. From its attachment to the haul rope, the carrier's hanger arm extends upwards and outwards so as to allow for expected carrier swing to occur without inducing contact between any part of the carrier and the other parts of the lift.



Photograph 9: Double-seat carriers at tower #2 - photo taken June 2014

The deropement occurred at tower #2. The distance between tower #1 and #2 was 65 meters. The spacing between carriers was 19.5 meters, allowing for three carriers to be within the space between towers #1 and #2.

At the time of the incident, CSA Z98-07 contained the following rule that was applicable to this installation and operation:

6.4 Horizontal clearances

6.4.2

With any 15° longitudinal swing, 15° lateral swing, or a combination of the two, no contact shall be permitted between any part of the carrier and any part of the supporting structure, sheave assemblies, or rope.

Investigation Findings

Carrier swing can occur as a result of passenger loading, passenger movement on chair, wind, changes in speed, movement over towers, induced swing from other chairs or contact from an external object.

Chair swing can also be influenced by the distance between towers, location of the chair between towers and the amount of tension in the haul rope. The tension in the haul rope influences the amount of sag in the rope between towers.

Worn station sheave liners, tower sheave liners and grip components can cause misalignment conditions that also influence chair swing. Wear was noted on these components but was not thought to be as significant as other factors observed above.

At the time of the incident, there were no abnormal wind conditions, changes in speed introduced into the lift or contact with objects that would have induced a swing into carriers.

As described in the attached report from ESG, the measured amount of chair swing required to induce contact with the rope catcher was in excess of the required 15 degrees longitudinal and lateral swing. The chair complied with rule 6.4.2.

The amount of sag in the haul rope between towers #1 and #2, as well as between towers #2 and #3, was evaluated in the ESG report and was found to be at the limits of what is considered accepted practice. The high sag ratios are an indication of low tension in the haul rope.

Carrier swing angles were recreated at the tower #2 site and confirmed that carrier #15 first made contact with sheave assembly rope catcher at an inward angle of 27° and a backward angle of 33°. Photographs10 and 11 below illustrates the damage made to the chair hanger arm from contact with the rope catcher. Given this discovery, the chair swing experienced during the incident would have been abnormally excessive.



Photograph 10: Carrier #15 hanger arm damage from contact with tower #2 rope catcher



Photograph 11: Carrier #15 hanger arm damage as viewed looking away from the haul rope/tower

During an interview, when asked about chair swing, the lift mechanic stated that approximately a week prior to the incident he noticed *"excessive chair swing"*. The lift mechanic stated that he asked the lift operations supervisor about his chair swing observation who indicated that was *"status quo"* so the lift mechanic did not investigate further.

During an interview, when asked about chair swing in comparison to previous seasons of operation, an employee involved with lift operations stated that he *"had noticed some abnormally violent swinging"*. The employee stated that he and the general manager *"would stand for 20 minutes to see why [there was chair swinging] and couldn't see a reason"*. The employee also stated that *"the lift supervisor had also noticed abnormal swinging of the chairs as well" and that they would discuss possible reasons for "why is it doing that"*.

Upon follow-up, the general manager stated that "at no time since the start of the 2013-2014 operating season, did I observe chair swing that I would consider to exceed the typical operating parameters of the blue chair lift."

At the time of the incident, carrier #14 and carrier #16 were fully loaded with passengers while carrier #15 was empty as shown in figures 1 and 3.

Carrier #14 and carrier #16 were loaded by the lift operator at the drive station. The lift operator stated he witnessed no carrier swing that raised concerns as he watched the carriers leave the station after both loads.

Statements provided by the passenger in carrier #14 noted nothing unusual after loading the chairlift and that he and the other passenger in carrier #14 were unaware that anything was wrong until the deropement occurred.

The passengers in carrier #16 stated that nothing unusual was noted at the time of loading. One passenger in carrier #16 stated that as carrier #16 got closer to tower #2 carrier #15 directly ahead was swinging excessively and that he was concerned carrier #15 going to strike tower #2. He stated that he remembered nothing after that point until he was on the snow surface below pinned underneath carrier #16.

In June 2014, BC Safety Authority conducted an evaluation of the lift for chair swing. The tension system, speed and carrier loading were arranged in a manner that was representative of the system configuration at the time of the incident. With the lift running, as carriers #14 and #16 passed through the loading area, a chair bounce was introduced that was representative of what occurs during a typical passenger load.

As the loaded carriers progressed toward tower #2, a carrier swing was observed between towers #1 and #2. As carrier #15 entered the sheave assembly at tower #2, the swing of carrier #15 was observed to be excessive although no contact occurred between the carrier and the tower.

The counterweight of the tensioning system was then raised to a point where the full force of the counterweight was being applied to the haul rope. The evaluation was repeated as above. Both the carrier swing between towers #1 and #2 and the carrier #15 swing at tower #2 were observed to be significantly less than the representative configuration at the time of the incident.

Conclusions

Given the statements from employees of CMRL, the Blue Chairlift was experiencing chair swing at times that was characterized as excessive or abnormal.

Carrier #15 was observed by a passenger in carrier #16, directly behind, to have been swinging excessively as it approached tower #2.

Contact between the hanger arm of carrier #15 and the rope catcher on tower #2 was a result of chair swing. The chair swing was likely induced into carrier #15 by the normal loading and movement of passengers in carriers #14 and #16. Tension in the haul rope was insufficient to dampen the swing between towers #1 and #2.

Investigation Conclusions

The Blue Chairlift at Crystal Mountain Resort had its haul rope installed in 1998. Over time, normal and expected lengthening of the haul rope had occurred. The haul rope had likely never been shortened following its initial installation.

While the lift system is designed to accommodate an amount of haul rope lengthening, the carriage was near the limits of its travel and the counterweight had not been adjusted for the amount of lengthening that had occurred. The counterweight was found to be in contact with the bottom of the counterweight pit.

The monitoring circuits designed to detect and shut the lift down when the counterweight or the carriage is at or near their limits of travel were not set-up properly to detect the conditions for which they were intended.

With the counterweight in contact with the ground, the full amount of tension required was not applied to the haul rope during operation. The reduced haul rope tension made the lift more susceptible to chair swing.

During normal loading conditions, a small amount of chair swing had occurred when loading carriers #14 and #16. Between these two carriers, carrier #15 was empty. As the empty carrier #15 approached tower #2, the chair swing energy induced into it was undampened because of the low tension in the haul rope and its light weight relative to the loaded carriers.

The carrier swing induced into carrier #15 became excessive and when it entered the sheave assembly at tower #2, the carrier hanger arm struck the blunt leading edge of the rope catching device.

The forces associated with the contact between the hanger arm and the rope catcher pulled the haul rope off the sheaves and over the rope catching device, causing the haul

rope and the carriers with passengers to fall approximately 10 meters to the ground at tower #2.

Root Cause and Contributing Factors

BC Safety Authority concludes that the primary cause of the incident was low tension within the haul rope directly caused by the counterweight being in contact with the ground within the counterweight pit.

There were numerous contributing factors to this incident including:

- improper set up of counterweight and carriage monitoring circuits
- exposure of the counterweight to contamination
- poor understanding relating to the elements of the tensioning system and haul rope dynamics
- shape and design of the rope catching device
- distance between towers #1 and #2 to dampen normal passenger loading dynamics

BC Safety Authority makes the following recommendations to prevent similar incidents from occurring.

Recommendations

Recommendations to Owners of Passenger Ropeways Utilizing Suspended Counterweights

Recommendation #1:

All tension systems that use a suspended counterweight should incorporate a means for responsible personnel to visually confirm that the counterweight is suspended freely.

Recommendation #2:

All tension systems that use a suspended counterweight within a pit should incorporate a means to shelter the counterweight and the pit from contamination that may interfere with the free suspension of the counterweight.

Recommendation #3:

Conduct annual inspections of the counterweight and the area beneath counterweight to ensure the integrity of the counterweight and required clearances are maintained.

The investigation discovered that the bottom of the counterweight pit on the Blue Chairlift was contaminated with organic material and sections of the concrete counterweight that had broken off. This area is not visible without lifting the counterweight completely out of the pit area due to the tight clearances around it.

Recommendations to Owners and Operators of Passenger Ropeways

Recommendation #4:

Establish a system to train and certify ropeway mechanics to promote their understanding of the system elements necessary for safe operation and how to inspect and maintain those safety elements.

Personnel responsible for maintaining and operating the Blue Chairlift did not communicate an understanding of the relationship between haul rope tension and chair swing. Monitoring systems were not setup correctly to warn that the system was not in a safe state. The knowledge did not appear to be in place to understand visual indicators that could have led persons who understood the consequences of not having proper haul rope tension to make corrections.

Recommendations to Canadian Standards Association

Recommendation #5:

Evaluate the Canadian requirements for the effectiveness of rope catching devices related to capture of the haul rope in the event that it departs from tower sheave assembly equipment.

A study of deropement events reported to BC Safety Authority was published in BC Safety Authority's 2014 Sate of Safety Report. The study suggests that rope catching devices are not performing their intended functions as reliably as expected.

Recommendation to Owners of Passenger Ropeways Manufactured by Mueller Lifts

Recommendation #6:

Owners of existing Mueller passenger ropeways, who have not utilized the previously identified modification to the leading edge of tower and station sheave assemblies, should consult with the manufacturer and a professional engineer to determine if the modification should be implemented to prevent possible deropements.

Recommendation #7:

Owners of existing Mueller passenger ropeways, where an intermediate tower has not been added to the system between the station tower near the loading point and the following tower, should consult with the manufacturer and a professional engineer to determine if the installation of an intermediate tower should be added to decrease carrier swing susceptibility in the system.

Appendix A Blue Chairlift Specifications

Manufacturer	Mueller
Effective length (Slope length)	815m
Vertical rise	175m
Capacity	950 PPH
Design line speed	2.54 m/s
Prime mover	Diesel
Prime mover power rating	100HP
Speed control	Manual
Auxiliary	Volkswagen
Speed reducer	Kissling VKDS 680 S
Distance between carriers	19 metres
Number of carriers	85
Passengers per carrier	2
Carrier weight (empty)	111 lb
Number of towers	7
Location of drive	Bottom
Location of tension system	Bottom
Rotation direction	Clockwise
Drive bull wheel diameter	2.5m
Line gauge change at portal tower	2.96m (assemblies fleeted)
Line gauge change at tower #2	3.6m (assemblies fleeted)
Line gauge at tower #3	4.0m
Haul rope diameter	29mm
Haul rope nominal breaking strength	122,000 lb

Table A-1: Blue Chairlift Specifications

Table A-2: Blue Chairlift Sheave Configuration

Tower	Drive guide	1 Portal	2	3	4	5	6	7	Return guide
Up	2	10N	10	8	4+2	8	10	12	2
Down	2	10N	6	4	4+2	6	4	12	2

Appendix B Reported incidents

Incidents involving passenger ropeways are required to be reported to the Provincial Safety Manager. The following lists the reported incidents occurring on the Blue Chairlift.

Date	Brief summary
Jan 25, 1984	Lift mechanic doing repair to chair; lift overhead rollers fell out of place, striking head.
Jan 24, 1986 (1)	Starter solenoid failure; main drive would not start
Jan 24, 1986 (2)	Main drive shut down due to fan pump housing bearing seized; fan cut rad
Feb 4, 1987	Operator stepped on a nail at loading area
Dec 3, 1988	Passengers stranded 1 hour 45 minutes
Feb 8, 1990	Lift attendant lifted child from chair, sustained injury
Feb 9, 1990	[An individual] 'smacked in head by swinging chair' (sic)
Feb 20, 1991	Passenger fell from chair between towers 3 and 4; sustained injuries
Feb 27, 1990	Gear box failure
Feb 27, 1990	Gear box failure; output shaft suspected
Dec 9, 1990	Operator struck by swinging carrier
Feb 24, 1991	Passenger (skier) struck by swinging chair at loading
Dec 15, 1991	Main drive failure; output shaft-clutch-main drive broken shaft
Dec 23, 1992	No information
Dec 23, 1992	Hooked on station. Guide rail; staff downloading swung chair as it entered station
Dec 23, 1996	Main drive shut down; fuel line to main drive kinked
Jan 5, 1997	Main drive – clutch slipping
Jan 22, 1998	Incoming empty carrier caught on station guide; operator sat in carrier path did not see chair coming
Jan 8, 2000	Loud sound coming from drive station; mechanical (gearbox) failure
Dec 10, 2010	Mechanical breakdown on a chairlift main drive clutch assembly; passengers evacuated (evacuation drive)
Jan 19, 2012	Extreme low temperatures caused the chair lift's diesel engine to stop due to the fuel gelling. Passengers evacuated.
Mar 1, 2012	Main diesel drive on chairlift stopped due to a plugged fuel filter. Main drive fuel filter plugged with sediment after a recent fuel delivery. Passengers evacuated.
Dec 28, 2012	Two passengers loaded onto carrier #1; during loading the carrier slipped back on the haul rope, lift was not stopped by the operator. Passengers reported that the carrier continued to migrate backwards each time the carrier passed over tower sheaves.
Jan 17, 2013	Main shaft lower pulley failed; metal fatigue
Jan 31, 2013	Main drive engine would not start due to a faulty motor starter; passengers evacuated.
Feb 11, 2013	Emergency brake hydraulic line ruptured; passengers manually evacuated.

Table B-1: Reported Incidents

Appendix C Engineering Specialties Group (ESG) Investigation Report

ESG Report



November 18, 2014

British Columbia Safety Authority Suite 200, 505 6th Street New Westminster, BC, V3L 0E

Re: Crystal Blue Chair Deropement Accident Investigation Project #1538.01

Dear

Find enclosed our final report for the work performed in assisting you in the accident investigation of the deropement on the Blue Chairlift at Crystal Mountain that occurred on March 1, 2014.

Our conclusions from this investigation as detailed in the attached report are based on the review and analysis of data provided by the BCSA from their investigation, maintenance documentation from Crystal Mountain, Mueller drawings and testing, BCSA inspection reports and the investigation and analysis of ESG.

The Blue Chairlift which is under investigation for the incident that occurred on March 1, 2014 when a carrier, due to excessive swinging, impaled its hanger on the lead-in four sheave assembly cable catcher at tower 2, as describe in detail in Section 6 of this report. This impalement initiated the complete dislodging of the hauling cable from its normal operating position, thus causing four carriers to contact the snow surface two of which each had two passengers.

The focus of this report was to verify the original assumption that the carrier hanger contacted the cable catcher and initiated the dislodging of the hauling cable; and to determine why the carrier experienced this excessive swinging.

Based on the information provided in Section 6, Carrier Swing Analysis, it is the opinion of the authors that excessive swinging caused the hanger to be impaled on the cable catcher, be moved approximately 30.5 cm along the catcher while "slicing" through the hanger tube and derope from the sheave assembly just uphill of sheave #2 causing the rope to be pulled from sheave #3. This action occurred in less than 0.25 seconds causing a severe dynamic action of the rope as it contacted the end of the cable catcher.

In ESG's opinion it is highly probable that if the leading edge of the cable catcher had been modified to incorporate the bevel as shown in the Mueller Service Bulletin of November 11, 1983, the incident would not have occurred. This is not to minimize the extreme carrier swing



that was occurring just prior to the incident as was evidenced by the field measurements and the swing models shown in Section 6.

It is the opinion of the authors of this report the primary factor contributing to the carrier swing that initiated the contact with the cable catcher was the fact that the counterweight concrete block, reference Section 3.1, was not applying its total load to the carriage reeving and thus to the hauling rope. This was due to the fact that the concrete block was partially resting on debris in the bottom of the counterweight pit.

The decrease in haul rope tension that resulted caused the sags in the haul rope between the towers to increase producing design sag ratios in excess of 3.5% (maximum normally accepted in design practice) in spans above tower 2 and tower 3. Considering these sag ratios and with an empty carrier weighing approximately 111 pounds, relatively light, the system was inherently susceptible to dynamic action and thus the probability for excessive carrier swing was increased. From statements of the operating personnel, carrier swing had been extreme during the 2013-2014 ski season and from field observations carrier contact with tower 2 assemblies and structure was evident. Further from observations during the ESG investigation, the empty carrier swing was more when the counterweight load was reduced.

Further, the issue of carrier swinging was apparently well known by the operations staff. The following instruction is included in Operator Manual, "To load passengers, swing chairs slightly forward before loading, this action reduces or eliminates chair swinging and the possibility of striking tower #2."¹

Secondary factors that may have contributed to the accident include the distance from tower 1 where passengers are loaded to tower 2 of approximately 63 m. With a chair spacing of 19.5 m, there are 3 carriers in this span at the time of loading. In the opinion of the authors, good design practice for this system, would allow one carrier to be in this span. The dynamics imparted to carriers when loading could have been significantly damped with the first tower after loading within 35 m of tower 1. In addition a carrier that was heavier would be less susceptible to dynamic action initiated at other locations such as loading.

Since the probability of excessive carrier swing was increased when the haul rope tension was reduced by the counterweight partially resting on ground surface at the bottom of the pit, it is not clear from the investigation as to how long this condition had been existing. In the BCSA incident investigation, photo chronicle of March 3, 2014, it is noted in reference to picture #130, "Records indicate that the counterweight was last inspected by **Sector** on Nov 1.2013." ESG could not from the information that they were supplied find this reference. Therefore, it is unclear what was done during the inspection. In a BCSA inspection report dated November 16, 2009 one of the non-compliance items read as follows, "2-516 TENSIONING-COUNTERWEIGHT TO BOTTOM OUT BEFORE CARRIAGE HITS – Drop counterweight 30 cm, move counterweight actuator up 75 mm."

¹ "Lift Operator Manual", Part 1, Page 7, Item 4, 2013-2014 season, Crystal Mountain.



November 18, 2014 Page 3 of 3

During the ESG investigation, it was observed that raising the counterweight off of the pit bottom allowed the carriage to move closer to the downhill physical limit of travel. With the haul rope in its current condition at the time of the ESG investigation with the counterweight fully suspended, the carriage did not have enough travel to prevent it from contacting the downhill physical limit. It is estimated that if the counterweight had been fully suspended on the day of the incident, given the rope shortening due to the temperature difference, the carriage would have been approximately 18 cm further uphill.

In conclusion, the following recommendations are offered for consideration:

- 1. Complete a detailed inspection of the haul to determine if there is excessive inner strand nicking or wire breaks.
- 2. If the inspection above reports significant issues, replace the haul rope, if not re-splice the haul rope to provide adequate downhill carriage travel.
- 3. Modify or replace the counterweight system to provide daily visual inspection beneath the counterweight and to eliminate excessive friction in the reeving system.
- 4. Revise the profile to add a tower between existing tower 1 and tower 2.

Respectfully, Engineering Specialties Group

Enclosure(s):
CRYSTAL MOUNTAIN ACCIDENT INVESTIGATION

CRYSTAL MOUNTAIN, WEST KELOWNA, CANADA

BLUE CHAIRLIFT DEROPEMENT NOVEMBER, 2014



BLUE CHAIRLIFT DEROPEMENT

Project Information

Project:

Prepared for:

CRYSTALL MOUNTAIN BLUE CHAIRLIFT DEROPEMENT

BRITISH COLUMBIA SAFETY AUTHORITY

Passenger Ropeways & Amusement Devices 200-500 6th Street New Westminster BC V3L 0E1

Project Representative

Prepared by:

Engineering Specialties Group 8501 Turnpike Drive, Suite 106 Westminster, CO 80031

303.341.6248 engineeringspecialtiesgroup.com

Contact:

Project Reference:

ESG #1538.01 Path: C:\PROJ130824\1538.01 Crystall Mountain Deropement\Report\CYRSTALL MTN. BLUE CHAIRLIFT ACCIDENT INVESTIGATION.docx

CERTIFICATION

The technical material and data contained in this document were prepared under the supervision and direction of the undersigned, whose seal, as a professional engineer licensed to practice as such, is affixed below.



1.	INTRODUCTION									
	1.1	Overview	3							
	1.2	History	3							
		Table 1 – Equipment Data	3							
	1.3	Approach	3							
r										
Ζ.	KEV		4							
		Picture 2 – Tower 2 Opgoing	4							
		Picture 2 – Grip Damage	5							
		Picture 3 – Hanger Damage	5							
3.	SITE	INVESTIGATION	6							
	3.1	General Observations	6							
		Picture 4 – CW Missing Piece 2	6							
		Picture 5 – CW Missing Piece 1	6							
		Picture 6 – Downhill End of Carriage	7							
	3.2	Measurements at Tower 2	8							
		Picture 7 – Tower 2 Measurements Location #1	8							
		Picture 8 - Tower 2 Measurements Location #2	9							
		Picture 9 - Tower 2 Measurements Location #3	9							
		Picture 10 - Tower 2 Measurements Location #3	. 10							
	3.3	Observations of Loaded Carriers	.10							
		Picture 11 – Simulated Carrier Loads	. 10							
		Picture 12 - Simulated Carrier Loads	. 11							
	3.4	Preliminary Tower Location Survey	.11							
		Picture 13 – Survey Obtaining Measurement	. 12							
		Picture 14 – Survey Target	. 12							
	3.5	Carrier Inspection	.12							
		Picture 15 – Damaged Carrier 13	. 13							
		Picture 16 – Damaged Carrier 9	. 13							
		Picture 18 – Damaged Carrier 14	. 13							
		Picture 17 – Damaged Carrier 16	. 13							
		Picture 19 – Damaged Carrier 15	. 14							
		Picture 20 – Detail of Hanger 15 Damage	. 14							
		Picture 21 – Carrier Detail Measurements of Damage	. 14							
4.	ROP	ELINE CALCULATIONS	15							
5.	SHE	AVE ASSEMBLY REVIEW	17							
	5.1	Design of Rope Catcher	. 17							
	5.2	i ower #2 Upgoing Assembly	19							
		Picture 22- March 2 after Reroping	. 19							
		Picture 23 – March 3 – Lead In	. 19							
		Picture 24 – After Raising Counterweight	.20							
	- -	Picture 25 – Damage to Cable Catcher Uphill	.20							
	5.3	Summary	.21							
		Picture 26 – Damage to Cable Catcher Lead-In	. 21							

6.	CARRIER SWING ANALYSIS – Tower 2	
	Table 2 – Model Photo Group Description	22
7.	CONCLUSIONS	
APP	ENDIX A – ROPELINE CALCULATIONS	29
APP	ENDIX B – SERVICE BULLETINS	
APP	ENDIX C – SWING CLEARANCE MODELS	
APP	ENDIX D – MUELLER DRAWINGS	

1. INTRODUCTION

1.1 Overview

On March 1, 2014 while operating for passenger service, the hauling rope was dislodged from its normal operating position at tower number two on the upgoing side of the Blue Chairlift. The Blue Chairlift is a Mueller 2-passenger per carrier chair located at Crystal Mountain Resort near Kelowna, British Columbia. When the hauling rope was dislodged from its normal operating position, it was not retained in the sheave assembly rope catchers, thus causing a number of carriers to contact the snow covered ground surface.

This incident resulted in injuries to four passengers while damaging a total of five carriers. Initially the British Columbia Safety Authority (BCSA) determined that an empty carrier located between two fully loaded carriers contacted the entry point of the rope catcher at the uphill sheave assembly on tower 2 causing the complete deropement of the sheave assembly sending four carriers to the snow surface.

BCSA has asked Engineering Specialties Group (ESG) to assist BCSA in an investigation of the incident that includes a review of existing documentation; a site investigation; and necessary analysis as determined from the initial observations and field analysis.

1.2 History

The Blue Chairlift was installed in 1967 by Gerhard Müller A.G. of Dietlikon, Switzerland. The basic lift data is shown in Table 1.

CAPACITY	950 PPH	SPEED	1.85m/s @ 2100 rpm
VERTICAL RISE	175 m	LINE GAUGE	VARIES 2.5m TO 4.0m
HORIZONTAL LENGTH	810 m	CARRIER SPACING	19.5 m
SLOPE LENGTH	831 m	DRIVE LOCATION	Lower Terminal
LOAD INTERVAL	10.5 s	TENSION LOCATION	Lower Terminal
NO. OF CARRIERS	85	ROTATION	CW
CARRIER WEIGHT	111 lbs	NO. OF TOWERS	7
TOTAL TENSION	34,000 lbs	COUNTERWEIGHT	8,500 lbs Ratio 4:1
HAUL ROPE	1-1/8″Ø	NOMINAL STRENGTH	105,200 lbs
ROPE DESIGN FACTOR	4.99	MAXIMUM ROPE ANG.	21.37°

GENERAL SPECIFICATIONS

1.3 Approach

Table 1 – Equipment Data

ESG developed a list of documentation that they believed to be pertinent to their investigation including:

- 1. As-built survey of the cable at the centerline of the sheave assemblies on each side of the towers for both the station and elevation.
- 2. All materials in the accident investigation file that have been accumulated to date by BCSA.
- 3. Equipment data sheet for the Blue Chair.
- 4. Drawing of carrier assembly.
- 5. Drawing of sheave assemblies at portal and towers 1 and 2.
- 6. Operations Logs for the 2013-2014 operating season.

- 7. Maintenance Logs for the last two years.
- 8. Manufacturer Bulletins relative to sheave assemblies, chairs, deropement switches or cable catchers.
- 9. BCSA and Insurance Company Inspection reports for 2012-2014.

This list was forwarded to BCSA and the following information was received:

- 1. Mueller documents consisting of 21 drawings; service bulletins; a maintenance manual and parts book.
- 2. Daily operation logs for December, 2013; January, 2014; February, 2014 and March 1, 2014.
- 3. Maintenance Logs for 2011; 2012; 2013 and maintenance specifications.
- BCSA inspection reports for November 16, 2009; December 10, 2010; December 7, 2011; December 19, 2011; January 27, 2012; December 7, 2012; January 29, 2013 and December 11, 2013.
- 5. Photographs taken by BCSA personnel between March 1 & March 5, 2014 with narratives.

ESG reviewed the various documents received and developed a site investigation protocol. From information collected during the site visit, they completed a profile analysis and carrier swing analysis. All of the information was used to determine the primary issues that precipitated the incident.

2. **REVIEW OF DOCUMENTS**

The document review revealed the following important elements that helped form the accident scenario:

- 1. The carrier, #15, that contacted the lead-in edge of the cable catcher at tower 2 was empty and was located between two loaded carriers, #14 and #16.
- 2. The resulting complete deropement missed the catchers and sent carriers #13 through #16 to the snow surface.
- Carrier #9 was damaged as a result of the passengers bouncing out of the chair seat and slamming down. The chair seat flipped into the up position during the incident.
- The sheave assembly upgoing at tower 2 was comprised of 10 sheaves. The incoming rope catcher was bent at the outgoing end and the sheave #3 flange was broken on the outside. Reference Picture 1.
- 5. The damage to carrier #15 included a complete tear on the hanger just below the grip; a deformed hanger; indentations on the grip body and rope marks on the arm rest. Reference Picture 2 and 3.

Damage from Contact with the Haul Rope – During Deropement



Picture 1 – Tower 2 Upgoing

Damage from Contact with the Cable Catcher During Deropement

Damage from contact with sheave #3



Picture 2 – Grip Damage



Picture 3 – Hanger Damage

- 6. Original and modified profile drawings showing the distance from the loading point to tower 2.
- 7. Mueller Chairlift Bulletin showing drawing of modification of rope catcher with taper on leading edge. Mueller had apparently suggested that this modification should be permitted for chairlifts operating in very high wind conditions.
- 8. Daily lift logs indicating free movement of the counterweight in comparison to BCSA accident investigation noting that the counterweight was in contact with the ground below the counterweight.
- 9. Pictures showing relationship of the carriage limit switch, the end of travel of the carriage and the carriage position on the day of the incident.
- 10. Drawing showing lower terminal counterweight to carriage connection reeving.
- 11. Noted that Crystal trained their operators to swing chairs slightly forward just prior to the loading process to reduce chair swinging and the possibility of contacting tower 2.
- 12. BCSA inspection report dated November 16, 2009 asks Crystal to drop counterweight 30cm and move actuator up 75mm. Noted that BCSA Inspection reports did not indicate counterweight or carriage location issues subsequently.

3. SITE INVESTIGATION

ESG personnel conducted a site investigation on June 2-4, 2014. They were accompanied by personal from the BCSA and personal from Crystal Mountain Resort (CMRL). ESG personnel made general observations of the operation of the Blue Chairlift; took specific measurements at tower 2; made observations of loaded carriers as was documented at the time of the accident as they traveled between the loading station and tower2; performed a preliminary tower location survey and inspected various carriers including carrier #15.

3.1 General Observations

- 1. Observed chairlift operating with empty carriers. Noted that some chairs exiting the lower terminal bullwheel were swinging more than others.
- 2. The counterweight to carriage reeving was not as was shown on the drawing that had been provided. Instead of a 2-part connection to the counterweight there is a single connection.
- 3. Rear carriage wheels were not in place. Counterweight switch was not in place. These items had been removed during the initial post-accident site investigation by the BCSA personal.
- 4. Counterweight was not free to move. Could not see beneath the counterweight when first observed. Subsequently, the counterweight was raised and it was observed that two pieces at the bottom of the concrete block had dislodged. One piece was observed in the pit.





Picture 5 – CW Missing Piece 1

Picture 4 – CW Missing Piece 2

- 5. When the lift was loaded to simulate the loading conditions at the time of the incident, the carriage did not move with the counterweight in the position at the time of the incident.
- 6. The carriage was located approximately 6½ inches more to the downhill direction than the day of the incident.

- 7. When the counterweight winch was rotated 20 turns the carriage moved downhill 2 inches with no counterweight movement. The carriage was then returned to the previous location, thus moving uphill 2 inches.
- 8. The speed of the chairlift was check by timing 5 bullwheel revolutions and by measuring the rotational speed of a sheave at tower 2 upgoing. With the chairlift loaded as it was at the time of the incident and with the engine reading 2000 rpm, the bullwheel measurements were 1.78 m/s (meter per second) and the sheave measurements were 1.79 m/s. At 2100 rpm, the sheave measurement was 1.85 m/s. With the chairlift operating with all empty carriers and the engine at 2100 rpm, the speed was measured between 1.90 m/s and 1.94 m/s for two separate measurements of bullwheel revolutions.
- 9. When the counterweight was lifted and fully supported by the counterweight rope, the carriage moved downhill 4³/₄ inches. This inidcated the lack of the total force of the counterweight being applied to the carriage.



Picture 6 – Downhill End of Carriage

10. After operating the chairlift while the line survey was being completed, the carriage location was measured at 2½ inches downhill from match marks. This is an indication of inherent friction in the counterweight to carriage connection.

3.2 Measurements at Tower 2

On June 3rd measurements were taken at tower 2 including verification of sheave dimensions and carrier clearances at various locations and orientations along the sheave assembly. The carriers numbered 13, 14, 15 and 16 that had been damaged during the incident had been removed from the line. Carrier #60 was placed on the line at the location of carrier #15 at the time of the incident. The work carrier was placed 4m behind carrier #60. The first set of measurements was taken with the grip of carrier #60 located one-sheave radius from its entry to the first sheave as shown in the following picture.



Picture 7 – Tower 2 Measurements Location #1

These measurements were taken to get a general overall sense of the extent of carrier swing that would produce contact with the tower. The carrier was oriented at 21° back along the line and at 27° inward across the line. At this combination it appeared that the carrier would be well inside the line of the cable catcher.

The second set of measurements was taken with the carrier grip located approximately midway between sheaves 1 and 2 as shown in the following picture. The following measurements were recorded:

- 1. With the carrier hanging vertically, 2½-2¾ inches were measured between the hanger and the cable catcher.
- 2. First contact of the hanger with the cable catcher occurred when the carrier was oriented at 21° back along the line and at 18.5°-19° inward across the line.
- 3. With the carrier hanging vertically, first contact of the hanger with the cable catcher occurred when the carrier was oriented at 24° inward across the line.
- 4. A sheave in the assembly was measured: Diameter of the rim=317mm; diameter of the liner=325mm; and width of sheave=60mm.
- 5. For the pair beam the distance from the center of the sheave to center of beam was 20cm.

Various other dimensions of the assembly were recorded such that the as-built conditions would be properly represented when the carrier and assembly were modeled. It was observed that the 2-sheave assembly had a side plate only on the inside of the assembly, thus producing an "overhung" condition for the sheave bearings and pair bushing as well as reducing the stiffness of the 2-sheave assembly.



Picture 8 - Tower 2 Measurements Location #2

The third set of measurements was taken with the carrier grip located approximately 4 inches downhill from the center of rotation of the 10-sheave assembly. With the carrier hanging vertically, the distance between the center line of the hanger and face of tower ski tip deflector was measured at 49½ inches. With the carrier hanging vertically, the inward swing of the carrier produced contact of the chair seat support frame at approximately 16°. This location is as shown in the following picture.



Picture 9 - Tower 2 Measurements Location #3

With the carrier hanging vertically, 2½-2¾ inches were measured between the hanger and the cable catcher which is the same as was measured at the lead-in 2-sheave assembly.



Picture 10 - Tower 2 Measurements Location #3

3.3 Observations of Loaded Carriers

The initial observations were made on June 3^{rd} with carriers loaded with water to simulate the carriers loaded below Tower 4 at the time of the incident. The following are the carriers that were loaded with $18'' \times 18''$ box filled with water to a height of $14\frac{1}{2}''$:

Carrier #2 loaded both seats. Carrier #3 loaded one seat. Carrier #4 loaded one seat. Carrier #5 loaded one seat. Carrier # 9 position (#40 in place) loaded both seats. Carrier #14 position (#30 in place) loaded both seats. Carrier #15 position (#60 in place) unloaded. Carrier #16 position (#16 in place) loaded both seats.



It was noted before adding the above load that the carriage was located 6¼ inches further downhill than at the time of

Picture 11 – Simulated Carrier Loads

the original accident investigation in March. Based on calculations performed, this is due to the lengthening of the haul rope due to the difference in temperatures from March to June.

Further the height location of the counterweight was as it was on the day of the incident and based on the carriage movement noted in Section 3.1 above, the force of the counterweight to tension the haul rope was being reduced by the fact that the counterweight was partially resting on broken pieces of the counterweight that were laying in the bottom of the pit or was partially resting on the pit bottom.

Observations were made by swinging carriers #9, #14 and #16 as they were approaching the loading point or just prior. This test yielded carriers swinging at tower #2 with no visible risk of carrier contact with the assembly although the swing of the empty carrier between the two loaded carriers was more than desirable. This was repeated with similar results.

On June 4th additional carriers were loaded with similar loads to those of June 3rd. The additional carriers loaded are as follows:

Carrier #68 loaded both seats. Carrier #69 loaded one seat. Carrier #70 loaded both seats. Carrier #76 loaded one seat. Carrier #77 loaded both seats. Carrier #81 loaded both seats. Carrier #82 loaded both seats. Carrier #83 loaded both seats. Carrier #84 loaded one seat. Carrier #85 loaded one seat.



Picture 12 - Simulated Carrier Loads

This loading condition represented the loading condition at the time of the incident. The chairlift was operated and swing was induced into loaded carriers just uphill and downhill of an empty carrier. The swinging at tower 2 of the empty carrier appeared to be similar to that observed on June 3rd, excessive but no contact with the tower or sheave assembly was observed.

Subsequent, to these observations the counterweight was raised such that its full force was providing tension to the rigging between the bullwheel and the counterweight, thus applying the full available force to the haul rope considering the friction in the rigging.

The chairlift was operated and swing was induced into loaded carriers just uphill and downhill of an empty carrier. The swinging at tower 2 of the empty carrier appeared to be much less than that observed when the counterweight was at the bottom of the pit but no contact with the tower or sheave assembly was observed.

Please reference conclusions for consideration of these observations.

3.4 **Preliminary Tower Location Survey**

A survey was conducted to determine the relative location of the tops of the towers. With the information obtained, a preliminary as-built condition of the rope working points at each tower and terminal could be developed. This survey was completed using a Laser Technology TruPulse[™] 200 range finder that reads both distance and angle to a target. The TruPulse was operated using either a tripod for support or as a hand held device as seen in the following pictures.





Picture 14 – Survey Target Picture 13 – Survey Obtaining Measurement The results of the information obtained are presented in the information provided for the rope line calculations.

3.5 Carrier Inspection

Based on review of information initially gathered in the initial accident investigation by BCSA and confirmed by ESG, carrier #15 initiated the incident by swinging and catching on the incoming cable catcher at tower 2. Based on this assessment, detailed measurements and observations were performed of carrier #15 by ESG personnel. This data was used to construct a computer model of the carrier along with the sheave assembly and to define the carrier movement after contact prior to deropement. This analysis is presented in Section 6, Carrier Swing Analysis. The field measurements are represented by the following pictures.



Measurements were taken on several undamaged carriers to determine if the dimensions conformed to the drawings and to determine if the carriers exhibited reasonably consistent fabrication. No significant irregularities were discovered.

BCSA personnel had documented damage to carriers involved in the accident. This damaged is represented in the following pictures.



Picture 17 – Damaged Carrier 9



Picture 16 – Damaged Carrier 13



Picture 19 – Damaged Carrier 14



Picture 18 – Damaged Carrier 16



Picture 20 – Damaged Carrier 15

Carrier was empty and was caught and damaged by cable catcher. The seat was down and the arm rest was in the up position. The hanger was deformed and supported some of the weight of the haul rope. The profile shows that for the tower 2 deroped cases that the rope would be below the ground surface. There was severe hanger distortion as evidenced by the angle of the grip.



Picture 21 – Detail of Hanger 15 Damage



Picture 22 – Carrier Detail Measurements of Damage

Reference Appendix D for design details of carrier. During the BCSA investigation, it was noted that carrier hangers #38 and #47 had indications in the location shown in these pictures that would indicate that they had also contacted a cable catcher, most likely the same one involved in the incident. Further it was noted that when carrier 15 was removed from the hauling rope, the rope rotated 180° indicating inherent rope twist.

4. **ROPELINE CALCULATIONS**

A ropeline calculation and analysis has been performed on the Crystal Mountain Blue Chair using the **PROFILEXL** program. **PROFILEXL** is proprietary software developed by ESG staff for analysis of ropeway systems. The program is used to calculate fixed and detachable grip monocable ropeway systems where the carriers are spaced at even intervals along the rope. The program is based on approximating the shape of the rope in spans between the towers using parabolic geometry even though the actual shape of the rope in spans is hyperbolic. The approximation error is less than 1% where the sag ratio (ratio of center sag to span length) is less than about 5%. The analysis assumes distributed loading on the rope from individual carriers over the length of the span. Where there are more than three carriers in a span, the approximation error is also very small. Where there are fewer than three carriers in a given span, the program assumes the maximum possible load of one or two carriers in the span. In every case, information relative to a span is the span above the tower reference.

The data output from **PROFILEXL** is arranged with a cover sheet with general information about the lift. The input information is entered in the left column of the cover sheet and the calculated data is in the right column. The second page has the input location information for each rope point and tower along the lift line. The program then provides a calculation of the geometry of the lift, and the tensions and loads at each tower considering bare rope, empty carriers, and loaded carriers on pages 3-9. Pages 10 and 11 are special loading cases with an over tension case, empty carriers in adjacent spans case, under tension case, and single loaded span case. The last page is a summary of the loaded, empty carriers, and rope only cases for uphill and downhill on a single page.

The American B77.1 Standard requires that the ropeline calculation test the tower loading with a 50% increase in tension. The Z98 requires that the ropeline calculation test for a 30% increase and decrease in tension. The special tension cases allow for adjustment of the increase and decrease.

Blue Chair Original Design

A ropeline calculation has been prepared based on the original design profile and field adjustments made during the construction as provided by BCSA. The original paper profile drawing and field update lack certain details that would typically be included in an analysis of this type, but with some assumptions and hand scaling of the drawing, a complete profile calculation is possible.

The original design appears to have acceptable tower loading and tensions. There are two long spans above Towers 2 and 3 with high sag ratios. With adjacent spans having sag rations of 3.5% and 4%, the lift could have had dynamic carrier motion, with vertical rope motions in the big spans. A loaded carrier minimum shear ratio of more than 32 would help control dynamic motion.

Based on the updated profile from 1969, it appears that the as-built conditions did not match the original design from 1967 and a field modification was added. The hand calculations on the updated profile indicate that the load conditions were 154 pounds per sheave negative in the bare rope conditions after the modification. The ESG calculations do not corroborate that calculation. The field measurements of the tower locations do not match the profile locations. Using the field measurements from 2014, the tower local is similar to the hand calculations. Our hypothesis is that the tower was not located correctly during construction. That would cause the loading to be incorrect and initiate the field modification in 1969. It is possible that the Mueller personnel performing the modification were aware of the location error at Tower 4, but did not want to relocate the tower foundation and therefore did

not present that information on the profile. It would be necessary to have a detailed survey to verify that information.

Blue Chair As-Built Survey 2014

On June 4, 2014 a field observation and simple verification survey was performed by the ESG team. This survey was performed using hand held distance and angle measurements from tower top to tower top. This type of survey is typically used to verify installation according to plans, but is not precise enough for primary survey or construction. If detailed as-built information is needed or modifications are to be performed, it is recommended that a precise survey be performed using GPS or total station surveying equipment.

While this check survey indicates some differences in station and elevation for many towers, it would be necessary to have a slope angle error of more than 1° to make a significant change in the profile and loading. There are some differences on the order of 1°, but in general the loading is acceptable. The major difference is in the location of Tower 4. The field check indicates that Tower 4 is about 67 feet downhill from the location indicated on the profile drawing. With this location and elevation as measured, the tower loading is similar to that indicated on the modified profile from 1969. Based on this corroboration, it is believed that the tower was not properly located in the original construction. With combination sheave assemblies, this configuration appears to conform to the current Z98 requirements.

The upper terminal was also measured to be farther uphill than the original design drawing by 40-50 feet, but that does not seem to affect the profile significantly. The sag ratios in spans 2 and 3 are both about 3.5%. A sag ratio of 3.5% is about the maximum recommended and two adjacent spans with a sag ratio that high can contribute to dynamic rope motions during speed transitions.

Accident Condition Profile

A ropeline calculation approximating the conditions at the time of the accident has been developed. According to operator statements and reports, the chair was relatively lightly loaded at the time of the accident. The ski patrol evacuation report has 23 names plus 4 people involved at the accident site for a total load of 27 persons. That is about 31% of the maximum load of 86 seats.

Field observations by the ESG team indicate the tension system consists of a gravity counter weight at one end of a four-part reeving arrangement with the adjustment winch at the other end. This tension system requires the counter weight rope to circulate through all of the reeving sheaves to self-adjust. This type of arrangement is known to be subject to a large amount of friction and inertia during movement. Field observations of the counter weight noted that the weight block was at least partially resting on a broken piece of the block in the bottom of the pit. In order to simulate the minimum tension condition, the reeving force of the counter weight on the carriage has been reduced from 4(x) to 3(x) the block weight of 8,500 pounds, for a force of 25,500 pounds. The tension was then further reduced in order to shorten the length of the haul rope by 9 inches for carriage travel to duplicate the location of the carriage at the time of the accident. The resulting tension is 21,700 pounds. This is considered the minimum tension that would have been placed on the carriage.

In this reduced load and tension condition, the resulting sheave loading on Tower 2 is 2,978 pounds or about 300 pounds per sheave. The design assembly load with empty carriers is about 3,480 pounds, or about 350 pounds per sheave. While 2,978 pounds is a reduction in loading of about 16% from normal

loading with empty carriers, the load is still significant and should be adequate to maintain the rope in the sheave grooves in normal conditions.

The three sets of ropeline calculations can be found in Appendix A.

5. SHEAVE ASSEMBLY REVIEW

BCSA in the scope of work requested the following work items:

"Inspect the sheave assembly where the deropement occurred and the data collected to date by BCSA on this component. Provide a report on the conclusions of your analysis and how they may represent the system failure scenario that led to this incident. Inspect and review the design of the sheave assembly rope catchers on this installation including a review of all manufacturers' bulletins and instructions related to this component. Provide a report on the conclusions of your inspection and review and how they may represent a system failure that led to the incident under your professional engineering seal."

The following information from our investigation is provided to answer this request.

5.1 Design of Rope Catcher

Review of Standards

The design of the chairlift and the associated components was performed prior to 1967 the year that the system was installed at Mt. Last, now Crystal Mountain. It is not clear what standard was used to design the sheave assembly and cable catcher, but standards and practices that existed at the time required the following as a minimum:

- 1. Sheave grooves should be designed with deep flanges to discourage the rope from leaving the sheaves.
- Suitable guards should be installed to prevent the rope from falling into dangerous positions either within or outside of the tower structure in case the rope does leave the sheaves and suitable devices should be installed to stop the tramway in that event.
- 3. Rope grips should be designed in relation to the sheave groove so as not to contact sheave flanges during normal operation taking into consideration the anticipated amount of wear on the sheave grooves.
- 4. Rope grips, sheave flanges and hanger guides shall be designed so that grips cannot be derailed from sheaves if the carrier is swinging as it approaches or passes the tower.

Other than the statement in item 2 above, a cable catcher was not specifically required as was the case in subsequent standards. Many lifts supplied during this time did not have a separate cable catcher as is seen today and as was installed on the Blue Chairlift. Many of the chairlifts being constructed during this time frame used a design philosophy that if any single tower completely deroped that the carrier could not come in contact with the ground or snow surface. Obviously, this particular philosophy was not incorporated in the design of tower 2 on the Blue Chairlift, but cable catchers were provided.

Considering item 4 above, absolute safety is required since there is no reference to a maximum level of swinging or clearance requirements. In subsequent standards published after the installation of the Blue Chairlift, minimum swing clearance requirements were defined, minimum sheave loading conditions were provided and the requirement for absolute prevention of deropement was replaced

with the requirement for designs that minimized this possibility. Today the safety levels continue to evolve with the next generation being based on a Risk Assessment Standard.

The following is the current requirements of the Canadian Standard, CSA Z98-14.

- 1. Minimum Sheave Loadings:
 - a. Support Sheaves
 - i. -500N/sheave
 - ii. -2kN/assembly
 - iii. -10N x the sum of the slope lengths in the adjacent spans, in meters/assembly
 - b. Hold Down Sheaves
 - i. -500N/sheave + a loaded carrier/assembly
- 2. Means shall be provided to restrict the movement of the haul rope to the inside of each sheave and sheave assembly if the rope leaves the groove.
- 3. Means shall be provided to retain the haul rope to the outside of each sheave and sheave assembly if it leaves its normal running position. Such means shall be located not more than one-half of the sheave diameter vertically from the normal position of the rope.
- 4. The design of the sheave assembly and the means provided to comply with items 2 and 3 shall allow free passage of the haul rope and carriers while the rope is in or out of the normal position.
- 5. With any 15° longitudinal swing, 15° lateral swing, or a combination of the two, no contact shall be permitted between any part of the carrier and any part of the supporting structure, sheave assemblies, or rope. Alternatively, where these clearances are not met, guides shall be provided.

Manufacturer's Service Bulletins

November 21, 1983 – This was a general letter from Mueller Lifts to the Ministry of Transport showing a modification to the leading edge of the lead-in cable catcher that allowed a bevel in the leading outside edge of 12mm across the line by 50mm along the line. The letter stated that Mueller had had only one customer request this modification for a lift subjected to extreme wind condition and stated that the modification should be permitted on any Mueller lifts operating in very high wind situations.

March 7, 1994 – This was a letter from Mueller Lifts Ltd to the Ministry of Municipal Affairs in reference to Mueller Triple Chair (Blue Chairlift is a double), carrier clearance on sheave assemblies. There were two items discussed, the second item dealt with the above referenced, 1983 Bulletin. It stated in part, "The use of a field template may have resulted in a variance of the rounded outside portion of the rope catcher." The request was to check the swing clearance of 15 degrees.

March 25, 1997 – This was a letter to CMRL enclosing a service bulletin from the Swiss Manufacturer of Mueller Lifts and a drawing # 97.02.21 showing the situation on cable catchers on existing sheave assemblies. It stated, "If you have not made any modifications (to cable catchers), none are required."

These service bulletins can be found in Appendix B.

5.2 Tower #2 Upgoing Assembly

A general overall inspection of the 10 sheave, upgoing assembly at tower 2 was completed including pictures and measurements as detailed above. Consideration was also given to the initial assessment performed by BCSA where it was noted that the assembly was misaligned and to the detailed inspection of the assembly performed in the Mueller shop.

The following pictures show the misalignment of the 10 sheave, upgoing assembly at tower 2 at different points during the investigation of BCSA.



Picture 23- March 2 after Reroping



Picture 24 – March 3 – Lead In



Picture 25 – After Raising Counterweight

Damage to the sheave assembly cable catcher is shown in more detail in the following picture.



Picture 26 – Damage to Cable Catcher Uphill

Length of Contact of Chair Hanger with the Cable Catcher during Accident

First Contact of Rope with Cable Catcher during Accident Reference Carrier Swing Analysis Section It is not evident what the alignment of the sheave assembly was just prior to the incident on March 1, 2014. From the above pictures the following observations can be made:

- 1. The misalignment after the accident was such that if this had been the misalignment prior to the accident, the chairlift would not be recommended for operation.
- 2. When the haul rope is tensioned with the full weight of the concrete counterweight, the sheave assembly is not misaligned such that operation would not be possible.
- 3. The stiffness of the 10 sheave assembly may not be appropriate for the maximum loading.
- 4. The full weight of the concrete counterweight is not tensioning the haul rope in Picture 25, but the assembly is not misaligned as shown Pictures 22 and 23. This is probably due to the work performed in the Mueller Shop on March 7 and 10, 2014.

5.3 Summary

It is not evident that either the sheave assembly or cable catcher designs were inadequate or the primary contributing factors in causing the incident. These designs meet the minimum requirements of the current CSA Z-98 Standard. Further, it is not evident that misalignment contributed to initiation of the incident.

In ESG's opinion it is highly probable that if the leading edge of the cable catcher had been modified to incorporate the bevel as shown in the Mueller Service Bulletin of November 21, 1983, the incident would not have occurred. This is not to minimize the extreme carrier swing that was occurring just prior to the incident as evidenced by the field measurements and the swing models shown in Section 6.

Relative to misalignment, Picture 25 shows that most if not all of the damage caused by the deropement occurred on the outgoing end of the cable catcher. It would be most probable if misalignment shown in Pictures 22 and 23 had contributed, the rope would have started to derope at sheave number 1 or the lead-in sheave. The markings on the cable catcher at this point appear to be from a secondary contact of the rope after the start of the deropement or most likely from the "slicing" of the chair hanger since they are less severe and toward the outside of the cable catcher. This can be seen in the following picture.



First Contact Point of Hanger with Cable Catcher

Picture 27 – Damage to Cable Catcher Lead-In

6. CARRIER SWING ANALYSIS – TOWER 2

A computer model, using SolidWorks 2014[™], was developed to model the carrier and its relationship to the 10-sheave assembly at tower 2 during the incident with carrier #15 that caused the deropement. Carrier swing analyses were performed for two primary reasons, (1) to verify that the as-built condition at tower 2 conformed to the drawings and regulations and (2) to define the carrier movement through the tower assembly during the incident to conclude the sequence that led to the deropement.

SolidWorks 2014[™], a three-dimensional computer analysis and design software tool, was used to analyze the dynamics of the chair assembly. The software is able to analyze the motion of the chair as it passes over the tower to gain a better understanding of what occurred during the accident. In order to provide an accurate model, components were dimensioned based on drawings provided by BCSA. For components lacking drawings, dimensions were determined using photos taken on site. To ensure an accurate SolidWorks model, the design was verified against field notes recorded by ESG staff.

All of the models are represented in Appendix C. The models have been organized into "Photo" Groups detailed in the following table.

GROUP	DESCRIPTION
1	Chair backward angle is 0° and the grip is turned until contact is made with the rope catcher. The chair is located at location 2 along the line. The model shows that with the chair vertical and the inward contact angle is 19°.
2	Chair backward angle is 21°, grip is at location 2 along the line. Grip is turned to make contact to reproduce what was recorded in the field. The inward angle for this case is 20°.
3	Chair backward angle is 5°, grip is at location 2 along the line. Inward angle is modified until contact occurs with the rope catcher. Contact occurs when the grip is turned 19° inward.
4	Chair backward angle is 10°, grip is at location 2 along the line. Inward angle is modified until contact occurs with the rope catcher. Contact occurs when the grip is turned 19° inward.
5	Chair is 15 degrees back and grip is at location 2 along the line. Inward angle is modified until contact occurs with the rope catcher. Contact occurs when the grip is turned 20° inward.
6	Stem entry point puncture and rope catcher initial contact. Angle inward 27° and chair backward angle at 33°.
7	Not used in report
8	Chair seat frame positioned to make contact with tower. Located approximately 4 inches downhill from center of rotation. Inward angle 16°, Chair backward angle is 0°
9	Not used in report
10	Not used in report
11	Not used in report
12	Not used in report
13	Match geometry with Jason's Image 238. Witness marks on rope catcher showing path along rope catcher of carrier 15 to match damaged hanger. Inward angle of 32° and backward angle of 41°.
14	Possible de-ropement scenario: The rope grip moves 2 inches off of rope center line and 1 in below current rope grip position. Contact is made between the rope grip inner yoke plate hitting rope catcher located about the middle of 4 Beam. This could have created the witness marks found in the field. Backward angle is 1° and the inward angle is 24°
15	Not used in report
16	Restrainer bar in the closed position and contact is made between the downhill side of the bar and the rope. Inward angle of 16° and a backward angle of 45°.
17	Restrainer bar in the open position and contact is made between the uphill side of the bar and the rope. Inward angle of 10° and a backward angle of 40°.

Table 2 – Model Photo Group	Description
-----------------------------	--------------------

For the carrier swing analyses, the carrier locations were those detailed in Section 3.2. The following is a summary of those locations.

- 1. Location 1 The grip was located approximately 6 inches before entering sheave 1 (Pic 7).
- 2. Location 2 The grip was located approximately midway between sheaves 1 and 2 (Pic 8).
- 3. Location 3 The grip was located 4 inches downhill from the 10-sheave rotation center (Pic 9).

The following model summaries represent important aspects of the carrier and assembly interaction that support the conclusions.

Carrier Hanging Vertically at Location 2



Carrier Contact with Cable Catcher Field Measurement Verification Location 2



Carrier Contact with Tower Structure Field Measurement Verification Location 3



Carrier Contact with Cable Catcher at Initiation of Hanger Tear





Looking Uphill – Carrier at Contact with Cable Catcher

Carrier Contact with Cable Catcher at Completion of Hanger Tear



Accident Investigation Report



GRIP CONTACT WITH CABLE CATCHER AFTER DEROPEMENT



7. CONCLUSIONS

Since the accident investigation by BCSA continues, ESG has provided its conclusion from the investigation conducted and described in this report in a separate letter.

APPENDIX A ROPELINE CALCULATIONS

• =====================================	============	=						
** ProfileXL **								
Copyright 2011 by								
Revision: 7 MAR 2011								
CLIENT:	British Columbia S	Safetv Aut	hority					
AREA:	Crystal Mountain 16:29:44 Tir							
	Blue Chair	21-Jul-14 Date						
COMMENTS	Accident review	2. 00 20.0						
	Profile based on 1	969 doco	cuments					
' ====================================		:						
/ *** GENERAL INPUT DATA ***			*** CALCULATED DATA ***					
CALC UNITS(ENG/SI)	ENG		HORIZONTAL	2613.5 FT				
DRIVE (TOP/BOT)	BOT		VERTICAL	573.1 FT				
TENSION (TOP/BOT)	BOT		SLOPE	2681.4 FT				
ROTATION (CW/CCW)	CW		SLOPE ANGLE	12.37 DEG				
GRIP (FIX/DET)	FIXED			7.77 SEC				
			SPACING	63.42 FT				
INPLIT CAPACITY	950	РРН		927 1 PPH				
DESIGN SPFFD	490	FPM	NO. OF CARRIERS	85.00 CARR				
	490	FPM	RHO W/EMPTY CARR	3.88 I B/FT				
	-30 0	FT/S^2		9.24 R/FT				
	2	PASS		3 88 R/FT				
PASS/CARR DNHILL	2	PASS		5205 73 LB				
	2	PASS		2223.73 LD				
	0.2	FT		057 /8 LB				
	3.2			6/1 01 LP				
	3.0 111.00			041.91 LD				
	111.00							
	C0							
	24000.00			0.00 LB				
	34000.00			0203.21 LB				
	2.130			1581.07 LB				
	1.125			4771.54 LB				
	105200.00			18.1 HP				
	8.2021		POWER-EMPTY CARR.	22.5 HP				
	50	LB		80.9 HP				
	50	LB		4.98				
	25	LB		1.33				
SHEAVE MAX LOAD +	1000	LB		32.46				
SHEAVE MAX LOAD -	900	LB	DESIGN COUNTER WT	34000.00 LB				
SHEAVE SPACING-C.L.	1.313197636		I IENSION TI	14614.23 LB				
PASSENGER WEIGHT	170	LB	I ENSION T2	19385.77 LB				
	0.88		I ENSION T3	20967.44 LB				
FRICTION FACTOR	0.030		IENSION T3'	20867.44 LB				
METALIC AREA RATIO	0.442		ROPE METALIC AREA	0.559 SQ IN				
ELASTICITY MODULUS	1.310E+07	PSI	ROPE LENGTH-ROPE	5389.3 FT				
OVER TENSION RATIO	1.5		ROPE LENGTH-EMPTY	5390.8 FT				
MIN SHEAR RATIO	10		ROPE STRETCH EMPTY	0.2 FT				
MAX T1/T2 RATIO	1.9		CARR TRAV ROPE-EMP	0.6 FT				
LOAD(STD/MAXUP/MAXDN)	STD		ROPE LENGTH-LOADED	5396.2 FT				
** FOR SURFACE LIFTS ONLY			STRETCH EMP-LOAD	0.3 FT				
**SNOW FRICTION FACT	0.06	=	CARR TRAV EMP-LOAD	2.4 FT				
For aerial lifts, set TOW-BAR				0.00 LB				
and ROPE-SEAT length to 1.0.			**BAR ANGLE BETA	0.0 DEG				
**ROPE-SEAT HEIGHT	1	FT	**RHO VERTICAL	0.00 LB/FT				
**TOW BAR LENGTH	1	FT	**RHO TANGENTIAL	0.00 LB/FT				
		=	== ==================================					

	DATE:	21-Jul-14						Page 2				
	TIME:	16:29:44										
	UPHILL T	OWER POINT	S		DOWNHI	LL TOWER PC	NTS					
701/55			CTF TO	BATTER			CTF TO	BATTER	ACTUA		CALCULATE	D
TOWER	STATION	ELEVATION	ROPE PT.	ANGLE	STATION	ELEVATION	ROPE PT.	ANGLE	SHEAVES	SHEAVES	SHEAVES	SHEAVES
NUMBER	Х	Z	LENGTH HT	DEGREES	Х	Z	LENGTH HT	DEGREES	UPHILL	DOWNHILL	UPHILL	DOWNHILL
DR BW	-36.40	10.59	10.55	0.00	-36.40	10.59	10.55	0.00	*** ***	*** ***	4 T/2FR	4 T/2FR
T1 PORT	23.60	10.59	9.84	0.00	23.60	10.59	9.84	0.00	10 N	10 N	6 D	4 T/2FR
T2	213.20	71.51	32.81	0.00	213.20	71.51	32.81	0.00	10 S	6 S	4 S	4 T/2FR
Т3	694.50	154.13	37.73	0.00	694.50	154.13	37.73	0.00	8 S	4 S	4 S	4 T/2FR
Τ4	1277.50	285.20	37.50	0.00	1277.50	285.20	37.50	0.00	4 S/2N	4 S/2N	4 S	4 T/2FR
T5	1528.40	351.20	26.90	0.00	1528.40	351.20	26.90	0.00	8 S	6 S	4 S	4 T/2FR
Т6	1997.70	480.93	37.73	0.00	1997.70	480.93	37.73	0.00	10 S	4 S	4 S	4 T/2FR
Τ7	2460.60	580.51	32.81	0.00	2460.60	580.51	32.81	0.00	12 S	12 S	4 S	4 T/2FR
UT GD	2570.10	583.65	10.55	0.00	2570.10	583.65	10.55	0.00	2 S	2 S	4 S	4 T/2FR
UTBW	2577.10	583.65	10.55	0.00	2577.10	583.65	10.55	0.00	*** ***	*** ***	4 S	4 T/2FR

DATE: 21-Jul-14 TIME: 16:29:44

Page 3

TOWER NUMBER	UP CHORD LENGTH	HILL CHORD ANG DEGREES	DOW CHORD LENGTH	NHILL CHORD ANG DEGREES	CARRIER C TO GR UPHILL	LEARANCE OUND DOWNHILL	STATION XCTF	FOUNDATION ELEVATION ZCTF	CTF-GND DISTANCE	CROSS SLOPE DEGREES	MAXIMUM R ACCELERAT UPHILL	ADIAL TION - G DOWNHILL
DR BW	60.00	0.00	60.00	0.00	1.39	1.39	-36.40	0.04	#VALUE!	0.00	0.00	0.00
T1 PORT	199.15	17.81	199.15	17.81	0.69	0.69	23.60	0.75	0.05	0.00	0.05	0.05
T2	488.34	9.74	488.34	9.74	23.61	23.61	213.20	38.70	0.00	0.00	0.06	0.07
Т3	597.55	12.67	597.55	12.67	28.53	28.53	694.50	116.40	0.00	0.00	0.06	0.03
T4	259.44	14.74	259.44	14.74	28.30	28.30	1277.50	247.70	0.00	0.00	0.10	0.03
T5	486.90	15.45	486.90	15.45	17.70	17.70	1528.40	324.30	0.00	0.00	0.04	0.02
T6	473.49	12.14	473.49	12.14	28.51	28.51	1997.70	443.20	-0.02	0.00	0.05	0.08
T7	109.55	1.64	109.55	1.64	23.61	23.61	2460.60	547.70	0.00	0.00	0.04	0.03
UT GD	7.00	0.00	7.00	0.00	1.35	1.35	2570.10	573.10	0.00	0.00	0.09	0.06
UTBW	0.00	0.00	2642.36	0.00	1.35	1.35	2577.10	573.10	0.00	0.00	0.00	0.00

Г

Page 4

DATE:	21-Jul-14
TIME:	16:29:44

ROPE ONLY

TOWER NUMBER	UPHILL TENSION TENS ALPH	UPHILL TENSION TENS BETA	UPHILL ROPE ANG ALPHA -[UPHILL ROPE ANG DEG- BETA	UPHILL REACTION ANGLE-DEG	UPHILL MAIN AXEL REACTION	UPHILL LOAD PER SHEAVE	UPHILL SAG TN+1 Fmup	UPHILL SAG CLEAR Gfm	UPHILL SAG STAT Xfm	UPHILL SAG ELEV Zfm	UPHILL ARC LENGTH
DR BW	16488.71	16488.71	0.00	-0.22	-90.11	63.87 *	**	0.06	10.47	-6.40	10.53	60.00
T1 PORT	16488.71	16634.75	0.22	17.12	98.67	-4867.75	-486.77	0.63	20.33	118.40	40.42	199.15
T2	16764.50	16856.85	18.50	8.00	-76.75	3078.55	307.85	3.75	34.59	453.85	109.07	488.42
Т3	17032.84	17040.69	11.46	10.58	-78.98	261.90	32.74	5.53	37.63	986.00	214.13	597.69
Τ4	17319.87	17327.76	14.72	13.85	-75.71	262.95	65.74	1.03	30.86	1402.95	317.17	259.45
T5	17468.34	17484.81	15.61	13.82	-75.29	549.03	68.63	3.58	30.94	1763.05	412.48	486.97
Т6	17761.14	17821.76	17.06	10.56	-76.19	2020.82	202.08	3.33	33.91	2229.15	527.39	473.55
Τ7	18033.86	18151.45	13.71	1.28	-82.51	3919.41	326.62	0.18	14.48	2515.35	581.90	109.55
UT GD	18158.14	18177.50	2.01	-0.02	-89.01	645.29	322.65	0.00	10.55	2573.60	583.65	7.00
UTBW	18177.50	0.00	0.02	-179.98	-179.98	18177.50 *	**	0.00	0.00	0.00	0.00	0.00
DATE:	21-Jul-14											
-------	-----------											
TIME:	16:29:44											

TOWER NUMBER	DOWNHILL TENSION TENS ALPH	DOWNHILL TENSION TENS BETA	Downhill Rope ang Alpha -[DOWNHILL ROPE ANG DEG- BETA	DOWNHILL REACTION ANGLE-DEG	DOWNHILL MAIN AXEL REACTION	DOWNHILL LOAD PER SHEAVE	DOWNHILL SAG TN+1 Fmup	DOWNHILL SAG CLEAR Gfm	DOWNHILL SAG STAT Xfm	DOWNHILL SAG ELEV Zfm	DOWNHILL ARC LENGTH
DR BW	17511.29	17511.29	0.00	-0.21	-90.10	63.87	***	0.05	10.47	-6.40	10.54	60.00
T1 PORT	17511.29	17357.18	0.21	17.14	98.68	-5136.81	-513.68	0.61	20.36	118.40	40.44	199.15
T2	17486.93	17391.87	18.47	8.05	-76.74	3168.80	528.13	3.63	34.70	453.85	109.19	488.41
Т3	17567.85	17560.80	11.41	10.65	-78.97	234.98	58.75	5.37	37.79	986.00	214.29	597.68
Τ4	17839.98	17832.65	14.66	13.88	-75.73	244.31	61.08	1.00	30.89	1402.95	317.20	259.45
T5	17973.23	17956.94	15.59	13.86	-75.28	543.16	90.53	3.49	31.03	1763.05	412.58	486.97
Т6	18233.26	18171.92	17.02	10.59	-76.20	2044.60	511.15	3.27	33.98	2229.15	527.45	473.55
Τ7	18384.03	18265.24	13.68	1.28	-82.52	3959.45	329.95	0.17	14.48	2515.35	581.90	109.55
UT GD	18271.93	18252.50	2.01	-0.02	-89.01	647.88	323.94	0.00	10.55	2573.60	583.65	7.00
UTBW	18252.50	0.00	0.02	-179.98	-179.98	18252.50	***	0.00	0.00	0.00	0.00	0.00

Г

Page 6

DATE:	21-Jul-14
TIME:	16:29:44

TOWER NUMBER	UPHILL TENSION TENS ALPH	UPHILL TENSION TENS BETA	UPHILL ROPE ANG ALPHA -E	UPHILL ROPE ANG DEG- BETA	UPHILL REACTION ANGLE-DEG	UPHILL MAIN AXEL REACTION	UPHILL LOAD PER SHEAVE	UPHILL SAG TN+1 Fmup	UPHILL SAG CLEAR Gfm	UPHILL SAG ELEV Xfm	UPHILL ARC Zfm	UPHILL TENSION LENGTH
DR BW	16359.61	16359.61	0.00	-0.41	-90.20	116.38	***	0.11	1.22	10.49	60.00	0.00
T1 PORT	16359.61	16497.93	0.41	16.53	98.47	-4610.80	-461.08	1.16	10.61	39.89	199.16	0.00
T2	16734.30	16844.04	19.07	6.57	-77.18	3658.09	365.81	6.80	22.33	106.02	488.59	0.00
Т3	17164.63	17200.14	12.85	8.91	-79.12	1183.72	147.96	9.92	24.04	209.74	597.99	0.02
T4	17708.72	17738.05	16.33	13.17	-75.25	977.56	244.39	1.83	20.86	316.37	259.47	0.02
T5	17994.14	18029.29	16.29	12.56	-75.58	1171.66	146.46	6.29	19.03	409.77	487.12	0.04
Т6	18532.67	18619.05	18.27	9.38	-76.18	2879.37	287.94	5.78	22.26	524.94	473.68	0.06
Τ7	19005.43	19143.36	14.85	1.01	-82.07	4597.69	383.14	0.30	5.15	581.78	109.55	0.01
UT GD	19155.56	19178.84	2.28	-0.04	-88.88	775.99	388.00	0.00	1.35	583.65	7.00	0.00
UTBW	19178.84	0.00	0.04	-179.96	-179.96	19178.84	***	0.00	0.00	0.00	0.00	0.00

DATE:	21-Jul-14
TIME:	16:29:44

TOWER NUMBER	DOWNHILL TENSION TENS ALPH	DOWNHILL TENSION TENS BETA	Downhill Rope ang Alpha -[DOWNHILL ROPE ANG DEG- BETA	DOWNHILL REACTION ANGLE-DEG	DOWNHILL MAIN AXEL REACTION	DOWNHILL LOAD PER SHEAVE	DOWNHILL SAG TN+1 Fmup	DOWNHILL SAG CLEAR Gfm	DOWNHILL SAG ELEV Xfm	DOWNHILL ARC Zfm	DOWNHILL TENSION LENGTH
DR BW	17640.39	17640.39	0.00	-0.38	-90.19	116.37 *	***	0.10	1.23	10.49	60.00	0.00
T1 PORT	17640.39	17491.56	0.38	16.61	98.49	-4960.98	-496.10	1.09	10.67	39.96	199.16	0.01
T2	17727.93	17614.34	19.00	6.71	-77.15	3786.13	631.02	6.51	22.63	106.31	488.57	0.02
Т3	17934.93	17900.53	12.72	9.06	-79.11	1146.73	286.68	9.54	24.42	210.13	597.96	0.04
Τ4	18409.11	18380.54	16.19	13.22	-75.30	952.43	238.11	1.76	20.93	316.44	259.47	0.02
T5	18636.63	18601.68	16.23	12.65	-75.56	1164.96	194.16	6.10	19.22	409.97	487.10	0.05
Т6	19105.06	19017.83	18.18	9.44	-76.19	2907.53	726.88	5.66	22.38	525.06	473.67	0.06
Τ7	19404.21	19265.00	14.79	1.01	-82.10	4640.46	386.70	0.30	5.15	581.78	109.55	0.01
UT GD	19277.19	19253.84	2.27	-0.04	-88.88	778.57	389.28	0.00	1.35	583.65	7.00	0.00
UTBW	19253.84	0.00	0.04	-179.96	-179.96	19253.84 *	***	0.00	0.00	0.00	0.00	0.00

	DATE: TIME:	21-Jul-14 16:29:44			UPHILL ROI	PE + CARRIER	S with	STANDARD L 100% 0%	OAD CASE UPHILL LOA DOWNHILL I	D .OAD		Page 8
TOWER NUMBER	UPHILL TENSION TENS ALPH	UPHILL TENSION TENS BETA	uphill Rope ang Alpha -[UPHILL ROPE ANG DEG- BETA	UPHILL REACTION ANGLE-DEG	UPHILL MAIN AXEL REACTION	UPHILL LOAD PER SHEAVE	UPHILL SAG TN+1 Fmup	UPHILL SAG CLEAR Gfm	UPHILL SAG ELEV Xfm	UPHILL ARC Zfm	UPHILL TENSION LENGTH
DR BW	14639.23	14639.23	0.00	-1.08	-90.54	277.17	***	0.28	1.04	10.31	60.00	-0.01
T1 PORT	14639.23	14741.54	1.09	14.41	97.75	-3410.40	-341.04	3.05	8.72	38.00	199.27	-0.04
T2	15304.47	15461.10	21.09	1.56	-78.68	5220.92	522.09	17.39	11.75	95.43	489.99	-0.08
Т3	16224.62	16345.73	17.55	3.31	-79.57	4036.87	504.61	24.33	9.63	195.33	600.19	-0.04
T4	17556.97	17652.87	21.39	10.98	-73.81	3196.57	799.14	4.33	18.36	313.87	259.63	0.00
T5	18262.79	18355.28	18.37	8.71	-76.46	3083.09	385.39	14.45	10.87	401.62	488.04	0.04
Τ6	19554.13	19716.45	21.78	5.95	-76.14	5410.54	541.05	12.84	15.21	517.88	474.42	0.09
Τ7	20636.67	20829.27	18.06	0.25	-80.85	6420.01	535.00	0.67	4.79	581.41	109.56	0.03
UT GD	20858.31	20892.44	3.03	-0.09	-88.53	1137.49	568.75	0.00	1.35	583.65	7.00	0.00
UTBW	20892.44	0.00	0.09	-179.91	-179.91	20892.44	***	0.00	0.00	0.00	0.00	0.00

	DATE: TIME:	21-Jul-14 16:29:44			DOWNHILL F	ROPE + CARRI	ERS with	STANDARD L 0%	OAD CASE	LOAD		Page 9
								100%	UPHILL LOA	D		
TOWER NUMBER	DOWNHILL TENSION TENS ALPH	DOWNHILL TENSION TENS BETA	Downhill Rope ang Alpha -[DOWNHILL ROPE ANG DEG- BETA	DOWNHILL REACTION ANGLE-DEG	DOWNHILL MAIN AXEL REACTION	DOWNHILL LOAD PER SHEAVE	DOWNHILL SAG TN+1 Fmup	DOWNHILL SAG CLEAR Gfm	DOWNHILL SAG ELEV Xfm	DOWNHILL ARC Zfm	DOWNHILL TENSION LENGTH
	19360 77	19360 77	0.00	-0 34	-90 17	6634 74	***	0.09	1 24	10 50	60.00	0.01
T1 PORT	19360.77	19196.03	0.34	16.71	98.53	-5491.43	-549.14	1.00	10.77	40.05	199.16	0.05
T2	19432.39	19311.61	18.90	6.97	-77.07	4025.93	670.99	5.94	23.19	106.88	488.53	0.11
Т3	19632.20	19600.39	12.46	9.37	-79.08	1060.25	265.06	8.72	25.24	210.94	597.89	0.14
T4	20108.98	20082.23	15.89	13.35	-75.38	891.39	222.85	1.62	21.08	316.58	259.46	0.06
T5	20338.33	20304.01	16.11	12.88	-75.50	1143.86	190.64	5.59	19.73	410.47	487.07	0.11
Т6	20807.39	20717.20	17.96	9.66	-76.19	3006.30	751.58	5.20	22.84	525.52	473.64	0.11
Τ7	21103.58	20955.06	14.58	1.06	-82.18	4950.92	412.58	0.28	5.18	581.80	109.55	0.03
UT GD	20967.25	20942.44	2.22	-0.04	-88.91	827.03	413.52	0.00	1.35	583.65	7.00	0.00
UTBW	20942.44	0.00	0.04	-179.96	-179.96	20942.44	***	0.00	0.00	0.00	0.00	0.00

	MAXIMUM DE	SIGN TENSIC	DN:	CARRIERS LO	DADED UP TO	ONE TOWER BELOW					Page 10
DATE:	21-Jul-14		TEST MAXIN	IUM DESIGN T	FENSION *	1.30	TEST MAXI	/UM DESIGN T	ENSION * 1.0	00	
TIME:	16:29:44		ADJACENT S	SPANS HAVE F	ROPE + EMPT	Y CARRIERS	ADJACENT	SPANS HAVE F	ROPE + EMPT	Y CARRIERS	
	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	FULL LOAD
TOWER	TENSION	TENSION	ROPE ANG	ROPE ANG	MAIN AXEL	REACTION	ROPE ANG	ROPE ANG	MAIN AXEL	REACTION	SAG
NUMBER	TENS ALPH	TENS BETA	ALPHA -c	deg- BETA	REACTION	ANGLE-DEG	ALPHA -	deg- BETA	REACTION	ANGLE-DEG	RATIO
DR BW	16359.61	16359.61	0.00	-0.31	116.37	-90.16	0.00	-0.41	116.38	-90.20	0.47%
T1 PORT	16359.61	16497.93	0.31	16.84	-6140.01	98.57	0.41	16.54	-4612.79	98.47	1.53%
T2	16916.45	17026.20	18.78	7.35	4395.94	-76.94	19.06	6.62	3679.13	-77.16	3.56%
Т3	17593.84	17629.36	12.10	9.89	886.08	-79.01	12.80	9.04	1156.15	-79.08	4.07%
Τ4	18529.87	18559.20	15.40	13.59	760.95	-75.51	16.20	13.24	957.56	-75.28	1.67%
T5	19012.65	19047.80	15.87	13.37	1080.20	-75.38	16.21	12.74	1152.50	-75.52	2.97%
Т6	19939.10	20025.48	17.49	10.18	3312.25	-76.16	18.09	9.59	2963.34	-76.16	2.71%
Τ7	20709.64	20847.57	14.07	1.19	6059.49	-82.37	14.64	1.06	4915.81	-82.15	0.61%
UT GD	20869.16	20892.44	2.09	-0.03	1004.89	-88.97	2.23	-0.02	819.02	-88.90	0.04%
UTBW	20892.44	0.00	0.03	-179.97	27160.17	-179.97	0.02	-179.98	20892.44	-179.98	0.00%

		MINIMUM DE	SIGN TENSIO	N:	CARRIERS LO	OADED FROM	ONE TOWER	BELOW TO T	OP			Page 11
DATE:	21-Jul-14		TEST MINIM	UM DESIGN T	ENSION *	0.70			TEST MINIMU	JM TENSION *	1.00	
TIME:	16:29:44		WITH ADJAC	ENT SPANS L	OADED				WITH SINGLE	LOADED SPA	N	
	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL
TOWER	TENSION	TENSION	ROPE ANG	ROPE ANG	MAIN AXEL	REACTION	ROPE ANG	ROPE ANG	MAIN AXEL	REACTION	SAG TN+1	SAG CLEAR
NUMBER	TENS ALPH	TENS BETA	ALPHA -c	deg- BETA	REACTION	ANGLE-DEG	ALPHA -c	deg- BETA	REACTION	ANGLE-DEG	Fmup	Gfm
DR BW	14639.23	14639.23	0.00	-1.55	277.14	-90.77	0.00	-1.08	277.17	-90.54	0.53	0.80
T1 PORT	14639.23	14741.54	1.55	12.89	-2032.95	97.22	1.09	14.39	-3405.03	97.74	2.96	8.81
T2	15122.32	15278.95	22.48	-2.22	4553.17	-79.87	21.11	1.39	5206.80	-78.75	18.62	10.51
Т3	15795.40	15916.51	20.92	-1.31	4278.57	-80.20	17.69	2.95	4071.39	-79.68	27.11	6.85
Τ4	16735.82	16831.72	25.29	9.04	3321.00	-72.84	21.71	10.77	3200.01	-73.76	4.65	18.04
T5	17244.28	17336.77	20.15	5.06	3180.22	-77.40	18.56	8.24	3111.19	-76.60	16.18	9.14
Т6	18147.70	18310.01	24.91	2.49	4962.91	-76.30	22.19	5.42	5319.28	-76.19	15.15	12.89
Τ7	18932.47	19125.07	21.15	-0.52	5009.29	-79.69	18.54	0.13	6090.38	-80.67	0.84	4.62
UT GD	19144.71	19178.84	3.80	-0.14	922.90	-88.17	3.16	-0.10	1088.27	-88.47	0.08	1.27
UTBW	19178.84	0.00	0.14	-179.86	13425.19	-179.86	0.10	-179.90	19178.84	-179.90	0.00	0.00

Г

														Page 12
		DATE:	21-Jul-14											
		TIME:	16:29:44											
	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	DN HILL	DN HILL	DN HILL	DN HILL	DN HILL	DN HILL	DN HILL
TOWER	SHEAVES	REACTION	LOAD/SHV	REACTION	LOAD/SHV	REACTION	LOAD/SHV	SHEAVES	REACTION	LOAD/SHV	REACTION	LOAD/SHV	REACTION	LOAD/SHV
NUMBER		LOADED	LOADED	EMPTY	EMPTY	ROPE	ROPE		LOADED	LOADED	EMPTY	EMPTY	ROPE	ROPE
DR BW	*** ***	277.17 *	**	116.38	***	63.87 *	**	*** ***	6634.74	***	116.37	***	63.87	***
T1 PORT	10 N	-3410.40	-341.04	-4610.80	-461.08	-4867.75	-486.77	10 N	-5491.43	-549.14	-4960.98	-496.10	-5136.81	-513.68
T2	10 S	5220.92	522.09	3658.09	365.81	3078.55	307.85	6 S	4025.93	670.99	3786.13	631.02	3168.80	528.13
Т3	8 S	4036.87	504.61	1183.72	147.96	261.90	32.74	4 S	1060.25	265.06	1146.73	286.68	234.98	58.75
T4	4 S/2N	3196.57	799.14	977.56	244.39	262.95	65.74	4 S/2N	891.39	222.85	952.43	238.11	244.31	61.08
T5	8 S	3083.09	385.39	1171.66	146.46	549.03	68.63	6 S	1143.86	190.64	1164.96	194.16	543.16	90.53
T6	10 S	5410.54	541.05	2879.37	287.94	2020.82	202.08	4 S	3006.30	751.58	2907.53	726.88	2044.60	511.15
T7	12 S	6420.01	535.00	4597.69	383.14	3919.41	326.62	12 S	4950.92	412.58	4640.46	386.70	3959.45	329.95
UT GD	2 S	1137.49	568.75	775.99	388.00	645.29	322.65	2 S	827.03	413.52	778.57	389.28	647.88	323.94
UTBW	*** ***	20892.44 *	**	19178.84	***	18177.50 *	**	*** ***	20942.44	***	19253.84	***	18252.50	***

* =====================================			· · · · · · · · · · · · ·
** ProfileXL **			
Copyright 2011 by James K. Bunc	h		
Revision: 7 MAR 2011			
I			
CLIENT:	British Columbia Safety Aut	hority	
AREA:	Crystal Mountain		16:16:21 Time
LIFT:	Blue Chair		21-Jul-14 Date
COMMENTS:	Accident review		
	as-built profile 2014, based	on field observations 4 JUN 14	
=====================================			= ======= =====
*** GENERAL INPUT DATA ***		*** CALCULATED DATA ***	
CALC UNITS(ENG/SI)	ENG		2658.5 FT
	BOI	VERTICAL	574.9 FI
TENSION (TOP/BOT)	BOT	SLOPE	2727.0 FT
ROTATION (CW/CCW)	CW	SLOPE ANGLE	12.20 DEG
GRIP (FIX/DET)	FIXED	INTERVAL	7.90 SEC
		SPACING	64.49 FT
	950 PPH	DESIGN CAPACITY	911.7 PPH
DESIGN SPEED	490 FPM	NO. OF CARRIERS	85.00 CARR.
OPERATING SPEED	490 FPM	RHO W/EMPTY CARR	3.85 LB/FT
ACCELERATION	0 FT/S^2	RHO LOADED UP	9.12 LB/FT
PASS/CARR. UPHILL	2 PASS	RHO LOADED DN	3.85 LB/FT
PASS/CARR. DNHILL	0 PASS	VERT TENSION-UP	5244.91 LB
CARRIER CAPACITY	2 PASS	VERT TENSION-DN	2214.03 LB
CARRIER LENGTH	9.2 FT	FRICTION UPHILL	946.50 LB
CARRIER WIDTH	3.6 FT	FRICTION DNHILL	627.41 LB
CARRIER WEIGHT	111.00 LB	ACCELL FORCE UP	0.00 LB
CARRIERS ON LINE	85 CARR.	ACCELL FORCE DN	0.00 LB
CARRIERS IN TERM.	0 CARR.	**TANGENT TENSION	0.00 LB
INPUT COUNTER WT.	34000.00 LB	TENSION CHANGE UP	6191.41 LB
ROPE WEIGHT	2.130 LB/FT	TENSION CHANGE DN	1586.62 LB
ROPE DIAMETER	1.125 IN	TORQUE TENSION	4704.79 LB
BREAKING STRENGTH	105200.00 LB	POWER-ROPE ONLY	18.7 HP
LINE GAUGE	8.2021 FT	POWER-EMPTY CARR.	22.0 HP
RETURN TERMINAL FRICTION	50 LB	POWER-FULL LOAD	79.8 HP
DRIVE TERMINAL FRICTION	50 LB	ROPE DESIGN FACTOR	4.99
DRIVE SYSTEM FRICTION	25 LB	T1:T2 RATIO	1.32
SHEAVE MAX LOAD +	1000 LB	SHEAR RATIO	32.53
SHEAVE MAX LOAD -	900 LB	DESIGN COUNTER WT	34000.00 LB
SHEAVE SPACING-C.L.	1.31 FT	TENSION T1	14647.61 LB
PASSENGER WEIGHT	170 LB	TENSION T2	19352.39 LB
DRIVE EFFICIENCY	0.88	TENSION T3	20939.02 LB
FRICTION FACTOR	0.030	TENSION T3'	20839.02 LB
METALIC AREA RATIO	0.442	ROPE METALIC AREA	0.559 SQ IN
ELASTICITY MODULUS	1.310E+07 PSI	ROPE LENGTH-ROPE	5480.4 FT
OVER TENSION RATIO	1.5	ROPE LENGTH-EMPTY	5481.8 FT
MIN SHEAR RATIO	10	ROPE STRETCH EMPTY	0.2 FT
MAX T1/T2 RATIO	1.9	CARR TRAV ROPE-EMP	0.5 FT
LOAD(STD/MAXUP/MAXDN)	STD	ROPE LENGTH-LOADED	5486.6 FT
** FOR SURFACE LIFTS ONLY		STRETCH EMP-LOAD	0.3 FT
**SNOW FRICTION FACT	0.06	CARR TRAV EMP-LOAD	2.1 FT
For aerial lifts, set TOW-BAR			0.00 LB
and ROPE-SEAT length to 1.0.		**BAR ANGLE BETA	0.0 DEG
**ROPE-SEAT HEIGHT	1 FT	**RHO VERTICAL	0.00 LB/FT
**TOW BAR LENGTH	1 FT	**RHO TANGENTIAL	0.00 LB/FT

	DATE:	21-Jul-14						Page 2				
	TIME:	16:16:21										
	UPHILL T	OWER POINT	S	I	DOWNHI	LL TOWER PO	INTS					
			CTF TO	BATTER			CTF TO	BATTER	ACTUA	L	CALCULATE	D
TOWER	STATION	ELEVATION	ROPE PT.	ANGLE	STATION	ELEVATION	ROPE PT.	ANGLE	SHEAVES	SHEAVES	SHEAVES	SHEAVES
NUMBER	Х	Z	LENGTH HT	DEGREES	Х	Z	LENGTH HT	DEGREES	UPHILL	DOWNHILL	UPHILL	DOWNHILL
DR BW AB	-36.40	10.75	10.55	0.00	-36.40	10.75	10.55	0.00	*** ***	*** ***	4 T/2FR	4 T/2FR
T1 PORT AB	23.60	10.75	10.00	0.00	23.60	10.75	10.00	0.00	10 N	10 N	6 D	4 T/2FR
T2 AB	220.20	70.60	32.80	0.00	220.20	70.60	32.80	0.00	10 S	6 S	4 S	4 T/2FR
T3 AB	697.50	150.12	37.72	0.00	697.50	150.12	37.72	0.00	8 S	4 S	4 S	4 T/2FR
T4 AB	1210.50	254.70	37.50	0.00	1210.50	254.70	37.50	0.00	4 S/2N	4 S/2N	4 S	4 T/2FR
T5 AB	1528.40	346.90	26.90	0.00	1528.40	346.90	26.90	0.00	8 S	6 S	4 S	4 T/2FR
T6 AB	2000.70	473.90	37.70	0.00	2000.70	473.90	37.70	0.00	10 S	4 S	4 S	4 T/2FR
T7 AB	2482.10	584.60	32.80	0.00	2482.10	584.60	32.80	0.00	12 S	12 S	4 S	4 T/2FR
UT GD AB	2615.10	585.65	10.55	0.00	2615.10	585.65	10.55	0.00	2 S	2 S	4 S	4 T/2FR
UTBW AB	2622.10	585.65	10.55	0.00	2622.10	585.65	10.55	0.00	*** ***	*** ***	4 S	4 T/2FR

DATE: 21-Jul-14 TIME: 16:16:21

	Page 3
--	--------

			DOW							00000		
	UP	HILL	DOW	INHILL	CARRIER	LEARANCE		FOUNDATION	1	CR055		ADIAL
TOWER	CHORD	CHORD ANG	CHORD	CHORD ANG	TO GR	ROUND	STATION	ELEVATION	CTF-GND	SLOPE	ACCELERAT	ION - G
NUMBER	LENGTH	DEGREES	LENGTH	DEGREES	UPHILL	DOWNHILL	XCTF	ZCTF	DISTANCE	DEGREES	UPHILL	DOWNHILL
DR BW AB	60.00	0.00	60.00	0.00	1.55	1.55	-36.40	0.20	#VALUE!	0.00	0.00	0.00
T1 PORT AB	205.51	16.93	205.51	16.93	0.85	0.85	23.60	0.75	0.05	0.00	0.05	0.05
T2 AB	483.88	9.46	483.88	9.46	21.66	21.66	220.20	37.80	-1.94	0.00	0.06	0.06
T3 AB	523.55	11.52	523.55	11.52	23.90	23.90	697.50	112.40	-4.62	0.00	0.05	0.04
T4 AB	331.00	16.17	331.00	16.17	20.68	20.68	1210.50	217.20	-7.62	0.00	0.07	0.00
T5 AB	489.08	15.05	489.08	15.05	13.40	13.40	1528.40	320.00	-4.30	0.00	0.05	0.03
T6 AB	493.96	12.95	493.96	12.95	20.83	20.83	2000.70	436.20	-7.67	0.00	0.05	0.07
T7 AB	133.00	0.45	133.00	0.45	19.95	19.95	2482.10	551.80	-3.65	0.00	0.05	0.04
UT GD AB	7.00	0.00	7.00	0.00	3.35	3.35	2615.10	575.10	2.00	0.00	0.06	0.03
UTBW AB	0.00	0.00	2686.71	0.00	3.35	3.35	2622.10	575.10	2.00	0.00	0.00	0.00

Г

Page 4

DATE:	21-Jul-14
TIME:	16:16:21

TOWER NUMBER	UPHILL TENSION TENS ALPH	UPHILL TENSION TENS BETA	UPHILL ROPE ANG ALPHA -E	UPHILL ROPE ANG DEG- BETA	UPHILL REACTION ANGLE-DEG	UPHILL MAIN AXEL REACTION	UPHILL LOAD PER SHEAVE	UPHILL SAG TN+1 Fmup	UPHILL SAG CLEAR Gfm	UPHILL SAG STAT Xfm	UPHILL SAG ELEV Zfm	UPHILL ARC LENGTH
DR BW AB	16469.68	16469.68	0.00	-0.22	-90.11	63.87	***	0.06	10.63	-6.40	10.69	60.00
T1 PORT AB	16469.68	16607.73	0.22	16.21	98.22	-4601.76	-460.18	0.67	19.23	121.90	40.00	205.51
T2 AB	16735.21	16822.29	17.65	7.73	-77.31	2902.79	290.28	3.69	31.44	458.85	106.67	483.95
T3 AB	16991.67	17004.94	11.17	9.68	-79.57	442.28	55.29	4.26	28.24	954.00	198.15	523.64
T4 AB	17227.69	17243.13	13.34	15.05	104.19	-514.60	-128.65	1.68	23.12	1369.45	299.12	331.02
T5 AB	17439.52	17475.03	17.29	13.40	-74.66	1183.69	147.96	3.62	24.87	1764.55	406.78	489.15
T6 AB	17745.54	17795.55	16.67	11.30	-76.01	1666.98	166.70	3.63	29.49	2241.40	525.62	494.04
T7 AB	18031.34	18169.14	14.58	0.01	-82.71	4593.46	382.79	0.26	11.77	2548.60	584.87	133.01
UT GD AB	18171.38	18180.15	0.90	-0.02	-89.56	292.49	146.24	0.00	12.55	2618.60	585.65	7.00
UTBW AB	18180.15	0.00	0.02	-179.98	-179.98	18180.15	***	0.00	0.00	0.00	0.00	0.00

DATE:	21-Jul-14
TIME:	16:16:21

TOWER NUMBER	DOWNHILL TENSION TENS ALPH	DOWNHILL TENSION TENS BETA	Downhill Rope ang Alpha -[DOWNHILL ROPE ANG DEG- BETA	DOWNHILL REACTION ANGLE-DEG	DOWNHILL MAIN AXEL REACTION	DOWNHILL LOAD PER SHEAVE	DOWNHILL SAG TN+1 Fmup	DOWNHILL SAG CLEAR Gfm	DOWNHILL SAG STAT Xfm	DOWNHILL SAG ELEV Zfm	DOWNHILL ARC LENGTH
DR BW AB	17530.32	17530.32	0.00	-0.21	-90.10	63.87 *	***	0.05	10.63	-6.40	10.70	60.00
T1 PORT AB	17530.33	17384.19	0.21	16.24	98.23	-4871.14	-487.11	0.64	19.26	121.90	40.03	205.51
T2 AB	17511.67	17421.85	17.62	7.79	-77.30	2994.07	499.01	3.56	31.57	458.85	106.80	483.95
T3 AB	17591.23	17578.59	11.11	9.74	-79.57	421.20	105.30	4.13	28.38	954.00	198.28	523.64
T4 AB	17801.35	17784.54	13.28	15.08	104.18	-560.05	-140.01	1.63	23.17	1369.45	299.17	331.02
T5 AB	17980.93	17945.11	17.25	13.45	-74.65	1193.95	198.99	3.52	24.97	1764.55	406.88	489.14
T6 AB	18215.62	18165.15	16.63	11.33	-76.02	1682.43	420.61	3.55	29.56	2241.40	525.70	494.03
T7 AB	18400.94	18261.71	14.55	0.01	-82.72	4641.01	386.75	0.26	11.77	2548.60	584.87	133.01
UT GD AB	18263.95	18255.15	0.90	-0.02	-89.56	293.08	146.54	0.00	12.55	2618.60	585.65	7.00
UTBW AB	18255.15	0.00	0.02	-179.98	-179.98	18255.15 *	***	0.00	0.00	0.00	0.00	0.00

DATE:	21-Jul-14
TIME:	16:16:21

TOWER NUMBER	UPHILL TENSION TENS ALPH	UPHILL TENSION TENS BETA	uphill Rope ang Alpha -[UPHILL ROPE ANG DEG- BETA	UPHILL REACTION ANGLE-DEG	UPHILL MAIN AXEL REACTION	UPHILL LOAD PER SHEAVE	UPHILL SAG TN+1 Fmup	UPHILL SAG CLEAR Gfm	UPHILL SAG ELEV Xfm	UPHILL ARC Zfm	UPHILL TENSION LENGTH
DR BW AB	16372.94	16372.94	0.00	-0.40	-90.20	115.51 *	:**	0.11	1.38	10.64	60.00	0.00
T1 PORT AB	16372.94	16503.56	0.40	15.62	98.01	-4353.79	-435.38	1.22	9.48	39.45	205.53	0.00
T2 AB	16734.05	16838.44	18.23	6.33	-77.72	3479.64	347.96	6.63	19.30	103.73	484.12	0.01
T3 AB	17144.68	17183.29	12.53	8.23	-79.62	1286.95	160.87	7.59	15.71	194.82	523.84	0.02
T4 AB	17586.05	17591.17	14.74	14.18	-75.54	170.97	42.74	2.97	12.63	297.83	331.07	0.02
T5 AB	17946.25	18002.42	18.13	12.16	-74.86	1872.42	234.05	6.31	12.98	404.09	489.29	0.04
T6 AB	18491.52	18566.92	17.87	10.09	-76.02	2513.34	251.33	6.25	17.66	523.00	494.18	0.06
T7 AB	18993.24	19153.16	15.74	-0.31	-82.28	5330.47	444.21	0.44	2.38	584.68	133.01	0.02
UT GD AB	19157.20	19169.83	1.22	-0.04	-89.41	420.84	210.42	0.00	3.35	585.65	7.00	0.00
UTBW AB	19169.83	0.00	0.04	-179.96	-179.96	19169.83 *	***	0.00	0.00	0.00	0.00	0.00

DATE:	21-Jul-14
TIME:	16:16:21

ROP	CARRIERS

TOWER NUMBER	DOWNHILL TENSION TENS ALPH	DOWNHILL TENSION TENS BETA	Downhill Rope ang Alpha -[DOWNHILL ROPE ANG DEG- BETA	DOWNHILL REACTION ANGLE-DEG	DOWNHILL MAIN AXEL REACTION	DOWNHILL LOAD PER SHEAVE	DOWNHILL SAG TN+1 Fmup	DOWNHILL SAG CLEAR Gfm	DOWNHILL SAG ELEV Xfm	DOWNHILL ARC Zfm	DOWNHILL TENSION LENGTH
DR BW AB	17627.06	17627.06	0.00	-0.38	-90.19	115.50 *	***	0.10	1.39	10.65	60.00	0.00
T1 PORT AB	17627.06	17486.62	0.38	15.69	98.03	-4681.23	-468.12	1.16	9.55	39.52	205.53	0.00
T2 AB	17717.11	17609.19	18.16	6.47	-77.69	3597.48	599.58	6.35	19.59	104.01	484.10	0.02
T3 AB	17915.43	17877.60	12.40	8.36	-79.62	1260.90	315.23	7.30	16.01	195.11	523.82	0.03
T4 AB	18280.36	18276.91	14.62	14.26	-75.56	114.94	28.73	2.86	12.74	297.94	331.07	0.03
T5 AB	18631.99	18575.41	18.06	12.25	-74.85	1885.78	314.30	6.12	13.17	404.28	489.28	0.05
T6 AB	19064.51	18988.56	17.78	10.16	-76.03	2531.79	632.95	6.12	17.80	523.13	494.17	0.06
T7 AB	19414.88	19253.42	15.68	-0.31	-82.31	5381.82	448.48	0.44	2.38	584.68	133.01	0.02
UT GD AB	19257.47	19244.83	1.21	-0.04	-89.41	421.37	210.69	0.00	3.35	585.65	7.00	0.00
UTBW AB	19244.83	0.00	0.04	-179.96	-179.96	19244.83 *	***	0.00	0.00	0.00	0.00	0.00

	DATE: TIME:	21-Jul-14 16:16:21			UPHILL ROI	PE + CARRIER	S with	STANDARD L 100% 0%	OAD CASE UPHILL LOA DOWNHILL I	D _OAD		Page 8
TOWER NUMBER	UPHILL TENSION TENS ALPH	UPHILL TENSION TENS BETA	uphill Rope ang Alpha -[UPHILL ROPE ANG DEG- BETA	UPHILL REACTION ANGLE-DEG	UPHILL MAIN AXEL REACTION	UPHILL LOAD PER SHEAVE	UPHILL SAG TN+1 Fmup	UPHILL SAG CLEAR Gfm	UPHILL SAG ELEV Xfm	UPHILL ARC Zfm	UPHILL TENSION LENGTH
DR BW AB	14672.61	14672.61	0.00	-1.07	-90.53	273.63	***	0.28	1.21	10.47	60.00	-0.01
T1 PORT AB	14672.61	14767.94	1.07	13.46	97.26	-3177.84	-317.78	3.20	7.50	37.47	205.64	-0.04
T2 AB	15313.96	15465.14	20.28	1.45	-79.14	5039.28	503.93	16.87	9.06	93.49	485.45	-0.08
T3 AB	16190.62	16307.47	17.12	3.36	-79.76	3895.09	486.89	18.62	4.68	183.79	525.32	-0.04
T4 AB	17261.57	17332.66	19.24	11.39	-74.68	2369.53	592.38	7.04	8.56	293.76	331.40	0.00
T5 AB	18173.81	18292.04	20.74	8.33	-75.47	3940.81	492.60	14.45	4.84	395.95	490.22	0.04
T6 AB	19450.68	19601.77	21.37	6.56	-76.04	5036.40	503.64	13.84	10.07	515.41	495.00	0.09
T7 AB	20611.70	20830.33	19.03	-1.22	-81.09	7287.65	607.30	0.97	1.86	584.16	133.02	0.03
UT GD AB	20839.91	20864.02	2.12	-0.09	-88.98	803.41	401.71	0.00	3.35	585.65	7.00	0.00
UTBW AB	20864.02	0.00	0.09	-179.91	-179.91	20864.02	***	0.00	0.00	0.00	0.00	0.00

	DATE:	21-Jul-14	S					STANDARD L	OAD CASE	Page 9		
	TIME:	16:16:21			DOWNHILL F	ROPE + CARRI	ERS with	0%	DOWNHILL I	_OAD		
								100%	UPHILL LOA	D		
	DOWNHILL	DOWNHILL	DOWNHILL	DOWNHILL	DOWNHILL	DOWNHILL	DOWNHILL	DOWNHILL	DOWNHILL	DOWNHILL	DOWNHILL	DOWNHILL
TOWER	TENSION	TENSION	ROPE ANG	ROPE ANG	REACTION	MAIN AXEL	LOAD PER	SAG TN+1	SAG CLEAR	SAG ELEV	ARC	TENSION
NUMBER	TENS ALPH	TENS BETA	ALPHA -E	DEG- BETA	ANGLE-DEG	REACTION	SHEAVE	Fmup	Gfm	Xfm	Zfm	LENGTH
								-				
DR BW AB	19327.39	19327.39	0.00	-0.34	-90.17	6585.45	***	0.09	1.40	10.66	60.00	0.01
T1 PORT AB	19327.39	19172.00	0.34	15.80	98.07	-5179.91	-517.99	1.05	9.65	39.62	205.52	0.05
T2 AB	19402.49	19287.97	18.05	6.73	-77.61	3817.09	636.18	5.80	20.13	104.56	484.06	0.11
T3 AB	19594.22	19558.20	12.14	8.63	-79.61	1200.74	300.18	6.68	16.63	195.73	523.78	0.12
T4 AB	19960.95	19960.31	14.36	14.42	104.39	-21.44	-5.36	2.62	12.98	298.18	331.06	0.08
T5 AB	20315.38	20257.81	17.90	12.48	-74.81	1918.99	319.83	5.62	13.67	404.78	489.25	0.11
T6 AB	20746.91	20669.10	17.56	10.38	-76.03	2593.85	648.46	5.62	18.29	523.63	494.13	0.11
T7 AB	21095.42	20923.01	15.47	-0.25	-82.39	5746.98	478.91	0.41	2.42	584.72	133.01	0.03
UT GD AB	20927.05	20914.02	1.15	-0.04	-89.44	434.54	217.27	0.00	3.35	585.65	7.00	0.00
UTBW AB	20914.02	0.00	0.04	-179.96	-179.96	20914.02	***	0.00	0.00	0.00	0.00	0.00

	MAXIMUM DE	SIGN TENSIC	DN:	CARRIERS LO	DADED UP TO	ONE TOWER BELC	W				Page 10
DATE:	21-Jul-14		TEST MAXIM	UM DESIGN T	ENSION *	1.30	TEST MAXIN	1UM DESIGN T	ENSION * 1.0	00	
TIME:	16:16:21		ADJACENT S	PANS HAVE F	ROPE + EMPT	TY CARRIERS	ADJACENT S	SPANS HAVE I	ROPE + EMPT	Y CARRIERS	
TOWER NUMBER	UPHILL TENSION TENS ALPH	UPHILL TENSION TENS BETA	UPHILL ROPE ANG ALPHA -c	UPHILL ROPE ANG leg- BETA	UPHILL MAIN AXEL REACTION	UPHILL REACTION ANGLE-DEG	UPHILL ROPE ANG ALPHA -(UPHILL ROPE ANG deg- BETA	UPHILL MAIN AXEL REACTION	UPHILL REACTION ANGLE-DEG	FULL LOAD SAG RATIO
DR BW AB	16372.94	16372.94	0.00	-0.31	115.50	-90.16	0.00	-0.40	115.51	-90.20	0.47%
T1 PORT AB	16372.94	16503.56	0.31	15.93	-5808.97	98.12	0.40	15.62	-4355.77	98.01	1.56%
T2 AB	16910.42	17014.81	17.92	7.10	4161.94	-77.49	18.22	6.39	3498.44	-77.70	3.49%
T3 AB	17555.40	17594.00	11.79	9.08	1080.86	-79.57	12.48	8.34	1269.91	-79.59	3.56%
T4 AB	18304.95	18310.08	13.93	14.71	-327.73	104.32	14.64	14.27	116.61	-75.54	2.13%
T5 AB	18936.86	18993.03	17.61	12.97	1998.93	-74.71	18.04	12.34	1887.60	-74.81	2.96%
T6 AB	19856.39	19931.79	17.09	10.92	2785.63	-75.99	17.70	10.31	2564.86	-76.00	2.80%
T7 AB	20684.34	20844.25	14.95	-0.09	7065.74	-82.57	15.54	-0.25	5705.84	-82.36	0.73%
UT GD AB	20851.39	20864.02	0.99	-0.03	483.62	-89.52	1.16	-0.02	428.18	-89.43	0.04%
UTBW AB	20864.02	0.00	0.03	-179.97	27123.22	-179.97	0.02	-179.98	20864.02	-179.98	0.00%

		MINIMUM DE	SIGN TENSIO	N:	CARRIERS LO	DADED FROM	ONE TOWER	R BELOW TO T	OP			Page 11
DATE:	21-Jul-14		TEST MINIM	JM DESIGN T	ENSION *	0.70			TEST MINIMU	JM TENSION *	1.00	
TIME:	16:16:21		WITH ADJAC	ENT SPANS L	OADED				WITH SINGLE	E LOADED SPA	N	
	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL
TOWER	TENSION	TENSION	ROPE ANG	ROPE ANG	MAIN AXEL	REACTION	ROPE ANG	ROPE ANG	MAIN AXEL	REACTION	SAG TN+1	SAG CLEAR
NUMBER	TENS ALPH	TENS BETA	ALPHA -c	leg- BETA	REACTION	ANGLE-DEG	ALPHA -o	deg- BETA	REACTION	ANGLE-DEG	Fmup	Gfm
DR BW AB	14672.61	14672.61	0.00	-1.53	273.60	-90.76	0.00	-1.07	273.63	-90.53	0.52	0.96
T1 PORT AB	14672.61	14767.94	1.53	11.90	-1864.93	96.72	1.07	13.44	-3172.52	97.25	3.07	7.63
T2 AB	15137.59	15288.77	21.70	-2.24	4420.03	-80.27	20.30	1.29	5026.69	-79.20	18.40	7.53
T3 AB	15779.90	15896.76	20.42	-0.62	4050.01	-80.10	17.26	3.07	3914.24	-79.84	19.52	3.78
T4 AB	16542.67	16613.75	22.71	8.93	2784.99	-74.18	19.50	11.14	2416.73	-74.68	7.45	8.15
T5 AB	17183.20	17301.43	22.93	4.71	3822.04	-76.18	20.96	7.88	3930.69	-75.58	16.44	2.85
T6 AB	18085.81	18236.90	24.49	2.99	4743.45	-76.26	21.77	6.02	4979.57	-76.10	15.96	7.96
T7 AB	18920.61	19139.24	22.18	-2.14	5614.68	-79.98	19.51	-1.36	6899.30	-80.92	1.06	1.76
UT GD AB	19145.72	19169.83	3.04	-0.14	744.23	-88.55	2.27	-0.09	790.01	-88.91	0.08	3.27
UTBW AB	19169.83	0.00	0.14	-179.86	13418.88	-179.86	0.10	-179.90	19169.83	-179.90	0.00	0.00

														Page 12
		DATE:	21-Jul-14											-
		TIME:	16:16:21											
	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	DN HILL	DN HILL	DN HILL	DN HILL	DN HILL	DN HILL	DN HILL
TOWER	SHEAVES	REACTION	LOAD/SHV	REACTION	LOAD/SHV	REACTION	LOAD/SHV	SHEAVES	REACTION	LOAD/SHV	REACTION	LOAD/SHV	REACTION	LOAD/SHV
NUMBER		LOADED	LOADED	EMPTY	EMPTY	ROPE	ROPE		LOADED	LOADED	EMPTY	EMPTY	ROPE	ROPE
DR BW AB *	** ***	273.63	***	115.51	***	63.87 '	***	*** ***	6585.45	***	115.50	***	63.87	***
T1 PORT AB	10 N	-3177.84	-317.78	-4353.79	-435.38	-4601.76	-460.18	10 N	-5179.91	-517.99	-4681.23	-468.12	-4871.14	-487.11
T2 AB	10 S	5039.28	503.93	3479.64	347.96	2902.79	290.28	6 S	3817.09	636.18	3597.48	599.58	2994.07	499.01
T3 AB	8 S	3895.09	486.89	1286.95	160.87	442.28	55.29	4 S	1200.74	300.18	1260.90	315.23	421.20	105.30
T4 AB	4 S/2N	2369.53	592.38	170.97	42.74	-514.60	-128.65	4 S/2N	-21.44	-5.36	114.94	28.73	-560.05	-140.01
T5 AB	8 S	3940.81	492.60	1872.42	234.05	1183.69	147.96	6 S	1918.99	319.83	1885.78	314.30	1193.95	198.99
T6 AB	10 S	5036.40	503.64	2513.34	251.33	1666.98	166.70	4 S	2593.85	648.46	2531.79	632.95	1682.43	420.61
T7 AB	12 S	7287.65	607.30	5330.47	444.21	4593.46	382.79	12 S	5746.98	478.91	5381.82	448.48	4641.01	386.75
UT GD AB	2 S	803.41	401.71	420.84	210.42	292.49	146.24	2 S	434.54	217.27	421.37	210.69	293.08	146.54
UTBW AB *	** ***	20864.02	***	19169.83	***	18180.15	***	*** ***	20914.02	***	19244.83	***	18255.15	***

** ProfileXL ** Copyright 2011 by James K. Bunch Revision: 7 MAR 2011 CLIENT: British Columbia Safety Authority AREA: Crystal Mountain 11:38:58 Time LIFT: Blue Chair 28-Jul-14 Date COMMENTS: Accident review, Low Tension Test 28-Jul-14 Date CWT 8500 x 3, plus carriage uphill ~9", 27 passengers *** **** GENERAL INPUT DATA *** 1 CALC UNITS(ENG/SI) ENG HORIZONTAL 2658.0 FT DATA *** CALC UNITS(ENG/SI) ENG HORIZONTAL 2658.0 FT TENSION (TOP/BOT) BOT VERTICAL 772.6 FT ROTATION (CW/CCW) CW SLOPE 2726.5 FT 1 ROTATION (CW/CCW) CW SLOPE 220 DEG GRIP (FIX/DET) FIXED INTERVAL 10.35 SEC I NPUT CAPACITY 950 PPH DESIGN CAPACITY 911.5 PPH DESIGN SPEED 490 FPM NO. OF CARRIERS 85.00 CAR I OPERATING SPEED 374 FPM RHO LOADED DN 3.85 LB/F ACCELERATION 0 FT/S^2 RHO LOADED UP 5.51 LB/F PASS/CARR. DNHILL 0 FAS	** ProfileXL ** opvright 2011 by James K. Bund			
Copyright 2011 by James K. Bunch Revision: 7 MAR 2011 CLIENT: British Columbia Safety Authority AREA: Crystal Mountain 11:38:58 Time LIFT: Blue Chair 28-Jul-14 Date COMMENTS: Accident review, Low Tension Test 28-Jul-14 Date CALC UNITS(ENG/SI) ENG HORIZONTAL 2658.0 FT DRIVE (TOP/BOT) BOT VERTICAL 574.9 FT TENSION (TOP/BOT) BOT VERTICAL 574.9 FT I TENSION (TOP/BOT) BOT SLOPE 2726.5 FT ROTATION (CW/CCW) CW SLOPE ANGLE 12.20 DEG I SPACING 64.51 FT 10.35 SEC SEC I INPUT CAPACITY 950 PPH DESIGN CAPACITY 911.5 PPH DESIGN SPEED 490 FPM NO. OF CARRIERS 85.00 CAR QPERATING SPEED 374 FPM RHO W/EMPTY CARR 3.85 LB/F ACCELERATION <td>opyright 2011 by James K. Bund</td> <td></td> <td></td> <td></td>	opyright 2011 by James K. Bund			
Revision: 7 MAR 2011 CLIENT: British Columbia Safety Authority AREA: Crystal Mountain 11:38:58 Time LIFT: Blue Chair 28-Jul-14 Date COMMENTS: Accident review, Low Tension Test 28-Jul-14 Date COMMENTS: Accident review, Low Tension Test CWT 8500 x 3, plus carriage uphill ~9", 27 passengers		ch		
Image: Client	Revision: 7 MAR 2011			
CLIENT: British Columbia Safety Authority AREA: Crystal Mountain 11:38:58 Time LIFT: Blue Chair 28-Jul-14 Date COMMENTS: Accident review, Low Tension Test 28-Jul-14 Date COMMENTS: Accident review, Low Tension Test 28-Jul-14 Date COMMENTS: Accident review, Low Tension Test 28-Jul-14 Date Image: Commentation of the state				
AREA: Crystal Mountain 11:38:58 Time LIFT: Blue Chair 28-Jul-14 Date COMMENTS: Accident review, Low Tension Test 28-Jul-14 Date CWT 8500 x 3, plus carriage uphill -9", 27 passengers	CLIENT:	British Columbia Safe	y Authority	
LIFT: Blue Chair 28-Jul-14 Date COMMENTS: Accident review, Low Tension Test CWT 8500 x 3, plus carriage uphill ~9", 27 passengers	AREA:	Crystal Mountain		11:38:58 Time
COMMENTS: Accident review, Low Tension Test CWT 8500 x 3, plus carriage uphill ~9", 27 passengers **** GENERAL INPUT DATA *** I *** CALCULATED DATA *** CALC UNITS(ENG/SI) ENG HORIZONTAL 2658.0 FT DRIVE (TOP/BOT) BOT VERTICAL 574.9 FT TENSION (TOP/BOT) BOT SLOPE 2726.5 FT ROTATION (CW/CCW) CW SLOPE ANGLE 12.20 DEG GRIP (FIX/DET) FIXED INTERVAL 10.35 SEC I INPUT CAPACITY 950 PPH DESIGN CAPACITY 911.5 PPH DESIGN SPEED 490 FPM NO. OF CARRIERS 85.00 CAR I OPERATING SPEED 374 FPM RHO W/EMPTY CARR 3.85 LB/F ACCELERATION 0 FT/S*2 RHO LOADED UP 5.51 LB/F PASS/CARR. UPHILL 0.63 PASS RHO LOADED UP 3.68.17 LB CARRIER CAPACITY 2 PASS VERT TENSION-UP 3168.17 LB <td>LIFT:</td> <td>Blue Chair</td> <td></td> <td>28-Jul-14 Date</td>	LIFT:	Blue Chair		28-Jul-14 Date
CWT 8500 x 3, plus carriage uphill ~9", 27 passengers	COMMENTS:	Accident review, Low	Fension Test	
Image: series of the series		CWT 8500 x 3, plus ca	arriage uphill ~9", 27 passengers	
**** GENERAL INPUT DATA *** **** CALCULATED DATA *** CALC UNITS(ENG/SI)ENG HORIZONTAL2658.0 FT DRIVE (TOP/BOT)BOT VERTICAL574.9 FT TENSION (TOP/BOT)BOT SLOPE2726.5 FT ROTATION (CW/CCW)CW SLOPE ANGLE12.20 DEG GRIP (FIX/DET)FIXED INTERVAL10.35 SEC INPUT CAPACITY950 PPHDESIGN CAPACITY911.5 PPH DESIGN SPEED490 FPMNO. OF CARRIERS85.00 CAR OPERATING SPEED374 FPMRHO W/EMPTY CARR3.85 LB/F ACCELERATION0 FT/S^2RHO LOADED UP5.51 LB/F PASS/CARR. UPHILL0.63 PASSRHO LOADED DN3.85 LB/F CARRIER CAPACITY2 PASSVERT TENSION-UP3168.17 LB CARRIER CAPACITY2 PASSVERT TENSION-UP3168.17 LB CARRIER LENGTH9.2 FTFRICTION UPHILL589.03 LB CARRIER KIDTH3.6 FTFRICTION DNHILL495.37 LB CARRIER WIDTH3.6 FTFRICTION DNHILL495.37 LB				
CALC UNITS(ENG/SI)ENGHORIZONTAL2658.0 FTDRIVE (TOP/BOT)BOTVERTICAL574.9 FTTENSION (TOP/BOT)BOTSLOPE2726.5 FTROTATION (CW/CCW)CWSLOPE ANGLE12.20 DEGGRIP (FIX/DET)FIXEDINTERVAL10.35 SECINPUT CAPACITY950 PPHDESIGN CAPACITY911.5 PPHDESIGN SPEED490 FPMNO. OF CARRIERS85.00 CAFI OPERATING SPEED374 FPMRHO W/EMPTY CARR3.85 LB/FACCELERATION0 FT/S^2RHO LOADED UP5.51 LB/FPASS/CARR. UPHILL0.63 PASSRHO LOADED DN3.85 LB/FI CARRIER CAPACITY2 PASSVERT TENSION-UP3168.17 LBCARRIER CAPACITY2 PASSVERT TENSION-UP3168.17 LBCARRIER LENGTH9.2 FTFRICTION UPHILL589.03 LBCARRIER WIDTH3.6 FTFRICTION DNHILL495.37 LBCARRIER WIDTH3.6 FTFRICTION DNHILL495.37 LB	*** GENERAL INPUT DATA ***		*** CALCULATED DATA **	*
DRIVE (TOP/BOT)BOTVERTICAL574.9 FTI TENSION (TOP/BOT)BOTSLOPE2726.5 FTI ROTATION (CW/CCW)CWSLOPE ANGLE12.20 DEGGRIP (FIX/DET)FIXEDINTERVAL10.35 SECI INPUT CAPACITY950 PPHDESIGN CAPACITY911.5 PPHDESIGN SPEED490 FPMNO. OF CARRIERS85.00 CAFI OPERATING SPEED374 FPMRHO W/EMPTY CARR3.85 LB/FACCELERATION0 FT/S^2RHO LOADED UP5.51 LB/FPASS/CARR. UPHILL0.63 PASSRHO LOADED DN3.85 LB/FI CARRIER CAPACITY2 PASSVERT TENSION-UP3168.17 LBCARRIER LENGTH9.2 FTFRICTION UPHILL589.03 LBCARRIER WIDTH3.6 FTFRICTION DNHILL495.37 LBCARRIER WIDTH0 PASVERT TENSION DNHILL495.37 LB	ALC UNITS(ENG/SI)	ENG	HORIZONTAL	2658.0 FT
TENSION (TOP/BOT)BOT SLOPE2726.5 FTROTATION (CW/CCW)CW SLOPE ANGLE12.20 DECGRIP (FIX/DET)FIXED INTERVAL10.35 SECINPUT CAPACITY950 PPH DESIGN CAPACITY911.5 PPHDESIGN SPEED490 FPM NO. OF CARRIERS85.00 CAFOPERATING SPEED374 FPM RHO W/EMPTY CARR3.85 LB/FACCELERATION0 FT/S^2 RHO LOADED UP5.51 LB/FPASS/CARR. UPHILL0.63 PASS RHO LOADED DN3.85 LB/FCARRIER CAPACITY2 PASSVERT TENSION-UP3168.17 LBCARRIER LENGTH9.2 FT FRICTION UPHILL589.03 LBCARRIER WIDTH3.6 FT FRICTION DNHILL495.37 LB	RIVE (TOP/BOT)	BOT	VERTICAL	574.9 FT
ROTATION (CW/CCW)CWSLOPE ANGLE12.20 DECGRIP (FIX/DET)FIXEDINTERVAL10.35 SECINPUT CAPACITY950 PPHDESIGN CAPACITY911.5 PPHDESIGN SPEED490 FPMNO. OF CARRIERS85.00 CAFOPERATING SPEED374 FPMRHO W/EMPTY CARR3.85 LB/FACCELERATION0 FT/S^2RHO LOADED UP5.51 LB/FPASS/CARR. UPHILL0.63 PASSRHO LOADED DN3.85 LB/FCARRIER CAPACITY2 PASSVERT TENSION-UP3168.17 LBCARRIER CAPACITY9.2 FTFRICTION UPHILL589.03 LBCARRIER WIDTH3.6 FTFRICTION DNHILL495.37 LBCARRIER WIDTH0.0 LP1.000 LP2.21 LP	ENSION (TOP/BOT)	BOT	SLOPE	2726.5 FT
GRIP (FIX/DET)FIXEDINTERVAL10.35 SECINPUT CAPACITY950 PPHDESIGN CAPACITY911.5 PPHDESIGN SPEED490 FPMNO. OF CARRIERS85.00 CAFOPERATING SPEED374 FPMRHO W/EMPTY CARR3.85 LB/FACCELERATION0 FT/S^2RHO LOADED UP5.51 LB/FPASS/CARR. UPHILL0.63 PASSRHO LOADED DN3.85 LB/FPASS/CARR. DNHILL0 PASSVERT TENSION-UP3168.17 LBCARRIER CAPACITY2 PASSVERT TENSION-DN2213.73 LBCARRIER LENGTH9.2 FTFRICTION UPHILL589.03 LBCARRIER WIDTH3.6 FTFRICTION DNHILL495.37 LB	OTATION (CW/CCW)	CW	SLOPE ANGLE	12.20 DEG
SPACING64.51 FT INPUT CAPACITY950 PPH DESIGN CAPACITY911.5 PPH DESIGN SPEED490 FPM NO. OF CARRIERS85.00 CAR OPERATING SPEED374 FPM RHO W/EMPTY CARR3.85 LB/F ACCELERATION0 FT/S^2 RHO LOADED UP5.51 LB/F PASS/CARR. UPHILL0.63 PASS RHO LOADED DN3.85 LB/F PASS/CARR. DNHILL0 PASS VERT TENSION-UP3168.17 LB CARRIER CAPACITY2 PASS VERT TENSION-DN2213.73 LB CARRIER LENGTH9.2 FT FRICTION UPHILL589.03 LB CARRIER WIDTH3.6 FT FRICTION DNHILL495.37 LB	RIP (FIX/DET)	FIXED	INTERVAL	10.35 SEC
INPUT CAPACITY950 PPHDESIGN CAPACITY911.5 PPHDESIGN SPEED490 FPMNO. OF CARRIERS85.00 CAROPERATING SPEED374 FPMRHO W/EMPTY CARR3.85 LB/FACCELERATION0 FT/S^2RHO LOADED UP5.51 LB/FPASS/CARR. UPHILL0.63 PASSRHO LOADED DN3.85 LB/FPASS/CARR. DNHILL0 PASSVERT TENSION-UP3168.17 LBCARRIER CAPACITY2 PASSVERT TENSION-DN2213.73 LBCARRIER LENGTH9.2 FTFRICTION UPHILL589.03 LBCARRIER WIDTH3.6 FTFRICTION DNHILL495.37 LB			SPACING	64.51 FT
I DESIGN SPEED490 FPMI NO. OF CARRIERS85.00 CAFI OPERATING SPEED374 FPMRHO W/EMPTY CARR3.85 LB/FI ACCELERATION0 FT/S^2RHO LOADED UP5.51 LB/FI PASS/CARR. UPHILL0.63 PASSRHO LOADED DN3.85 LB/FI PASS/CARR. DNHILL0 PASSVERT TENSION-UP3168.17 LBI CARRIER CAPACITY2 PASSVERT TENSION-DN2213.73 LBI CARRIER LENGTH9.2 FTFRICTION UPHILL589.03 LBI CARRIER WIDTH3.6 FTFRICTION DNHILL495.37 LB	IPUT CAPACITY	950 PPH	DESIGN CAPACITY	911.5 PPH
OPERATING SPEED374 FPM RHO W/EMPTY CARR3.85 LB/F ACCELERATION0 FT/S^2 RHO LOADED UP5.51 LB/F PASS/CARR. UPHILL0.63 PASS RHO LOADED DN3.85 LB/F PASS/CARR. DNHILL0 PASS VERT TENSION-UP3168.17 LB CARRIER CAPACITY2 PASS VERT TENSION-DN2213.73 LB CARRIER LENGTH9.2 FT FRICTION UPHILL589.03 LB CARRIER WIDTH3.6 FT FRICTION DNHILL495.37 LB	ESIGN SPEED	490 FPM	NO. OF CARRIERS	85.00 CARR.
ACCELERATION0 FT/S^2RHO LOADED UP5.51 LB/FPASS/CARR. UPHILL0.63 PASSRHO LOADED DN3.85 LB/FPASS/CARR. DNHILL0 PASSVERT TENSION-UP3168.17 LBCARRIER CAPACITY2 PASSVERT TENSION-DN2213.73 LBCARRIER LENGTH9.2 FTFRICTION UPHILL589.03 LBCARRIER WIDTH3.6 FTFRICTION DNHILL495.37 LB	PERATING SPEED	374 FPM	RHO W/EMPTY CARR	3.85 LB/FT
PASS/CARR. UPHILL0.63 PASSRHO LOADED DN3.85 LB/FPASS/CARR. DNHILL0 PASSVERT TENSION-UP3168.17 LBCARRIER CAPACITY2 PASSVERT TENSION-DN2213.73 LBCARRIER LENGTH9.2 FTFRICTION UPHILL589.03 LBCARRIER WIDTH3.6 FTFRICTION DNHILL495.37 LB	CCELERATION	0 FT/S	^2 RHO LOADED UP	5.51 LB/FT
PASS/CARR. DNHILL0 PASSVERT TENSION-UP3168.17 LBCARRIER CAPACITY2 PASSVERT TENSION-DN2213.73 LBCARRIER LENGTH9.2 FTFRICTION UPHILL589.03 LBCARRIER WIDTH3.6 FTFRICTION DNHILL495.37 LB	ASS/CARR. UPHILL	0.63 PAS	S RHO LOADED DN	3.85 LB/FT
CARRIER CAPACITY2 PASS VERT TENSION-DN2213.73 LB CARRIER LENGTH9.2 FT FRICTION UPHILL589.03 LB CARRIER WIDTH3.6 FT FRICTION DNHILL495.37 LB CARRIER WEIGULT114.00 LB ACCELL SODOC LID2021 B	ASS/CARR. DNHILL	0 PAS	S VERT TENSION-UP	3168.17 LB
CARRIER LENGTH9.2 FTFRICTION UPHILL589.03 LBCARRIER WIDTH3.6 FTFRICTION DNHILL495.37 LBCARRIER WEIGUT444.00 LBCARRIER WEIGUT200 LB	ARRIER CAPACITY	2 PAS	S VERT TENSION-DN	2213.73 LB
CARRIER WIDTH 3.6 FT FRICTION DNHILL 495.37 LB CARRIER WIDTH 444.00 LB ACCELL FORCE LID ACCELL FORCE LID	ARRIER LENGTH	9.2 FT	FRICTION UPHILL	589.03 LB
	ARRIER WIDTH	3.6 FT	FRICTION DNHILL	495.37 LB
CARRIER WEIGHT TTT.UU LB ACCELL FORCE UP 0.00 LB	ARRIER WEIGHT	111.00 LB	ACCELL FORCE UP	0.00 LB
CARRIERS ON LINE85 CARR.ACCELL FORCE DN0.00 LB	ARRIERS ON LINE	85 CAR	R. ACCELL FORCE DN	0.00 LB
CARRIERS IN TERM.0 CARR.**TANGENT TENSION0.00 LB	ARRIERS IN TERM.	0 CAR	R. **TANGENT TENSION	0.00 LB
INPUT COUNTER WT. 21700.00 LB TENSION CHANGE UP 3757.20 LB	IPUT COUNTER WT.	21700.00 LB	TENSION CHANGE UP	3757.20 LB
ROPE WEIGHT2.130 LB/FTTENSION CHANGE DN1718.36 LB	OPE WEIGHT	2.130 LB/F	T TENSION CHANGE DN	1718.36 LB
ROPE DIAMETER 1.125 IN TORQUE TENSION 2138.84 LB	OPE DIAMETER	1.125 IN	TORQUE TENSION	2138.84 LB
BREAKING STRENGTH105200.00 LBPOWER-ROPE ONLY10.7 HP	REAKING STRENGTH	105200.00 LB	POWER-ROPE ONLY	10.7 HP
LINE GAUGE8.20 FTPOWER-EMPTY CARR.14.0 HP	INE GAUGE	8.20 FT	POWER-EMPTY CARR.	14.0 HP
RETURN TERMINAL FRICTION50 LBPOWER-FULL LOAD27.9 HP	ETURN TERMINAL FRICTION	50 LB	POWER-FULL LOAD	27.9 HP
DRIVE TERMINAL FRICTION 50 LB ROPE DESIGN FACTOR 7.65	RIVE TERMINAL FRICTION	50 LB	ROPE DESIGN FACTOR	7.65
DRIVE SYSTEM FRICTION25 LBT1:T2 RATIO1.22	RIVE SYSTEM FRICTION	25 LB	T1:T2 RATIO	1.22
SHEAVE MAX LOAD + 1000 LB SHEAR RATIO 44.96	HEAVE MAX LOAD +	1000 LB	SHEAR RATIO	44.96
SHEAVE MAX LOAD - 900 LB DESIGN COUNTER WT 21700.00 LB	HEAVE MAX LOAD -	900 LB	DESIGN COUNTER WT	21700.00 LB
SHEAVE SPACING-C.L. 1.31 FT TENSION T1 9780.58 LB	HEAVE SPACING-C.L.	1.31 FT	TENSION T1	9780.58 LB
PASSENGER WEIGHT170 LB TENSION T211919.42 LB	ASSENGER WEIGHT	170 LB	TENSION T2	11919.42 LB
DRIVE EFFICIENCY0.88TENSION T313637.78 LB		0.88	TENSION T3	13637.78 LB
FRICTION FACTOR0.030 TENSION T3'13537.78 LB		0.030	TENSION T3'	13537.78 LB
METALIC AREA RATIO 0.442 ROPE METALIC AREA 0.559 SQ I	IETALIC AREA RATIO	0.442		0.559 SQ IN
ELASTICITY MODULUS1.310E+07 PSI ROPE LENGTH-ROPE5480.3 FT0.000 PUTDE TENDED TO THE TENDED TO	LASTICITY MODULUS	1.310E+07 PSI	ROPE LENGTH-ROPE	5480.3 FT
OVER LENSION RATIO1.5 ROPE LENGTH-EMPTY5483.4 FT	VER TENSION RATIO	1.5	ROPE LENGTH-EMPTY	5483.4 FT
I MIN SHEAR RATIO 10 I ROPE STRETCH EMPTY 0.2 FT	IIN SHEAR RATIO	10		0.2 FT
MAX 11/12 KATIO 1.9 CARR TRAV ROPE-EMP 1.4 FT		1.9		1.4 FT
LUAD(STD/MAXUP/MAXDN) STD ROPE LENGTH-LOADED 5485.9 FT	LUAD(STD/MAXUP/MAXDN)	SID		5485.9 FI
"FUR SURFACE LIFTS UNLY STRETCH EMP-LOAD 0.1 FT		0.00		
"SNOW FRICTION FACT 0.06 CARR TRAV EMP-LOAD 1.1 FT		0.06 = ====== ====	CAKK IKAV EMP-LOAD	1.1 FI ==== ======= =====
For aerial lifts, set TOW-BAR **TOW BAR PULL 0.00 LB				
and ROPE-SEAT length to 1.0. **BAR ANGLE BETA 0.0 DEC	For aerial lifts, set TOW-BAR		**TOW BAR PULL	0.00 LB
**ROPE-SEAT HEIGHT 1 FT **RHO VERTICAL 0.00 LB/F	For aerial lifts, set TOW-BAR and ROPE-SEAT length to 1.0.		**TOW BAR PULL **BAR ANGLE BETA	0.00 LB 0.0 DEG
**TOW BAR LENGTH 1 FT **RHO TANGENTIAL 0.00 LB/F	For aerial lifts, set TOW-BAR and ROPE-SEAT length to 1.0. ROPE-SEAT HEIGHT	1 FT	**TOW BAR PULL **BAR ANGLE BETA **RHO VERTICAL	0.00 LB 0.0 DEG 0.00 LB/FT

	DATE:	28-Jul-14						Page 2				
	TIME:	11:38:58										
	UPHILL T	OWER POINT	S		DOWNHI	LL TOWER PC	NTS					
			CTF TO	BATTER			CTF TO	BATTER	ACTUA	L	CALCULATE	D
TOWER	STATION	ELEVATION	ROPE PT.	ANGLE	STATION	ELEVATION	ROPE PT.	ANGLE	SHEAVES	SHEAVES	SHEAVES	SHEAVES
NUMBER	Х	Z	LENGTH HT	DEGREES	Х	Z	LENGTH HT	DEGREES	UPHILL	DOWNHILL	UPHILL	DOWNHILL
DR BW AB	-35.90	10.75	10.55	0.00	-35.90	10.75	10.55	0.00	*** ***	*** ***	4 T/2FR	4 T/2FR
T1 PORT AB	23.60	10.75	10.00	0.00	23.60	10.75	10.00	0.00	10 N	10 N	6 D	4 T/2FR
T2 AB	220.20	70.60	32.80	0.00	220.20	70.60	32.80	0.00	10 S	6 S	4 S	4 T/2FR
T3 AB	697.50	150.12	37.72	0.00	697.50	150.12	37.72	0.00	8 S	4 S	4 S	4 T/2FR
T4 AB	1210.50	254.70	37.50	0.00	1210.50	254.70	37.50	0.00	4 S/2N	4 S/2N	4 S	4 T/2FR
T5 AB	1528.40	346.90	26.90	0.00	1528.40	346.90	26.90	0.00	8 S	6 S	4 S	4 T/2FR
T6 AB	2000.70	473.90	37.70	0.00	2000.70	473.90	37.70	0.00	10 S	4 S	4 S	4 T/2FR
T7 AB	2482.10	584.60	32.80	0.00	2482.10	584.60	32.80	0.00	12 S	12 S	4 S	4 T/2FR
UT GD AB	2615.10	585.65	10.55	0.00	2615.10	585.65	10.55	0.00	2 S	2 S	4 S	4 T/2FR
UTBW AB	2622.10	585.65	10.55	0.00	2622.10	585.65	10.55	0.00	*** ***	*** ***	4 S	4 T/2FR

DATE:	28-Jul-14
TIME:	11:38:58

TOWER NUMBER	UPI CHORD LENGTH	HILL CHORD ANG DEGREES	DOW CHORD LENGTH	NHILL CHORD ANG DEGREES	CARRIER C TO GR UPHILL	CLEARANCE COUND DOWNHILL	STATION XCTF	FOUNDATION ELEVATION ZCTF	I CTF-GND DISTANCE	CROSS SLOPE DEGREES	MAXIMUM R ACCELERAT UPHILL	ADIAL TON - G DOWNHILL
DR BW AB	59.50	0.00	59.50	0.00	1.55	1.55	-35.90	0.20	#VALUE!	0.00	0.00	0.00
T1 PORT AB	205.51	16.93	205.51	16.93	0.85	0.85	23.60	0.75	0.05	0.00	0.03	0.03
T2 AB	483.88	9.46	483.88	9.46	21.66	21.66	220.20	37.80	-1.94	0.00	0.03	0.04
T3 AB	523.55	11.52	523.55	11.52	23.90	23.90	697.50	112.40	-4.62	0.00	0.03	0.04
T4 AB	331.00	16.17	331.00	16.17	20.68	20.68	1210.50	217.20	-7.62	0.00	0.04	0.02
T5 AB	489.08	15.05	489.08	15.05	13.40	13.40	1528.40	320.00	-4.30	0.00	0.03	0.03
T6 AB	493.96	12.95	493.96	12.95	20.83	20.83	2000.70	436.20	-7.67	0.00	0.02	0.06
T7 AB	133.00	0.45	133.00	0.45	19.95	19.95	2482.10	551.80	-3.65	0.00	0.03	0.03
UT GD AB	7.00	0.00	7.00	0.00	3.35	3.35	2615.10	575.10	2.00	0.00	0.03	0.03
UTBW AB	0.00	0.00	2686.71	0.00	3.35	3.35	2622.10	575.10	2.00	0.00	0.00	0.00

Г

Page 4

DATE:	28-Jul-14
TIME:	11:38:58

TOWER NUMBER	UPHILL TENSION TENS ALPH	UPHILL TENSION TENS BETA	UPHILL ROPE ANG ALPHA -E	UPHILL ROPE ANG DEG- BETA	UPHILL REACTION ANGLE-DEG	UPHILL MAIN AXEL REACTION	UPHILL LOAD PER SHEAVE	UPHILL SAG TN+1 Fmup	UPHILL SAG CLEAR Gfm	UPHILL SAG STAT Xfm	UPHILL SAG ELEV Zfm	UPHILL ARC LENGTH
DR BW AB	10458.47	10458.47	0.00	-0.35	-90.17	63.35	***	0.09	10.59	-6.15	10.66	59.50
T1 PORT AB	10458.47	10543.18	0.35	15.79	98.07	-2823.65	-282.36	1.06	18.84	121.90	39.61	205.52
T2 AB	10670.66	10733.96	18.06	6.75	-77.60	2109.77	210.98	5.76	29.37	458.85	104.60	484.06
T3 AB	10903.33	10923.16	12.13	8.66	-79.61	660.95	82.62	6.61	25.89	954.00	195.80	523.77
T4 AB	11145.92	11146.53	14.33	14.43	104.38	-20.48	-5.12	2.59	22.21	1369.45	298.21	331.05
T5 AB	11342.92	11374.83	17.88	12.52	-74.80	1063.63	132.95	5.53	22.96	1764.55	404.87	489.24
T6 AB	11645.34	11688.61	17.52	10.44	-76.02	1442.46	144.25	5.50	27.61	2241.40	523.75	494.13
T7 AB	11924.40	12022.16	15.41	-0.22	-82.41	3258.59	271.55	0.39	11.63	2548.60	584.73	133.01
UT GD AB	12024.40	12031.72	1.13	-0.03	-89.45	244.02	122.01	0.00	12.55	2618.60	585.65	7.00
UTBW AB	12031.72	0.00	0.04	-179.96	-179.96	12031.72	***	0.00	0.00	0.00	0.00	0.00

DATE:	28-Jul-14
TIME:	11:38:58

TOWER NUMBER	DOWNHILL TENSION TENS ALPH	DOWNHILL TENSION TENS BETA	Downhill Rope ang Alpha -[DOWNHILL ROPE ANG DEG- BETA	DOWNHILL REACTION ANGLE-DEG	DOWNHILL MAIN AXEL REACTION	DOWNHILL LOAD PER SHEAVE	DOWNHILL SAG TN+1 Fmup	DOWNHILL SAG CLEAR Gfm	DOWNHILL SAG STAT Xfm	DOWNHILL SAG ELEV Zfm	DOWNHILL ARC LENGTH
DR BW AB	11241.53	11241.53	0.00	-0.32	-90.16	63.35 *	**	0.08	10.60	-6.15	10.67	59.50
T1 PORT AB	11241.53	11150.71	0.32	15.86	98.09	-3027.30	-302.73	1.00	18.90	121.90	39.67	205.52
T2 AB	11278.19	11212.72	18.00	6.86	-77.57	2182.42	363.74	5.52	29.61	458.85	104.84	484.05
T3 AB	11382.09	11362.76	12.02	8.77	-79.61	644.55	161.14	6.36	26.14	954.00	196.05	523.76
T4 AB	11585.51	11583.83	14.22	14.50	104.36	-56.07	-14.02	2.50	22.30	1369.45	298.30	331.05
T5 AB	11780.22	11748.05	17.82	12.60	-74.79	1072.08	178.68	5.36	23.13	1764.55	405.04	489.23
T6 AB	12018.56	11974.92	17.45	10.50	-76.03	1454.65	363.66	5.37	27.74	2241.40	523.88	494.12
T7 AB	12210.72	12111.82	15.35	-0.22	-82.43	3296.57	274.71	0.39	11.64	2548.60	584.74	133.01
UT GD AB	12114.05	12106.72	1.12	-0.03	-89.46	244.59	122.30	0.00	12.55	2618.60	585.65	7.00
UTBW AB	12106.72	0.00	0.04	-179.96	-179.96	12106.72 *	**	0.00	0.00	0.00	0.00	0.00

DATE:	28-Jul-14
TIME:	11:38:58

TOWER NUMBER	UPHILL TENSION TENS ALPH	UPHILL TENSION TENS BETA	uphill Rope ang Alpha -[UPHILL ROPE ANG DEG- BETA	UPHILL REACTION ANGLE-DEG	UPHILL MAIN AXEL REACTION	UPHILL LOAD PER SHEAVE	UPHILL SAG TN+1 Fmup	UPHILL SAG CLEAR Gfm	UPHILL SAG ELEV Xfm	UPHILL ARC Zfm	UPHILL TENSION LENGTH
DR BW AB	10332.18	10332.18	0.00	-0.64	-90.32	114.53 *	**	0.16	1.32	10.59	59.50	0.00
T1 PORT AB	10332.19	10409.20	0.64	14.85	97.74	-2567.26	-256.73	1.93	8.77	38.74	205.56	0.00
T2 AB	10639.66	10720.07	18.97	4.56	-78.24	2680.09	268.01	10.36	15.57	100.00	484.47	0.00
T3 AB	11026.27	11071.37	14.22	6.42	-79.68	1503.36	187.92	11.70	11.60	190.71	524.25	0.02
T4 AB	11474.07	11494.02	16.44	13.13	-75.22	665.00	166.25	4.52	11.08	296.28	331.16	0.02
T5 AB	11849.05	11901.56	19.13	10.68	-75.09	1750.39	218.80	9.48	9.81	400.92	489.57	0.04
T6 AB	12390.59	12459.17	19.25	8.70	-76.03	2286.07	228.61	9.27	14.65	519.98	494.43	0.06
T7 AB	12885.44	13005.25	17.06	-0.68	-81.81	3993.95	332.83	0.65	2.17	584.47	133.01	0.02
UT GD AB	13009.30	13020.47	1.58	-0.06	-89.24	372.33	186.17	0.00	3.35	585.65	7.00	0.00
UTBW AB	13020.47	0.00	0.06	-179.94	-179.94	13020.47 *	**	0.00	0.00	0.00	0.00	0.00

Page 7

DATE:	28-Jul-14
TIME:	11:38:58

TOWER NUMBER	DOWNHILL TENSION TENS ALPH	DOWNHILL TENSION TENS BETA	Downhill Rope ang Alpha -E	DOWNHILL ROPE ANG DEG- BETA	DOWNHILL REACTION ANGLE-DEG	DOWNHILL MAIN AXEL REACTION	DOWNHILL LOAD PER SHEAVE	DOWNHILL SAG TN+1 Fmup	DOWNHILL SAG CLEAR Gfm	DOWNHILL SAG ELEV Xfm	DOWNHILL ARC Zfm	DOWNHILL TENSION LENGTH
DR BW AB	11367.82	11367.82	0.00	-0.58	-90.29	114.53 *	***	0.15	1.33	10.60	59.50	0.00
T1 PORT AB	11367.82	11282.42	0.58	15.01	97.79	-2846.48	-284.65	1.78	8.92	38.89	205.55	0.01
T2 AB	11512.88	11429.25	18.81	4.86	-78.16	2787.79	464.63	9.73	16.20	100.63	484.40	0.02
T3 AB	11735.45	11691.04	13.94	6.69	-79.69	1480.37	370.09	11.09	12.21	191.32	524.18	0.03
T4 AB	12093.74	12075.26	16.19	13.27	-75.27	615.95	153.99	4.30	11.30	296.50	331.15	0.03
T5 AB	12430.29	12377.42	18.99	10.85	-75.08	1762.32	293.72	9.12	10.17	401.28	489.53	0.05
T6 AB	12866.45	12797.41	19.09	8.81	-76.05	2301.44	575.36	9.03	14.89	520.22	494.40	0.06
T7 AB	13223.67	13102.61	16.96	-0.67	-81.85	4035.42	336.28	0.65	2.18	584.48	133.01	0.02
UT GD AB	13106.65	13095.47	1.57	-0.06	-89.24	372.80	186.40	0.00	3.35	585.65	7.00	0.00
UTBW AB	13095.47	0.00	0.06	-179.94	-179.94	13095.47 *	***	0.00	0.00	0.00	0.00	0.00

	DATE:	28-Jul-14						STANDARD L	OAD CASE			Page 8
	TIME:	11:38:58			UPHILL RO	PE + CARRIER	RS with	32%	UPHILL LOA	D		
								0%	DOWNHILL I	OAD		
	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL
TOWER	TENSION	TENSION	ROPE ANG	ROPE ANG	REACTION	MAIN AXEL	LOAD PER	SAG TN+1	SAG CLEAR	SAG ELEV	ARC	TENSION
NUMBER	TENS ALPH	TENS BETA	ALPHA -D	DEG- BETA	ANGLE-DEG	REACTION	SHEAVE	Fmup	Gfm	Xfm	Zfm	LENGTH
								-				
DR BW AB	9805.58	9805.58	0.00	-0.96	-90.48	163.91	***	0.25	1.23	10.50	59.50	0.00
T1 PORT AB	9805.58	9871.58	0.96	13.79	97.37	-2199.93	-219.99	2.90	7.80	37.78	205.62	-0.01
T2 AB	10201.40	10296.53	19.97	2.18	-78.92	3171.09	317.11	15.34	10.59	95.02	485.18	-0.02
T3 AB	10734.75	10804.43	16.44	4.07	-79.74	2322.52	290.32	17.02	6.28	185.39	525.03	-0.01
T4 AB	11380.75	11421.42	18.60	11.79	-74.80	1355.78	338.95	6.46	9.14	294.34	331.34	0.00
T5 AB	11929.52	12001.55	20.37	8.86	-75.38	2400.99	300.12	13.34	5.95	397.06	490.05	0.01
T6 AB	12701.42	12793.81	20.90	7.03	-76.03	3079.67	307.97	12.83	11.08	516.42	494.85	0.03
T7 AB	13403.86	13542.21	18.60	-1.10	-81.25	4611.59	384.30	0.90	1.93	584.23	133.02	0.01
UT GD AB	13547.99	13562.78	2.00	-0.08	-89.04	492.87	246.44	0.00	3.35	585.65	7.00	0.00
UTBW AB	13562.78	0.00	0.08	-179.92	-179.92	13562.78	***	0.00	0.00	0.00	0.00	0.00

	DATE:	28-Jul-14						STANDARD L	OAD CASE			Page 9
	TIME:	11:38:58			DOWNHILL F	ROPE + CARRI	ERS with	0%	DOWNHILL	LOAD		
								32%	UPHILL LOA	D		
	DOWNHILL	DOWNHILL	DOWNHILL	DOWNHILL	DOWNHILL	DOWNHILL	DOWNHILL	DOWNHILL	DOWNHILL	DOWNHILL	DOWNHILL	DOWNHILL
TOWER	TENSION	TENSION	ROPE ANG	ROPE ANG	REACTION	MAIN AXEL	LOAD PER	SAG TN+1	SAG CLEAR	SAG ELEV	ARC	TENSION
NUMBER	TENS ALPH	TENS BETA	ALPHA -[DEG- BETA	ANGLE-DEG	REACTION	SHEAVE	Fmup	Gfm	Xfm	Zfm	LENGTH
DR BW AB	11894.42	11894.42	0.00	-0.55	-90.28	6479.34	***	0.14	1.34	10.61	59.50	0.00
T1 PORT AB	11894.42	11804.39	0.55	15.09	97.82	-3000.93	-300.09	1.71	9.00	38.97	205.55	0.01
T2 AB	12034.85	11949.17	18.73	5.06	-78.10	2856.01	476.00	9.31	16.62	101.05	484.36	0.03
T3 AB	12255.38	12211.51	13.75	6.90	-79.68	1462.09	365.52	10.63	12.68	191.78	524.13	0.04
T4 AB	12614.21	12597.00	16.00	13.39	-75.30	573.89	143.47	4.13	11.47	296.67	331.14	0.02
T5 AB	12952.02	12898.84	18.88	11.02	-75.05	1772.79	295.46	8.76	10.53	401.64	489.50	0.03
T6 AB	13387.87	13318.24	18.94	8.97	-76.05	2320.96	580.24	8.68	15.23	520.57	494.37	0.04
T7 AB	13744.51	13620.04	16.81	-0.62	-81.91	4148.77	345.73	0.63	2.20	584.50	133.01	0.01
UT GD AB	13624.09	13612.78	1.53	-0.06	-89.26	376.89	188.44	0.00	3.35	585.65	7.00	0.00
UTBW AB	13612.78	0.00	0.06	-179.94	-179.94	13612.78	***	0.00	0.00	0.00	0.00	0.00

	MAXIMUM DE	SIGN TENSIC	DN:	CARRIERS LO	DADED UP TO	ONE TOWER BELC	WC				Page 10
DATE:	28-Jul-14		TEST MAXIM	IUM DESIGN T	ENSION *	1.30	TEST MAXIN	IUM DESIGN T	ENSION * 1.0	00	
TIME:	11:38:58		ADJACENT S	SPANS HAVE F	ROPE + EMPT	Y CARRIERS	ADJACENT S	SPANS HAVE F	ROPE + EMPT	Y CARRIERS	
	UPHILL TENSION	UPHILL TENSION		UPHILL ROPE ANG	UPHILL MAIN AXEL	UPHILL REACTION		UPHILL ROPE ANG	UPHILL MAIN AXEL		FULL LOAD SAG
NUMBER	TENS ALPH	TENS BETA	ALPHA -0	leg- BETA	REACTION	ANGLE-DEG	ALPHA -	Jeg- BETA	REACTION	ANGLE-DEG	RATIO
DR BW AB	10332.18	10332.18	0.00	-0.49	114.53	-90.24	0.00	-0.64	114.53	-90.32	0.42%
T1 PORT AB	10332.19	10409.20	0.49	15.34	-3485.66	97.91	0.64	14.85	-2568.27	97.74	1.41%
T2 AB	10696.12	10776.52	18.50	5.73	3105.56	-77.89	18.96	4.60	2685.37	-78.22	3.17%
T3 AB	11157.74	11202.84	13.11	7.68	1378.73	-79.61	14.18	6.51	1497.57	-79.66	3.25%
T4 AB	11704.19	11724.14	15.27	13.89	366.78	-75.42	16.37	13.20	648.35	-75.22	1.95%
T5 AB	12166.14	12218.65	18.41	11.81	1826.14	-74.89	19.06	10.82	1754.60	-75.06	2.73%
T6 AB	12827.49	12896.07	18.20	9.81	2447.80	-75.99	19.12	8.86	2303.00	-76.01	2.60%
T7 AB	13426.76	13546.58	16.01	-0.38	5001.76	-82.18	16.91	-0.63	4115.46	-81.86	0.68%
UT GD AB	13551.61	13562.78	1.29	-0.04	408.78	-89.38	1.53	-0.03	370.59	-89.25	0.04%
UTBW AB	13562.78	0.00	0.04	-179.96	17631.62	-179.96	0.03	-179.97	13562.78	-179.97	0.00%

		MINIMUM DE	SIGN TENSIO	N:	CARRIERS LO	DADED FROM	ONE TOWER	BELOW TO T	OP			Page 11
DATE:	28-Jul-14		TEST MINIM	UM DESIGN T	ENSION *	0.70			TEST MINIMU	JM TENSION *	1.00	
TIME:	11:38:58		WITH ADJAC	ENT SPANS L	OADED				WITH SINGLE	E LOADED SPA	N	
	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL	UPHILL
TOWER	TENSION	TENSION	ROPE ANG	ROPE ANG	MAIN AXEL	REACTION	ROPE ANG	ROPE ANG	MAIN AXEL	REACTION	SAG TN+1	SAG CLEAR
NUMBER	TENS ALPH	TENS BETA	ALPHA -c	deg- BETA	REACTION	ANGLE-DEG	ALPHA -c	deg- BETA	REACTION	ANGLE-DEG	Fmup	Gfm
DR BW AB	9805.58	9805.58	0.00	-1.37	163.90	-90.68	0.00	-0.96	163.91	-90.48	0.43	1.06
T1 PORT AB	9805.58	9871.58	1.37	12.40	-1325.23	96.89	0.96	13.78	-2198.40	97.37	2.80	7.90
T2 AB	10144.94	10240.08	21.25	-1.07	2762.85	-79.91	19.98	2.11	3166.77	-78.95	16.39	9.54
T3 AB	10603.28	10672.96	19.39	0.64	2426.50	-79.99	16.50	3.94	2328.59	-79.78	17.53	5.78
T4 AB	11150.63	11191.30	21.63	9.71	1625.15	-74.33	18.72	11.68	1371.30	-74.80	6.68	8.93
T5 AB	11612.42	11684.45	22.25	5.85	2326.15	-75.95	20.47	8.66	2397.52	-75.43	14.52	4.77
T6 AB	12264.53	12356.92	23.53	4.10	2908.23	-76.18	21.08	6.80	3061.86	-76.06	14.06	9.85
T7 AB	12862.54	13000.89	21.22	-1.85	3621.36	-80.32	18.81	-1.16	4488.06	-81.17	0.95	1.88
UT GD AB	13005.68	13020.47	2.76	-0.12	457.56	-88.68	2.07	-0.08	488.59	-89.01	0.06	3.29
UTBW AB	13020.47	0.00	0.12	-179.88	9114.33	-179.88	0.09	-179.91	13020.47	-179.91	0.00	0.00

DATE:	28-Jul-14
TIME	11.38.58

Page 2	12
--------	----

		I IIVIE.	11.30.30											
TOWER NUMBER	UPHILL SHEAVES	UPHILL REACTION LOADED	UPHILL LOAD/SHV LOADED	UPHILL REACTION EMPTY	UPHILL LOAD/SHV EMPTY	UPHILL REACTION ROPE	UPHILL LOAD/SHV ROPE	DN HILL SHEAVES	DN HILL REACTION LOADED	DN HILL LOAD/SHV LOADED	DN HILL REACTION EMPTY	DN HILL LOAD/SHV EMPTY	DN HILL REACTION ROPE	DN HILL LOAD/SHV ROPE
DR BW AB *	BW AB *** *** 163.91 **		**	114.53 ***		63.35 ***		*** ***	6479.34 ***		114.53 ***		63.35 ***	
T1 PORT AB	10 N	-2199.93	-219.99	-2567.26	-256.73	-2823.65	-282.36	10 N	-3000.93	-300.09	-2846.48	-284.65	-3027.30	-302.73
T2 AB	10 S	3171.09	317.11	2680.09	268.01	2109.77	210.98	6 S	2856.01	476.00	2787.79	464.63	2182.42	363.74
T3 AB	8 S	2322.52	290.32	1503.36	187.92	660.95	82.62	4 S	1462.09	365.52	1480.37	370.09	644.55	161.14
T4 AB	4 S/2N	1355.78	338.95	665.00	166.25	-20.48	-5.12	4 S/2N	573.89	143.47	615.95	153.99	-56.07	-14.02
T5 AB	8 S	2400.99	300.12	1750.39	218.80	1063.63	132.95	6 S	1772.79	295.46	1762.32	293.72	1072.08	178.68
T6 AB	10 S	3079.67	307.97	2286.07	228.61	1442.46	144.25	4 S	2320.96	580.24	2301.44	575.36	1454.65	363.66
T7 AB	12 S	4611.59	384.30	3993.95	332.83	3258.59	271.55	12 S	4148.77	345.73	4035.42	336.28	3296.57	274.71
UT GD AB	2 S	492.87	246.44	372.33	186.17	244.02	122.01	2 S	376.89	188.44	372.80	186.40	244.59	122.30
UTBW AB *	** ***	13562.78 *	**	13020.47	***	12031.72 *	** *	*** ***	13612.78 *	***	13095.47	***	12106.72 *	**

APPENDIX B SERVICE BULLETINS



A CORPORATE PARTNERSHIP of MUELLER LIFTS LTD. TIM ATTRIDGE LTD.

21. th STREET VERNON, B.C. VIT 449

TELEPHONE 542-3368 . CABLE ADDRESS, LIFTMUELLER . TELEX 048-85268 (MUELLER VRN)

Associated with MUELLER LIFTS A.G., ZURICH, SWITZERLAND

November 21, 1983

Ministry of Transportation & Highways Suite 245 - 4299 Canada Way Burnaby, B.C. V5G IH9

Attention: Mr. F.H. Christensen Chief Inspecting Engineer

Re: Cable catcher channels

Dear Sir,

Following a request from your inspector Mr. A. Lowe during my recent visit to the Burnaby offices, we enclose our drawing no. 83.20.11 showing a small modification.

We only had one customer (Hemlock Valley) who had requested this modification for the Skyline Chair, which is subject to extreme wind conditions.

We suggest that this modification should be permitted on any Mueller lifts operating in very high wind situations.

Yours truly K. Ernst

Manager



enc. KE/pk





Copy to RB pbe

MUELLER LIFTS LTD.

GMD MUELLER LIFTS A.G., ZURICH, SWITZERLAND T-BARS - CHAIRLIFTS - GONDOLAS

BORER SWITZERLAND PLATTERS HANDLE TOWS

FILE 1507.2

Ministry of Municipal Affairs Suite 245 4299 Canada Way Burnaby, B.C. V5G 1H9

Attention: Tom Hamilton

MIN. OF MUNICIPAL AFFAIRS RECEIVED MAR 1 1 1994 ENGINEERING & INSPECTION BRANCH

Service Bulletin BURNABY, B.C.

March 7/94

1

Re: Triple Chair Carrier clearance on sheave assemblies

Dear Sirs,

It was brought to our attention that a certain position of the axle and spacer rings could reduce the lateral swing clearance of the chair hanger to the axle coverplate.

1. Please verify that there are not more than 2 spacer rings on the <u>outside</u> of the sheave assembly. This should be done immediately and spacer ring adjustments made if necessary.

<u>Also note</u>: Tilting the sheave assembly towards the outside increases the swing clearance - tilting the sheave assembly towards the inside reduces the swing clearance!

2. In 1983 a field modification was made to the shape and height of the rope catchers. The use of a field template may have resulted in a variance of the rounded outside portion of the rope catcher. We suggest to check the swing clearance of 15 degrees with a magnetic angle indicator on top of the clamp. This should be checked and done not later than the '94 summer season.

Please contact us if you require further information in this matter.

Yours t

Mueller Lifts Ltd.
MUELLER LIFTS LTD.

ROWEMA AG, SWIZERLAND TEARS - CHARLIFTS - GONDOLAS

BORER TECHNIK AG, SWITZERLAND PLATTERS - HANDLE TOWS T.A.S., FRANCE, Avalanche Control

March 25, 1997

To: Crystal Mtn. Resorts Ltd. Westbank Postal Outlet Box 26044 Westbank, BC V4 2G3

Dear Customer,

We enclose a service bulletin from the Swiss Manufacturer of Mueller Lifts. We also enclose drawing No. 97.02.21, showing the situation on cable catchers on existing sheave assemblies. If you have not made any modifications, none are required.

We encourage you to upgrade all old chair stems as per item 2 of the enclosed bulletin.

Please do not hesitate to call us if you require further information.

Yours truly,

Karl Ernst Mueller Lifts Ltd.



FEBRUARY 1997

1.1

SERVICE BULLETIN

Dear Sus.

1. ROPE CATCHERS ON Ø 12 INCH PULLEY ASSEMBLIES

It was brought to our attention that some customers in Canada have made unauthorized modifications to the rope-catchers on standard Mueller rockers for cable sizes of 1 ½ and 1 1/8 inches.

The function of the rope catcher channel is to retain the rope, therefore the maximum bevelling or rounding of the rope catcher channel on each end is 12 mm (1/2 inch), see attached drawing no 97,02,21 Any 4-er and 6-er rockers that exceed these measurements must be corrected or exchanged prior to the next operating senson.

2. CHAIR STEMS FOR CENTRE POST DOUBLE CHAIRS

Any chait stems older that 25 years should be exchanged for the new model which features increased swing clearance and welding certification according to the new code requirements.

We request that all existing double chairs with centre post chair stems are up-graded to meet the above requirements prior to September 1997

For further information, please contact Mueller Lifts Ltd., Vernon B C

Yours truly.

ROWEMA

K AREALIZVILLER



1.1

APPENDIX C SWING CLEARANCE MODELS



Rope Grip position at Location 2 (recorded in ESG staff field notes). Chair backward angle: 0° .



Tower and Chair configuration looking uphill.



Tower and Chair configuration looking across the line.







Tower and Chair configuration looking uphill.



Tower and Chair configuration looking across







Tower and Chair configuration looking uphill.







Tower and Chair configuration looking across the line.









Tower and Chair configuration looking uphill.

Tower and Chair configuration looking across the line.



Photo group 6

Initial contact from stem entry point puncture and rope catcher. Chair backward angle: 33.2°





Tower and Chair configuration looking uphill.



Tower and Chair configuration looking across the line.



Chair backward angle: 0° $(\cdot) \Delta$ Inward Angle: 16.2°

Tower and Chair configuration looking across the line.











Restrainer bar in the closed position making contact with the rope. Inward angle: 15.9° Backward angle: 45.4°



Restrainer bar in the open position making contact with the rope. Inward angle: 9.7° Backward angle: 40.2°

APPENDIX D MUELLER DRAWINGS









Appendix D Blue Chairlift Timeline

The Blue Chairlift was installed in 1967 and was operated until 2014. The ropeway history is summarized below:



Figure D-1: Blue Chairlift Timeline

[1] 1967

Ropeway (Blue Chairlift) designed and installed Code silent on rope catcher placement

[2] 1968

CAN/CSA Z98 published

Rope catcher requirement:

Rope catcher placement extends at least 2.5 rope diameters outside of sheave flanges and prevents vertical displacement

[3] 1969

Ropeway modification Height of towers #4 and #5 modified

[4] 1983

Rope catcher modification made available by the manufacturer

[5] 1991

a. CAN/CSA Z98 M1991 published

Rope catcher requirement updated: Adequate means shall be provided to retain haul rope if it leaves normal run position located not more than half-sheave diameter from normal run position

b. Ropeway modification Chair guide added

_

[6] 1992

Ropeway modification Carrier replacement program completed

[7] 2014

Deropement