

SUPPORTING INFORMATION	Incident Date			July 26, 2016
	Location			West Vancouver
	Regulated industry sector			Natural Gas System
	Impact	Injury	Qty injuries	4
			Injury description	One person deceased, one person was found unconscious and was taken to hospital in critical condition and two other individuals were transported to hospital for further treatment.
			Injury rating	Fatal
		Damage	Damage description	N/A
			Damage rating	None
	Incident rating			Severe
	Incident overview			The fire department responded to a 911 call and discovered four individuals who had suffered various degrees of carbon monoxide poisoning. The fire department measured up to 900 parts per million of carbon monoxide in the ambient air within the home. No carbon monoxide detectors were found to be installed within the home so the residents were not alerted to the presence of carbon monoxide.
INVESTIGATION	Site, system and components		em and ents	The mechanical system within the home is comprised of two main components, a low mass fin tube hot water boiler which provides heat for the domestic hot water, fan coil, pool and spa and an air handling unit which moves air throughout the home to be either heated in the winter by the boiler water or cooled in the summer by the outdoor condensing unit. The basic configuration of the mechanical system is illustrated below in Figure 1, and the components are discussed following the illustration.







	through two coils, one coil will heat the air in the winter and one will cool the air in the summer. The heated or cooled air is then distributed throughout the home through a separate sealed "supply" air ducting system. Any area within a home which has return air drawn from it will also have supply air provided to it to ensure a balanced system.
Failure scenario(s)	A negative ambient pressure condition was created within the homes mechanical room due to a large unrestricted opening in the return air ductwork serving an air handling unit installed within the room. The opening in the return air ductwork allowed the air handling unit to draw large amounts of air from the mechanical room without supplying any air back into the room, lowering the ambient pressure in the room. Additionally it was identified that the combustion air supply to the mechanical room was fully blocked. The negative pressure within the room caused air to be drawn from the outdoors down through the boilers venting system and into the mechanical room. When the boiler was energized, due to the flow of air down through the venting system, it was not able to vent the flue gases (containing carbon monoxide) to the outdoors and they began to fill the mechanical room. As the boiler continued to operate and the flue gases continued to fill the mechanical room the oxygen content within the air in the mechanical room would begin to deplete causing the boiler to create excessive levels of carbon monoxide due to incomplete combustion. Due to the air handling unit continually drawing air from the mechanical room, the flue gases containing carbon monoxide were drawn into the return air ducting system and distributed throughout the home. Since the majority of the windows and doors within the home were closed the flue gases within the home were contained and continued to increase as the boiler operated. Figure 2 illustrates the configuration observed and measured air flow. The residents within the home were not alerted to the increasing levels of carbon monoxide within the home due to the fact that there were no carbon monoxide detectors installed
	within the home.







	<ul> <li>Multiple smoke tests were performed within the mechanical room which found that the air within the mechanical room was being drawn with force into a large unrestricted opening in the return air ductwork.</li> </ul>
Causes and contributing factors	<ul> <li>It is highly probable that the main cause of the incident can be attributed to the large unrestricted opening in the return air duct work creating a reduced ambient pressure condition in the mechanical room.</li> <li>Multiple contributing factors which were identified were: <ul> <li>A blocked/inadequate combustion air supply into the mechanical room.</li> <li>An elongated boiler run time.</li> <li>A lack of carbon monoxide detectors within the home which would have alerted the residents to the presence of carbon monoxide.</li> </ul> </li> </ul>

#### Figure 3: Natural gas boiler (green arrow) and Air handling unit (red arrow)







Figure 4: Proximity of dryer vent (red arrow) to combustion air supply intake (blue arrow)



Figure 5: Blocked combustion air supply (outdoor termination)



Figure 6: Obstructed combustion air supply ductwork (mechanical room ceiling)





Figure 7: Match flame being forced downward (The red arrow represents the flow of air down and out through the draft hood)







#### Figure 8: Open ceiling space housing return air ductwork drawing air from the mechanical room



Figure 9: Return air ductwork in ceiling space and large unrestricted opening into ductwork (The red arrow represents the path of airflow into the return air ducting system)

