



**Acuren Group Inc.**

12271 Horseshoe Way  
Richmond, BC, Canada V7A 4V4  
[www.acuren.com](http://www.acuren.com)

Phone: 604.275.3800  
Fax: 604.274.7235

**A Higher Level of Reliability**



**KICKING HORSE MOUNTAIN SKI RESORT  
GOLDEN EAGLE EXPRESS  
LEITNER-POMA OF AMERICA GONDOLA**

**HANGER ARM FAILURE**

**Prepared for:**

TECHNICAL SAFETY B.C.  
2889 East 12 Avenue  
Vancouver, B.C.  
V5M 4T5

**Attention:**

Mr. Ryan Hazlett P.Eng.  
Leader, Incident Investigations  
Provincial Safety Manager

File Number: 605-J215610  
EGBC Permit Number: 1001973  
Date: January 28, 2026

**TECHNICAL SAFETY BC**

Leitner-Poma Gondola Arm Failure Kicking Horse Ski Area

Page 1 of 77

**TABLE OF CONTENTS****CONTENTS**

Table of contents .....	1
Executive Summary.....	2
1.0 INTRODUCTION.....	3
2.0 GONDOLA ARM HISTORY .....	3
3.0 NON-DESTRUCTIVE TESTING AT SITE.....	4
4.0 FAILURE ANALYSIS.....	4
4.1 VISUAL EXAMINTION .....	4
4.1.1 Laser Scanning of Arm and Fracture Surface .....	6
4.2 KEYANCE EVALUATION OF FRACTURE SURFACE .....	10
4.3 SCANNING ELECTRON MICROSCOPE EVALUATION OF FRACTURE SURFACE.....	12
4.4 STEEL PHYSICAL PROPERTIES .....	14
4.4.1 CHEMICAL ANALYSIS .....	15
4.4.2 TENSILE TESTS .....	15
4.4.3 CHARPY IMPACT TESTING .....	15
4.4.5 METALLOGRAPHY.....	17
5.0 DISCUSSION OF FINDINGS .....	17
6.0 CONCLUSIONS.....	21
7.0 ADDITIONAL CONSIDERATIONS .....	22



## EXECUTIVE SUMMARY

The gondola arm fractured due to sudden brittle cleavage preceded by fatigue cracking at 4 distinct areas in the pipe cross section. The following causes contributed to the arm fracture:

1. The arm was fabricated from ASTM A500 B steel pipe. This material may not be suitable for dynamic loading conditions requiring low temperature fracture toughness as stated in the ASTM A500 specification. Low temperature requirements for steel used in dynamic loading conditions should be specified.
2. The arm was cold bent into shape which further reduced the toughness of the material in the bend area through a phenomenon known as strain age embrittlement. Strain age embrittlement occurs due to cold work in combination with the heating cycle associated with galvanizing.
3. A multi-step fracture sequence occurred which included 4 zones of fatigue cracking followed by a final overload consisting of brittle cleavage. Cracking was not found during daily (operator) or bi-yearly (professional inspection company) inspections.
4. The fracture origin was a multi-mode thumbnail shaped precrack that contained both fatigue cracking and shallow brittle cleavage crack growth mechanisms. The initial shallow brittle fractures (within the thumbnail) were likely created by very short duration high strain rate loading. Impact dents found in the upper arm support bracket would account for this type of loading.
5. A larger brittle fracture initiated when the thumbnail reached a depth of 5mm. This crack arrested for a period of time when the tougher material associated with the pipe seam weld was encountered. Fatigue cracks grew through the tougher weld zone and final brittle overload occurred when a critical through-wall circumferential crack length of 26 cm was reached.



The steel arm was not overloaded by in-service stresses. The poor fracture toughness of the steel, in combination with cold bending fabrication practices and impact loads at the station in normal service, were the primary contributors to the failure.

## 1.0 INTRODUCTION

A gondola arm from a Leitner- Poma gondola lift at the Kicking Horse Ski Area suffered a catastrophic failure during normal operations. The arm was in service for approximately 25 years and had been inspected regularly using visual and magnetic particle (MT) techniques required by the manufacturer and CSA Z98 requirements. The gondola was last inspected in 2023. The failure resulted in the gondola falling approximately 3 m to the ground and rolling to a stop.

The failed gondola arm had serial number 026400 stamped into the welded plate at the end of the arm. An undamaged gondola arm from the same lift and vintage was submitted to the Acuren lab for inspection at the same time (Serial number 026600). It is understood that the number of gondolas operated on the line was increased from 29 to 55 in 2006.

Acuren was asked to perform failure analysis on the fractured arm. The undamaged arm was used for test comparisons. The failed arm and the undamaged arm were brought to the Acuren Facility on 14 March, 2025. Another 3 intact arms were brought to the laboratory for further testing on 30 June, 2025.

## 2.0 GONDOLA ARM HISTORY

The Kicking Horse Gondola was originally built with 29 gondolas and operated this way for a number of years. The gondola was upgraded to 55 gondola cars in 2006 and has operated this way continuously since 2006. It is understood that the arm was fabricated from carbon steel

meeting the specification requirements of ASTM A500 grade B and was cold bent into its final form. The arm was hot-dip galvanized after fabrication.

The gondola arm that failed had suffered a severe impact on the upper arm guideway bracket that resulted in permanent bending of the bracket. This damage is remote from the arm failure location. Evidence of smaller impacts on this and other arm brackets was reported.

### **3.0 NON-DESTRUCTIVE TESTING AT SITE**

Technical Safety B.C. requested that an NDT technician be sent to the site to check other arms for cracking using magnetic particle inspection (MT) techniques. No cracks in other support arms were found at this time (NDT Report 1; Appendix C) After preliminary failure analysis was complete, another 24 gondola arms were checked for cracks using an ultrasonic technique (UT) developed specifically for looking for cracks in the intrados of the arm at the same location where the failure took place. No cracks were found (NDT report 2; Appendix C) at the intrados of any of the arm bends using these techniques.

### **4.0 FAILURE ANALYSIS**

#### **4.1 VISUAL EXAMINTION**

Overall views of the fractured arm are shown in Figures 1 – 7. The bend intrados is arbitrarily labelled as the 6:00 o'clock position. The fracture origin is at roughly the 07:00 position (looking forward toward the bolted connection) near the intrados of the bend in a small thumbnail shaped area shown in Figure 8. A higher magnification view of the thumbnail feature is shown in Figure 9. The red mark is at the centerline of the intrados of the bend. Discolouration on the thumbnail fracture surface reveals notable features:

1. The thumbnail fracture surface contains 3 small origins and 5 distinct growth zones. The zones have varying amount of corrosion product on them, indicating a certain amount of time had passed between the formation of each zone.
2. The galvanized layer cracked uniformly through the thumbnail zone. No evidence of previously molten zinc is present on the fracture surface.
3. Zone 1 and zone 2 have a brittle appearance.
4. Zone 3 has a fine texture typical of fatigue cracking.
5. Zone 4 has a brittle appearance similar to zones 1 and 2.
6. Zone 5 has a fine texture similar to zone 3 and is typical of fatigue cracking.

Beyond the thumbnail feature, the fracture appearance is brittle around the circumference of the pipe until the pipe seam weld is reached. At this point, the brittle fracture arrested and fatigue cracking occurred through the weld zone (Figure 10). A similar crack arrest and fatigue crack initiation occurred on the pipe cross section opposite to the weld at the same relative location (Figure 11). Once the tougher weld metal was passed through by fatigue cracking, a final brittle overload of the pipe occurred suddenly in bending.

A large open crack would have been visible to the naked eye for a period of time while the fatigue crack grew through the weld metal. The last inspection of the arm by a professional inspection company (Intermountain Inspection) was in 2023. It is probable that the fatigue cracking through the weld zone grew over a period of at least a few weeks and the brittle crack between the thumbnail and the weld metal would have been visible at this time. The visible evidence shows that the crack had a total length of 12 cm before weld metal fatigue cracking started. The final brittle fracture traversed approximately 26 cm of the pipe circumference in an irregular brittle fracture path. A scratch mark was found on the external surface of the pipe which originated on one side of the crack. It is understood that all of the hanger arms were visually inspected by a millwright 3 days




before the incident. It is possible that an inspector noticed something resembling a crack and picked at it with a sharp tool. The scratch is precisely at the center of the thumbnail (Figure 12).


No other cracks were found on the fractured galvanized surface. Evidence of rubbing was found at one location on the arm surface (Figure 13), and a large dent was present on a reinforcing bracket near the upper attachment pin (Figure 14). This damage likely occurred from contact with some of the station hardware while the gondola was in operation. The impact required to create the observed bracket deformation was severe and likely contributed to some part of the arm fracture history.

#### 4.1.1 Laser Scanning of Arm and Fracture Surface

An optical laser scanner was used to determine the shape of the fractured pipe arm at the location of the bend and the overall angle of the bend at the fracture location. An exemplar arm was used to determine the bend angle (Chair No. 21).




**Scan of Exemplar Arm Chair No.21 (no serial Number)**



**Bend Angle - Chair No. 21 (no serial number)**

A further scan at the fracture location shows the degree of permanent ovality caused by the cold bending operation. The fracture origin thumbnail is near the point where the pipe ovality is most pronounced. (highest amount of cold work).

The observed ovality is caused by the cold bending method used to form the hanger. There was no apparent attempt to reduce or eliminate pipe deformation during the cold forming operation. A roughly 1 cm difference in ID exists between the two planes of the bend.



Pipe Ovality at Fracture Surface

#### 4.2 KEYANCE EVALUATION OF FRACTURE SURFACE

Segments of the arm fracture surface were examined with a Keyence light microscope. This microscope is capable of viewing surfaces up to 5000 times with good depth of field by taking images over small areas and assembling the views to make a single in-focus image.

The fracture origin area near the intrados of the bend is shown in Figure 15. The thumbnail shaped origin initially started as three small thumbnails which eventually joined together to form a single crack front. The larger thumbnail contains 5 distinct zones beneath the fractured outer galvanized layer as numbered on Figure 15. Each zone was examined using a scanning electron microscope to confirm the fracture mode in each zone (Section 4.3).

Magnified views of the entire fracture surface are shown in segments around the circumference of the pipe. The fracture features on each segment is described in Table 1:

**Table 1 – Description of Fracture Features**

Approximate Position	Figure No.	Description
0 7:00 origin	16	Multi-zone thumbnail shaped fracture origin
1	17	Full thumbnail
2	18	Brittle Cleavage
3	19	Brittle Cleavage
4	20	Brittle Cleavage
5	21	Fatigue starting at HAZ of weld



6	22	Brittle cleavage; edge smearing
7	23	Brittle cleavage; edge smearing
8	24	Brittle Cleavage; edge smearing
9	25	Brittle Cleavage; edge smearing
10	26	Brittle Cleavage; edge smearing
11	27	Brittle cleavage; edge smearing
12	28	Brittle cleavage
13	29	Brittle cleavage edge smearing
14	30	Brittle Cleavage edge smearing
15	31	Brittle Cleavage edge smearing
16	32	Brittle Cleavage
17	33	Brittle Cleavage
18	34	Brittle Cleavage
19	35	Brittle Cleavage
20	36	Cleavage plus fatigue opposite weld
21	37	Brittle Cleavage
22	38	Brittle Cleavage
23	39	Brittle cleavage
24	40	Brittle Cleavage
25	41	Cleavage plus thumbnail origin

There are fatigue features in two zones (zones 3 and 5) in the origin thumbnail. Fatigue features are also found at the pipe weld, and at roughly a position 15 cm circumferentially from the pipe weld. It is clear that the brittle fracture below the thumbnail and around the circumference of the pipe was arrested when it reached the tougher modified microstructure of the pipe weld metal and heat affected zone. Fatigue cracking with fine striations started after the initial arrest of the brittle crack at these locations . Striation

spacing in the weld metal fatigue zone was very fine (approximately 0.3  $\mu\text{m}$ ), (Section 4.3), which indicates that nominal dynamic stresses were very low relative to the yield strength of the steel.

Very similar features were found in the fatigue zone opposite the weld metal. Although the microstructure was not altered at this location, the running brittle fracture arrested when the weld metal was encountered on the opposite side of the crack. Fatigue cracking originated at this location in an identical manner as the opposite side of the pipe at the weld metal.

The majority of the fracture surface was brittle cleavage outside of the small fatigue zones. This indicates that the fracture toughness of the ASTM A500 grade B pipe was poor at the ambient temperature on the day of the failure.

#### 4.3 SCANNING ELECTRON MICROSCOPE EVALUATION OF FRACTURE SURFACE

A scanning electron microscope was used to examine fracture features on the arm fracture surface. The areas examined include each zone in the thumbnail shaped fracture origin, the fatigue indications in pipe weld zone and area opposite the weld zone, and in select areas between the fatigue areas and the last areas to fail. Table 2 lists the locations of SEM examinations and the image number representing the areas examined.

**Table 2 - SEM Images of Fracture Features**

Image Location	Figure Number	Description
Thumbnail origin zone 0	42,43,44	Zinc oxide haze; Mixed cleavage and dimples on edge; areas of intergranular separation

Thumbnail origin zone 1	45	Brittle cleavage
Thumbnail origin zone 2	46	Brittle cleavage
Thumbnail origin zone 3	47	Fatigue striations
Thumbnail origin zone 4	48	Brittle cleavage
Thumbnail origin zone 5	49	Fatigue striations
Below thumbnail	50	Brittle cleavage
Between thumbnail and ID of pipe	51	Brittle cleavage
Between thumbnail and weld zone	52	Brittle cleavage
Fatigue at weld zone	53, 54	Fatigue striations
Between weld zone fatigue and final overload	55	Brittle cleavage
Final Overload	56	Brittle cleavage
Fatigue zone opposite weld metal	57	Fatigue striations
Area adjacent to fatigue zone	58	Brittle cleavage

opposite weld metal		
Fracture origin	59 (EDXA)	Zinc oxide washed onto fracture origin thumbnail

The SEM images confirm the fracture evidence shown in the Table 1 descriptions. The zone 0-zone 5 images show that the initial origin produced brittle cleavage in two separate events from three small origins on the external surface of the intrados of the pipe bend. These are followed by a thin zone of fine fatigue striations (zone 3). Once a critical depth was reached, a third brittle cleavage event took place over a small distance of about 0.8 mm (Zone 4). This was followed by a thin zone of fatigue over a further depth of 0.8mm (zone 5). A relatively large brittle cleavage step then took place through the pipe wall and around the pipe circumference until the brittle fracture was arrested by the tougher altered microstructure in the weld metal and heat affected zone. The crack arrested on the opposite side of the pipe as well since the overall tearing action was arrested when the weld metal was encountered. Fatigue cracks grew from the tougher weld zone. Once the fatigue crack at the weld metal (and the fatigue crack opposite the weld metal fatigue zone) reached a critical size, the remaining pipe cross section failed completely through by brittle cleavage caused by tensile bending stresses.

The white haze found on the thumbnail before cleaning was checked using EDXA and found to be zinc oxide (Figure 59). The zinc oxide likely washed onto the upper fracture surface during wet weather.

#### 4.4 STEEL PHYSICAL PROPERTIES



#### 4.4.1 CHEMICAL ANALYSIS

Chemical analysis using optical emission spectroscopy (OES) was used to determine the chemical content of the failed arm steel. The results are shown in Appendix B. The steel meets the chemical requirements of ASTM A500 grade B.

#### 4.4.2 TENSILE TESTS

The manufacturer's drawings show that the arm is specified to be made from steel pipe meeting the requirements of ASTM A500 Grade B. This specification contains a warning in the Scope, Note 1, *"Products manufactured to this specification may not be suitable for those applications such as dynamically loaded elements in welded structures, etc., where low temperature notch toughness properties may be important"*. In this case, the arm is both dynamically loaded and requires good low temperature notch toughness.

The arm steel tensile results are shown in Appendix B. The arm steel meets the requirements of ASTM A500 grade B in terms of ultimate strength, yield strength, and elongation.

#### 4.4.3 CHARPY IMPACT TESTING

ASTM A500 grade B steel does not have any specified toughness properties. Charpy Impact tests were performed on samples taken from the fractured arm and from samples removed at the same locations on an exemplar un-cracked arm. The results of impact testing are shown in Appendix B. All Charpy samples are 2/3 size due to pipe wall thickness limitations.

#### **4.4.3.1 Charpy Impact Testing of Failed Arm Serial Number 026400**

Impact samples taken from the intrados of the bend near the fracture surface (see figure B-1) revealed low Charpy values at room temperature along the center-line of the bend, and higher values on the right and left sides of the bend nearer the neutral bending axis (11 o'clock and 1 o'clock positions) (Appendix C). One low value was obtained along the 1 o'clock position (7 joules).

#### **4.4.3.2 Charpy Impact Testing of Exemplar Arm Serial Number 02600**

Samples taken from the intrados of the exemplar arm did not display the same low toughness at room temperature as did the failed unit. One sample, taken from the 1 o'clock side of the bend axis, displayed a relatively low Charpy value of 19 joules. All other Charpy values were in the 52 Joule to 112 joule range.

#### **4.4.3.3 Further Charpy Testing of Chair Arm No. 21 (No serial number ) Intrados, Chair Arm N0.21 Straight Section , and Failed Arm Straight Section**

Chair arm No.21 contained impact damage on the arm upper pin reinforcement bracket similar to that found on the failed arm. Charpy tests were performed on the intrados and straight section of this sample to determine the Charpy transition temperature of the steel in the most heavily cold worked area. As a comparison , a Charpy transition temperature was determined from the straight section of the failed arm, and a straight section of the chair arm No 21.

#### 4.4.5 METALLOGRAPHY

Metallographic samples were taken through the fracture origin and correlated to the features found across the fracture surface.

An overall view of the pipe microstructure away from the fracture is shown in Figure 60. The microstructure consists of fine grained pearlite and ferrite. The longitudinal plate rolling direction is indicated by the elongated grain structure visible in the micrograph.

The fracture origin area through the thumbnail is shown at low magnification in Figure 61. Cold work is visible in the direction of the pipe forming operation (transverse). The distances shown on the micrograph match the distances shown in Figure 15 on the thumbnail fracture surface.

No metallurgical anomalies were found with the fractured steel pipe microstructure.

### 5.0 DISCUSSION OF FINDINGS

The fracture evidence shows a thumb nail shaped fracture origin at approximately the 7:00 o'clock position (looking toward the fractured end of the arm and from the center of the bend intrados). The thumbnail is older than the rest of the fracture surface as indicated by the amount of corrosion product present. The larger thumbnail was created in five distinct steps, but originated from three small origin areas on the intrados surface of the pipe. The initial step (including the 3 origin spots) on the pipe outer surface has a depth of approximately 1 mm and is comprised of brittle cleavage. The second step is also a brittle cleavage mechanism, and has a total maximum depth of 2.8 mm. The brittle crack arrested and stayed dormant for an unknown period.

The crack then restarts in a fatigue mode and travels to a depth of 0.4mm before brittle cleavage again occurs and arrests after growing another 0.6 mm of depth. The last crack zone grew by fatigue over a depth of 0.5 mm before a brittle cleavage fracture took place over a larger portion of the remaining pipe wall cross section in opposite directions from the thumbnail.

This larger brittle fracture arrested when it reached the heat affected zone of the pipe weld seam. The crack then begins to grow by fatigue in the tougher HAZ and weld metal in the weld zone. The crack also arrests on the opposite side of the pipe fracture plane where cold work from the pipe bending operation is less severe. Fatigue cracking also restarted at the location opposite the weld metal and travelled for a distance of approximately 5 – 6 mm .

Final fracture occurred when the mid-diameter fatigue cracks reached a critical size and brittle cleavage fracture occurred over the remaining cross section. The low fracture toughness inherent to the cold bent arm determined the critical depth and length at which final fracture occurred. In general terms, there is a geometric relationship between the fracture toughness number and the critical crack size. The lower the fracture toughness, the lower the tolerable crack depth in accordance with the following equation:

$$K = Y\sigma\sqrt{\pi a} \quad \text{(Paris Equation)<sup>1</sup>}$$

Where : K = stress intensity factor or fracture toughness number

Y = Geometrical Factor

$\sigma$  = applied stress

<sup>1</sup> Paris and Sih, ASTM STP 381, 1965



$a$  = crack depth

Toughness is basically a measure of the resistance to crack growth once a crack has originally formed and is a material property, like tensile strength. If fracture toughness is low, fatigue cracks will grow more quickly and the final critical crack depth for a given applied stress will be smaller.

An important question is the sequence of events that took place on the gondola lift over a period of 25 years without the transverse crack being discovered by regular nondestructive testing. The evidence shows that molten zinc did not penetrate the crack, indicating that the crack was not present when galvanizing took place. The following theory is postulated and is supported by the evidence:

1. Cold bending of the pipe created high residual tensile stresses (from spring back) at the intrados of the bend. This can sometimes cause immediate "spring back" cracking a few grains deep, but will leave high residual tensile stresses if cracking does not occur. No cracking occurred since the pipe was initially in a relatively tough, ductile condition at the manufacturing temperature.
2. Galvanizing caused "strain-age embrittlement<sup>2</sup>" of the pipe in the intrados of the bend. Some strain aging might also have been experienced from the original cold bending of the plate into pipe. The bend area would have more severe cold work and would therefore have a more pronounced strain aging effect. Strain aging has the effect of raising the ductile-brittle transition temperature of the steel. Where the steel might have had an original glass transition temperature of -10 °C, strain aging could create an upward glass transition temperature shift to +10° C. The exact amount of strain aging effect is unpredictable in a given steel. A number of factors, including the steel chemistry, the temperature of the galvanizing bath, the degree of cold work, and the time in the bath can all be contributors to

---

<sup>2</sup> ASTM A143 - Standard Practice for Safeguarding Against Embrittlement of Hot-Dip Galvanized Structural Steel Products and Procedure for Detecting Embrittlement



strain aging. The heating cycle of the cold worked steel is the most significant factor. The heating cycle can be provided by the galvanizing bath, by welding (heating adjacent to the weld), by preheat, or any other heating method applied to the steel.

3. The uncracked highly stressed surface of the steel suffered a small cleavage crack beneath the galvanized layer due to the high residual tensile stresses and a reduction in toughness caused by strain aging.

This initial crack would have “popped in” below the galvanized surface when the residual stress level and glass transition temperature reached critical values. The initial crack was approximately 1 mm deep and arrested when the residual stress from forming (spring back) was relieved by the cracking. The galvanized layer was not broken at this time. A deeper initial crack through the galvanizing layer would be expected from impacts or operating loads.

4. The 2<sup>nd</sup> zone of brittle fracture likely occurred during first impact loading of the gondola arm due to contact with lateral rail hardware (evidence of impact damage on arm bracket). The crack arrested when a lack of sustained loads removed the driving force for the low energy brittle crack to proceed.
5. Fatigue cracking started at the edge of the brittle origin crack and progressed for approximately 0.4mm in depth due to applied dynamic loads. This may have occurred over several seasons under specific weather and loading conditions.
6. A 3rd zone of brittle fracture occurred due to sudden short duration high strain rate loading. This may have been something like another impact load as indicated by the dent on the guide bracket.
7. The final zone in the thumbnail was again fatigue caused by applied dynamic loads



8. The multistep thumbnail grew over an unknown period of time. It is difficult to explain why the crack was not discovered by professional inspectors over the 25 year operating life of the gondola. The galvanized layer may have survived the initial cracking at the "pop in" period, but would have been visible once the fatigue crack began to grow.
9. The visible zinc oxide that washed onto the fracture surface shows that the crack was open to the atmosphere for an unknown period of time

The larger brittle fracture that took place between the thumbnail origin and the tougher weld metal occurred when the thumbnail reached a critical size by fatigue. Fatigue cracking occurred over a length of 5 - 6 mm through the entire cross section of the pipe and would have been visible through both visual (VT) and magnetic particle (MT) inspection methods. The final pipe overload occurred when the total circumferential crack length (initial brittle fracture plus fatigue cracking) reached a length of 15 cm.

A Charpy specimen study of straight pieces of pipe and cold bent pieces of pipe show that strain age embrittlement occurred as a result of the cold bending of the pipe during fabrication. Strain age embrittlement occurred as a result of cold work plus the heating cycle introduced during galvanizing. The ductile-brittle transition temperature of the raw galvanized pipe away from the bends was determined to be between 0 and -10 ° C. The bend area on the failed unit displayed a ductile-brittle transition of +20 degrees (or higher).

## 6.0 CONCLUSIONS

The gondola arm fractured due to sudden brittle fracture preceded by fatigue cracking at 3 distinct areas in the pipe cross section. The following causes contributed to the arm fracture:

1. The steel arm was not overloaded by in-service stresses.
2. The arm was cold bent ASTM A500 B pipe. This material may not have been suitable for dynamic loading conditions requiring low temperature fracture toughness as stated in the

ASTM A500 specification. Even if strain aging did not occur in the cold bent areas, the toughness of the original steel pipe was inadequate for dynamic loading conditions at normal winter operating temperatures (-5 ° C to -15 °C).

3. The toughness properties of the steel pipe varied from hanger to hanger, and at different positions along the hanger shape. The lowest Charpy values were found along the intrados of the bends where cold work was most severe.
4. The arm was cold bent into shape which further reduced the original toughness of the material through a phenomenon known as strain-age embrittlement. Strain-age embrittlement occurs due to cold work in combination with the heating cycle associated with galvanizing.
5. A multi-step fracture sequence occurred which included 4 zones of fatigue cracking followed by a final overload consisting zone of brittle cleavage. Small brittle cleavage steps were likely caused by guide rail impacts which caused impact damage to upper arm brackets.
6. The fracture origin was a multi-mode thumbnail shaped precrack that contained both fatigue cracking and brittle cleavage growth mechanism. The critical defect depth which lead to sudden brittle fracture was approximately 5 mm.
7. Brittle fracture was arrested for a period of time at the tougher material associated with the pipe seam weld. Fatigue cracks grew through the tougher weld zone and final brittle overload occurred with a through-wall circumferential crack length of 26 cm .

## 7.0 ADDITIONAL CONSIDERATIONS

Structural components destined for use in cold weather should be made from steels with known fracture toughness properties. This will ensure adequate low temperature toughness and prevent sudden brittle fracture of structural components in the presence of small fatigue cracks.

Steel components that are formed by bending and then galvanized should be hot bent or stress relieved after bending to prevent strain age embrittlement. The fabrication rules stated in ASTM A143 should be followed at all times.


**TECHNICAL SAFETY BC**

Leitner-Poma Gondola Arm Failure Kicking Horse Ski Area

Page 23 of 77

Please contact the undersigned with any questions.

**ACUREN GROUP INC.**



Bob Milne, P.Eng.

Client acknowledges receipt and accepts custody of the report, work or other deliverable (the "Deliverable"). Client agrees that it is responsible for assuring that any standards or criteria identified in the Deliverable and Statement of Work ("SOW") are clear and understood. Client acknowledges that Acuren is providing the Deliverable according to the SOW and not other standards. Client acknowledges that it is responsible for the failure of any items inspected to meet standards, and for remediation. Client has 15 business days following the date Acuren provides the Deliverable to inspect, identify deficiencies in writing, and provide written rejection, or else the Deliverable is deemed accepted. The Deliverable and services are governed by the Master Services Agreement ("MSA") and SOW (Including Job Sheet). If the parties have not entered into an MSA, then the Deliverable and services are governed by the Statement of Work and the "Acuren Standard Service Terms" ([www.acuren.com/serviceterms](http://www.acuren.com/serviceterms)) in effect when the services were ordered.



## APPENDIX A

FIGURES 1 - 61



**Figure 1** Overall view of gondola attachment arm failure as shown in Global news photo. Fracture occurred at the top of the bend outside of the “H frame” attachment point (arrow).



ACUREN



**Figure 2** Overall view of straight section of hanger arm containing fracture as received at the Acuren Facility.




ACUREN



**Figure 3** Overall view of the opposite side of the fracture (short 60° bend section) as it exists the gondola cover.



**Figure 4** Serial number on fractured hanger arm.



**Figure 5** Scratch on intrados of the bend aligning with center of thumbnail.



**Figure 6** Deformation on upper reinforcing bracket cause by impact with lateral rail at drive station.



ACUREN




**Figure 7** Shiny area on hanger arm galvanized surface indicating light contact during normal operation.



ACUREN



**Figure 8**      Thumbnail shaped fracture origin at roughly the 7 o'clock position from the intrados of the bend (intrados centerline at 6 0'clock position)



**Figure 9** Close-up view of thumbnail area showing brittle fracture lines leading back to the thumbnail origin. The red mark is at the centerline of the intrados of the bend. The grey line is a scratch coming from the middle of the thumbnail (unknown origin).



**Figure 10** Crack arrest at the pipe seam weld. Fatigue crack grew until reaching a critical size and brittle cleavage proceeded. Microstructure change at weld arrested brittle fracture



**Figure 11** Fatigue crack initiation and growth on opposite side of thumbnail at the same relative location as the pipe weld fatigue crack. .




**Figure 12** Close-up view of scratch in galvanizing shown at low magnification in Figure 5.



**Figure 13** Shiny galvanizing from contact with unknown hardware during normal operations.




**Figure 14** Close-up view of deformation in upper reinforcing bracket.



**Figure 15** Close-up view of thumbnail origin showing multiple steps before final overload occurred. Progressive zones are arbitrarily labelled 1 – 5 for reference.



ACUREN




**Figure 16** Keyence microscope view of fracture at the 6:00 position (black vertical mark) on the external surface of the intrados of the bend. Zones are arbitrarily labelled 1 – 5.



ACUREN



**Figure 17** Reference 1 at roughly the 7:00 position.



**Figure 18** Reference 2 moving toward the seam weld (100% brittle)




**Figure 19** Reference 3 moving toward the seam weld (100% brittle)



**Figure 20** Reference 4 brittle fracture arrested at seam weld HAZ.




**Figure 21** Reference 5 brittle fracture on either side of fatigue cracking through seam weld HAZ



**Figure 22** Reference 6 brittle fracture starting at tip of HAZ fatigue zone.



**Figure 23** Reference 7 brittle fracture in overload zone.




**Figure 24** Reference 8 brittle fracture in overload zone




**Figure 25** Reference 9 brittle fracture in overload zone




**Figure 26** Reference 10 brittle fracture in overload zone




**Figure 27** Reference 11 brittle fracture in overload zone.



**Figure 28** Reference 12 brittle fracture in overload zone.




**Figure 29** Reference 13 brittle fracture in overload zone.



**Figure 30** Reference 14 brittle fracture in overload zone.




**Figure 31** Reference 15 brittle fracture in overload zone. Note dross on inside of pipe



**Figure 32** Reference 16 brittle fracture in overload zone.



**Figure 33** Reference 17 brittle fracture in overload zone.



**Figure 34** Reference 18 brittle fracture in overload zone.



**Figure 35** Reference 19 brittle fracture in overload zone.




ACUREN




**Figure 36** Reference 20 brittle fracture arrested . Beginning of fatigue crack at toe of brittle fracture zone. Position of fatigue zone roughly corresponds to position of HAZ fatigue zone on opposite side of thumbnail.



**Figure 37** Reference 21 end of fatigue and start of brittle fracture heading away from thumbnail.



**Figure 38** Reference 22 brittle fracture heading toward fatigue zone.




**Figure 39** Reference 23 brittle fracture heading toward fatigue zone.



**Figure 40**      Brittle fracture near large thumbnail containing small thumbnail.




**Figure 41**      Back to intrados at 6:00 position.



**Figure 42** SEM view of uncleaned thumbnail. White haze is zinc oxide washed onto surface after initial cracking took place.




**Figure 43**      Thumbnail after cleaning with detergent in ultrasonic bath . Zones are labelled 1 – 5




**Figure 44** Features in origin area right at the surface. Features are a mixture of ductile and brittle cleavage.




ACUREN




**Figure 45** Features in Zone 1 containing 100% brittle cleavage.




**Figure 46** Features in Zone 2 containing 100% brittle cleavage.



**Figure 47** Features in Zone 3 containing fine fatigue striations. Striation spacing is approximately 0.3 microns




**Figure 48** Features in Zone 4 containing 100% brittle cleavage.




**Figure 49** Features in Zone 5 containing fatigue striations. Striation spacing is approximately 0.3 microns.




ACUREN




**Figure 50** 100% brittle cleavage below thumbnail.




**Figure 51** 100% brittle cleavage between thumbnail and ID of pipe




**Figure 52** 100% brittle cleavage between thumbnail and weld zone.




**Figure 53** Fatigue zone starting at brittle fracture arrest in weld metal HAZ




**Figure 54** Fine fatigue striations in weld metal fatigue zone




**Figure 55** 100% brittle cleavage in overload zone



**Figure 56** 100% brittle cleavage in last area to separate.




**Figure 57** Fine fatigue striations in fatigue zone on opposite side. Striation spacing is 0.2 - 0.3 microns




**Figure 58** 100% brittle fracture toward thumbnail



ACUREN



**Figure 59** EDXA of haze showing decreasing zinc content toward the bottom of the thumbnail



**Figure 59b**



ACUREN




Figure 59c




Figure 59d



ACUREN




Figure 59e




Figure 59f



ACUREN




Figure 59g




Figure 59h



ACUREN




Figure 59i




Figure 59j



ACUREN




Figure 59k





Figure 59l



ACUREN



**Figure 60** Hanger microstructure through fracture. Steel is relatively low carbon ferrite – pearlite microstructure.



ACUREN




Figure 61

Locations of zones 1 – 5 through large thumbnail. Distances correspond to Figure 15 fracture surface measurements



## APPENDIX B

### LABORATORY REPORTS



Acuren Group Inc.

12271 Horseshoe Way  
Richmond, BC, Canada V7A 4V4  
www.acuren.com

Phone: 604.275.3800  
Fax: 604.274.7235

A Higher Level of Reliability



## CHEMICAL ANALYSIS REPORT

Technical Safety B.C.

DATE: March 19, 2025

OUR FILE NO: 605-J215610

PO NO: -

REPORT NO: 07

PAGE: 1 of 1

ATTENTION: RYAN HAZLETT

DESCRIPTION: Steel Pipe - Gondola Hanger

TEST METHOD: ASTM E415-21 (Optical Emission Spectroscopy – Spectro MAXx LMM04 – S/N08003788)

### TEST RESULTS

ELEMENT	CHEMICAL COMPOSITION (wt %)	
	Hanger Pipe s/n 0026400	ASTM A500 B
Carbon	0.057	0.26 max
Manganese	1.06	1.35 max
Phosphorus	0.010	0.035 max
Sulphur	0.010	0.035 max
Silicon	0.035	--
Copper	0.132	--
Nickel	0.050	--
Chromium	0.058	--
Molybdenum	0.015	--
Vanadium	0.056	--
Niobium	0.003	--
Grain Refining Elements (V+Nb)	0.005	--
Boron	0.0004	--
Carbon Equivalent**	0.25	--
Iron	Balance	Balance

\* Hanger pipe meets the chemical requirements of ASTM A500 grade B

\*\*Carbon Equivalence as per CSA W59-23 Clause 3.2.1:  $CE = C + \frac{Mn}{6} + \frac{(Cr+Mo+V)}{5} + \frac{(Ni+Cu)}{15}$

Reported by: \_\_\_\_\_

Reviewed by: \_\_\_\_\_

Bob Milne P.Eng.

Client acknowledges receipt and custody of the report or other work ("Deliverable"). Client agrees that it is responsible for assuring that acceptance standards, specifications and criteria in the Deliverable and Statement of Work ("SOW") are correct. Client acknowledges that Acuren is providing the Deliverable according to the SOW, and not any other standards. Client acknowledges that it is responsible for the failure of any items inspected to meet standards, and for remediation. Client has 15 business days following the date Acuren provides the Deliverable to inspect it, identify deficiencies in writing, and provide written rejection, or else the Deliverable will be deemed accepted. The Deliverable and other services provided by Acuren are governed by a Master Services Agreement ("MSA"). If the parties have not entered into an MSA, then the Deliverable and services are governed by the SOW and the "Acuren Standard Service Terms" ([www.acuren.com/serviceterms](http://www.acuren.com/serviceterms)) in effect when the services were ordered.

The Client Representative who receives this report is responsible for verifying that any acceptance standards listed in the report are correct, and promptly notifying Acuren of any issues with this report and/or the work summarized herein. The owner is responsible for notifying Acuren in writing if they would like their samples returned or placed into storage (at their cost) otherwise, all samples/specimens associated with this report will be disposed of 60 days after the report date.

NOTES:

- This report shall not be reproduced except in full without the prior written approval of Acuren Group Inc.
- Results in this report relate only to the item(s) tested as provided by the client unless otherwise indicated.



## Acuren Group Inc.

12271 Horseshoe Way  
Richmond, BC, Canada V7A 4V4  
[www.acuren.com](http://www.acuren.com)

Phone: 604.275.3800  
Fax: 604.274.7235



## A Higher Level of Reliability

# TENSILE TEST REPORT

Technical Safety BC

DATE: March 19, 2025

ATTENTION: RYAN HAZLETT

OUR FILE NO: 605-1215610

PO No. -

REPORT No: 08

PAGE: 1 of 1

DESCRIPTION: Longitudinal tensile test of Failed Gondola Hanger Pipe

TEST SPECIFICATION: ASTM A370

MATERIAL SPECIFICATION: ASTM A500 grade B

SPECIMEN IDENTIFICATION	YIELD STRENGTH 0.2% OFFSET (ksi)	TENSILE STRENGTH (ksi)	% ELONGATION (IN 2")	% REDUCTION IN AREA	FAILURE LOCATION
Gondola Hanger s/n 0026400	73.9	82.2	22.75	N/A	Center gauge
Specification Requirements	46	58	23	N/A	

- Technical Safety BC Certificate of Recognition Registration No. CR-5
- Test machine calibrated to ASTM E4 and CSA A23.2-9C specifications.
- Specimens will be disposed of after 30 days unless alternate provisions are made.

Reported by:

Reviewed by:

Bob Milne P.Eng.

Client acknowledges receipt and custody of the report or other work ("Deliverable"). Client agrees that it is responsible for assuring that acceptance standards, specifications and criteria in the Deliverable and Statement of Work ("SOW") are correct. Client acknowledges that Acuren is providing the Deliverable according to the SOW, and not any other standards. Client acknowledges that it is responsible for the failure of any items inspected to meet standards, and for remediation. Client has 15 business days following the date Acuren provides the Deliverable to inspect it, identify deficiencies in writing, and provide written rejection, or else the Deliverable will be deemed accepted. The Deliverable and other services provided by Acuren are governed by a Master Services Agreement ("MSA"). If the parties have not entered into an MSA, then the Deliverable and services are governed by the SOW and the "Acuren Standard Service Terms" ([www.acuren.com/serviceterms](http://www.acuren.com/serviceterms)) in effect when the services were ordered.

The Client Representative who receives this report is responsible for verifying that any acceptance standards listed in the report are correct, and promptly notifying Acuren of any issues with this report and/or the work summarized herein. The owner is responsible for notifying Acuren in writing if they would like their samples returned or placed into storage (at their cost) otherwise, all samples/specimens associated with this report will be disposed of 60 days after the report date.

with th

a) This report shall not be reproduced except in full without the prior written approval of Acuren Group Inc.  
b) Results in this report relate only to the item(s) tested as provided by the client unless otherwise indicated.



## APPENDIX C

### CHARPY IMPACT TESTING

**Acuren Group Inc.**12271 Horseshoe Way  
Richmond, BC, Canada V7A 4V4  
www.acuren.comPhone: 604.275.3800  
Fax: 604.274.7235**A Higher Level of Reliability**

## CHARPY IMPACT TEST REPORT

Technical Safety BC  
2889 E 12th Ave suite 600,  
Vancouver, BC  
V5M 4T5

DATE: May 5, 2025

OUR FILE NO: 605-J215610

PO NO:

REPORT NO: 1

ATTENTION: RYAN HAZLETT

PAGE: 1 of 2

DESCRIPTION: Charpy Samples Fractured Arm (Position See Figure 1)

SPECIMEN TYPE: Standard V Notch

TEST SPECIFICATION: ASTM A370

SPECIMEN SIZE: 10 mm x 6.7 mm

MATERIAL SPECIFICATION: ASTM A500 grade B

SPECIMEN IDENTIFICATION	TEST TEMPERATURE (° C)	IMPACT ENERGY (J)	SHEAR FRACTURE (% ESTIMATE)
Intrados centre line (1) (12 o'clock)	20	10	5
Intrados centre line (2)	20	11	5
Intrados centre line (3)	20	7	2
1 o'clock (4)	30	6	2
1 o'clock (5)	30	143	100
1 o'clock (6)	30	150	100
11 o'clock (7)	30	155	100
11 o'clock (8)	20	129	95
11 o'clock (9)	20	7	2
Average			
Specification Requirements			

- Technical Safety BC Certificate of Recognition Registration No. CR-5
- Instrument calibrated annually to N.I.S.T. and ASTM E23.
- Specimens will be disposed of after 30 days unless alternate provisions are made.

Reported by:

Reviewed by:

Bob Milne P.Eng.

Client acknowledges receipt and custody of the report or other work ("Deliverable"). Client agrees that it is responsible for assuring that acceptance standards, specifications and criteria in the Deliverable and Statement of Work ("SOW") are correct. Client acknowledges that Acuren is providing the Deliverable according to the SOW, and not any other standards. Client acknowledges that it is responsible for the failure of any items inspected to meet standards, and for remediation. Client has 15 business days following the date Acuren provides the Deliverable to inspect it, identify deficiencies in writing, and provide written rejection, or else the Deliverable will be deemed accepted. The Deliverable and other services provided by Acuren are governed by a Master Services Agreement ("MSA"). If the parties have not entered into an MSA, then the Deliverable and services are governed by the SOW and the "Acuren Standard Service Terms" [www.acuren.com/serviceterms](http://www.acuren.com/serviceterms) in effect when the services were ordered.


The Client Representative who receives this report is responsible for verifying that any acceptance standards listed in the report are correct, and promptly notifying Acuren of any issues with this report and/or the work summarized herein. The owner is responsible for notifying Acuren in writing if they would like their samples returned or placed into storage (at their cost) otherwise, all samples/specimens associated with this report will be disposed of 60 days after the report date.

NOTES:

- a) This report shall not be reproduced except in full without the prior written approval of Acuren Group Inc.
- b) Results in this report relate only to the item(s) tested as provided by the client unless otherwise indicated.



ACUREN



**Figure 1** Charpy Sample Positions

**Acuren Group Inc.**

12271 Horseshoe Way  
Richmond, BC, Canada V7A 4V4  
www.acuren.com

Phone: 604.275.3800  
Fax: 604.274.7235

**A Higher Level of Reliability**

## CHARPY IMPACT TEST REPORT

Technical Safety BC  
2889 E 12th Ave suite 600,  
Vancouver, BC  
V5M 4T5

DATE: May 5, 2025

OUR FILE NO: 605-J215610

PO NO:

REPORT NO: 2

ATTENTION: RYAN HAZLETT P.ENG.

PAGE: 1 of 2

DESCRIPTION: Charpy Samples Intact Arm (Position See Figure 1)

SPECIMEN TYPE: Standard V Notch

TEST SPECIFICATION: ASTM A370

SPECIMEN SIZE: 10 mm x 6.7 mm

MATERIAL SPECIFICATION: ASTM A500 grade B

SPECIMEN IDENTIFICATION	TEST TEMPERATURE (° C)	IMPACT ENERGY (J)	SHEAR FRACTURE (% ESTIMATE)
Intrados centre line (1) (12 o'clock)	20	97	65
Intrados centre line (2)	20	52	35
Intrados centre line (3)	20	106	75
1 o'clock (4)	20	93	65
1 o'clock (5)	20	19	15
1 o'clock (6)	20	112	100
11 o'clock (7)	20	90	50
11 o'clock (8)	20	53	35
11 o'clock (9)	20	105	65
Average			
Specification Requirements			

- Technical Safety BC Certificate of Recognition Registration No. CR-5
- Instrument calibrated annually to N.I.S.T. and ASTM E23.
- Specimens will be disposed of after 30 days unless alternate provisions are made.

Reported by:



Reviewed by:



Bob Milne P.Eng.

Client acknowledges receipt and custody of the report or other work ("Deliverable"). Client agrees that it is responsible for assuring that acceptance standards, specifications and criteria in the Deliverable and Statement of Work ("SOW") are correct. Client acknowledges that Acuren is providing the Deliverable according to the SOW, and not any other standards. Client acknowledges that it is responsible for the failure of any items inspected to meet standards, and for remediation. Client has 15 business days following the date Acuren provides the Deliverable to inspect it, identify deficiencies in writing, and provide written rejection, or else the Deliverable will be deemed accepted. The Deliverable and other services provided by Acuren are governed by a Master Services Agreement ("MSA"). If the parties have not entered into an MSA, then the Deliverable and services are governed by the SOW and the "Acuren Standard Service Terms" ([www.acuren.com/serviceterms](http://www.acuren.com/serviceterms)) in effect when the services were ordered.


The Client Representative who receives this report is responsible for verifying that any acceptance standards listed in the report are correct, and promptly notifying Acuren of any issues with this report and/or the work summarized herein. The owner is responsible for notifying Acuren in writing if they would like their samples returned or placed into storage (at their cost) otherwise, all samples/specimens associated with this report will be disposed of 60 days after the report date.

## NOTES:

- a) This report shall not be reproduced except in full without the prior written approval of Acuren Group Inc.
- b) Results in this report relate only to the item(s) tested as provided by the client unless otherwise indicated.



ACUREN





## APPENDIX D

NDT REPORTS FROM SITE



## NONDESTRUCTIVE EXAMINATION

CLIENT: Technical Safety BC

### Acuren Group Inc.

12271 Horseshoe Way  
Richmond, BC, Canada V7A 4V4  
www.acuren.com

Phone: 604.275.3800  
Fax: 604.274.7235

A Higher Level of Reliability



PAGE: 1 of 4

DATE: April 10, 2025

ACUREN JOB #: 605-J215610

REPORT #: 01

CONTRACT/PO: -

WO: -

WORK LOCATION: Kicking Horse Resort, Golden, BC

ATTENTION: DEAN SCHMITKE

PROJECT: Gondola Arms

ITEM(S) EXAMINED: Gondola Arms

PART #: - MATERIAL: Carbon steel THICKNESS: 9 mm to 11 mm

SCOPE: Perform shear wave ultrasonic examinations on the suspect areas of the gondola arms to locate any relevant OD-connected reflectors or OD subsurface reflectors beneath the galvanized coating.

TYPES OF INSPECTION: Magnetic Particle; Ultrasonic

### RESULTS:

As requested by the client, shear wave ultrasonic examinations were conducted on the suspect areas of the gondola arms to identify any relevant OD-connected reflectors or OD subsurface reflectors beneath the galvanized coating.

Calibration was referenced using the OD notch on the calibration block, and scanning was performed with a total gain of +9 dB (+3 dB transfer value and +6 dB scanning gain). A 2" x 4" area, centered 28" from the bottom end—corresponding to the location of a previously reported fracture—was scanned in the vertical direction.

A total of 24 gondola arms were examined, including Gondolas #23 through #41, #47, #54, #2, #12, and #20.

- No relevant or reportable reflectors were identified in any of the inspected gondola arms, with the exception of #25.
- Gondola arm #25 exhibited two minor reflectors during ultrasonic examination. Subsequent dry and wet magnetic particle examinations revealed no surface-breaking indications. Scratches on the galvanized coating were observed in the area and were smoothed using a file. The area was then re-examined using ultrasonic testing, with no further reflectors detected.

Client acknowledges receipt and custody of the report or other work ("Deliverable"). Client agrees that it is responsible for assuring that acceptance standards, specifications and criteria in the Deliverable and Statement of Work ("SOW") are correct. Client acknowledges that Acuren is providing the Deliverable according to the SOW, and not any other standards. Client acknowledges that it is responsible for the failure of any items inspected to meet standards, and for remediation. Client has 15 business days following the date Acuren provides the Deliverable to inspect it, identify deficiencies in writing, and provide written rejection, or else the Deliverable will be deemed accepted. The Deliverable and other services provided by Acuren are governed by a Master Services Agreement ("MSA"). If the parties have not entered into an MSA, then the Deliverable and services are governed by the SOW and the "Acuren Standard Service Terms" ([www.acuren.com/serviceterms](http://www.acuren.com/serviceterms)) in effect when the services were ordered.

CLIENT: _____	CLIENT PRINTED NAME: _____	CLIENT SIGNATURE ACCEPTED & ACKNOWLEDGED BY _____	TOTAL HOURS	S.T.	O.T.	SHIFT Day <input type="checkbox"/>
ACUREN TECHNICIAN: _____	_____	2 <sup>nd</sup> Technician _____	1 <sup>ST</sup> TECHNICIAN: See DTR			PM <input type="checkbox"/>
REVIEWER: Bob Milne, P.Eng.	_____	<i>R.M.</i>	2 <sup>ND</sup> TECHNICIAN: KILOMETRES: _____	OTHER CHARGES: YES <input type="checkbox"/>	NO <input type="checkbox"/>	(IF YES, SEE DAILY OR PROJECT TIME REPORT)
(Generated Using: CAN-QUA-02F007 R10 - 12/09/2021)						

*Photo 1:*

General view of Gondolas and Gondola Arms.



*Photo 2:*

Typical view of the suspect area where ultrasonic examinations were performed.



*Photo 3:*

Typical view of the suspect area where ultrasonic examinations were performed.





ACUREN JOB # 605-J215610

REPORT # 01

TECHNICAL SAFETY BC  
Gondola Arms

Page 4 of 4

**TEST DETAILS: MAGNETIC PARTICLE**

ACCEPTANCE STANDARD: Client's Information REVISION: N/A

PROCEDURE/TECHNIQUE: CAN-MT-14P001 REVISION: 19

TYPE: Wet Visible	METHOD: Yoke
PARTICLE BRAND: Magnaflux	PRODUCT No.: 7HF
PARTICLE COLOUR: Black	CURRENT: AC
SUSPENSION: Oil	MT INSTRUMENT: Parker B-300
CONTRAST PAINT: Magnaflux	PRODUCT No.: 8901W
MAG TIME (SECONDS): 5	DEMAG REQUIRED?: No
TECHNIQUE DEMONSTRATED OVER A PAINTED SURFACE?: N/A	LIFT CHECK BEFORE USE: Yes
	LIFT WEIGHT S/N: P16-090
	LIGHTING EQUIPMENT: Flashlight
	BLACKLIGHT MAKE: N/A
	S/N: N/A
	LIGHT METER S/N: 11010287
	CAL DUE: Sept 27 2025
	LIGHT INTENSITY: > 100 fc (1076 lx)

BATCH NOS. (WHEN REQUIRED): PARTICLES: SUSPENSION: CONTRAST PAINT:

TEST SURFACE CONDITION: Clean Bare Metal TEST SURFACE TEMPERATURE: 0°C to 20°C

**TEST DETAILS: ULTRASONIC**

ACCEPTANCE STANDARD: Client's Information REVISION: N/A

PROCEDURE/TECHNIQUE: CAN-UT-14P002 REVISION: 10

TYPE: Flaw Detection	METHOD: Contact
INSTRUMENT: Olympus	MODEL: Epoch 650
CAL. BLOCK: IIW	S/N: 11-5068
CAL. BLOCK: ASME	S/N: IDEAL 6422

## Probe &amp; Technique Details:

TEST ANGLE (°)	PROBE TYPE	CRYSTAL SIZE	FREQ. (MHz)	SERIAL NUMBER	DAMPING Ω	TEST FROM	REFERENCE REFLECTOR	TRANSFER VALUE	REFERENCE		SCAN dB	RANGE
									dB	% FSH		
1	45	Single	6.35 mm	5	SC0684	50	OD	OD Notch	+3	37.3	80	+12
2	0	Dual	6.35 mm	5	871683	50	OD	Back wall	N/A	As req.	80	+6
3												
4												

TEST SURFACE CONDITION: Clean Bare Metal TEST SURFACE TEMPERATURE: 0°C to 20°C



## NONDESTRUCTIVE EXAMINATION

CLIENT: Technical Safety BC  
104 – 9525 201 Street,  
Langley, BC  
V1N 4A5

Acuren Group Inc.

12271 Horseshoe Way  
Richmond, BC, Canada V7A 4V4  
www.acuren.com

Phone: 604.275.3800  
Fax: 604.274.7235

A Higher Level of Reliability



PAGE: 1 of 15

DATE: March 14, 2025

ACUREN JOB #: 605-J215610

REPORT #: 02

CONTRACT/PO: N/A

WO: N/A

ATTENTION: **Dean Schmitke**

WORK LOCATION: Kicking Horse Mountain

PROJECT: Kicking Horse Mountain - Golden Eagle Express Gondola Inspection

ITEM(S) EXAMINED: Four (4) gondola lift spools

PART #: Various MATERIAL: Carbon steel THICKNESS: Not provided

SCOPE: Perform a VT and MT of gondola lift spools as directed by Technical Safety BC in accordance with manufacturers procedure and report findings.

TYPES OF INSPECTION: Magnetic Particle; Visual

### RESULTS:

Acuren was called by Technical Safety BC to perform a visual (VT) and magnetic particle (MT) examination as a third-party at Kicking Horse Mountain Resort in Golden, BC on March 12, 2025, and March 13, 2025. This request was in response to the Golden Eagle Express Gondola having an incident where one of its arms sustained a critical failure resulting in the gondola arm fracturing and its cabin falling from a height above the ground.

Four (4) gondola arms were pointed out and made accessible to perform a VT and MT as directed by Technical Safety BC. The first gondola (Serial # 026600) arm was inspected in the Kicking Horse Mountain's shop on March 12, 2025. The remaining three (Cabin 21-Arm serial NA, Cabin 22-Arm serial 024400, Cabin 23 Arm serial 026800) were inspected at the base of the gondola in position on March 13, 2025.

All four arms were inspected visually with MT being conducted at a minimum of the accessible areas at each of the two bends, 6" above, and 6" below each bend as referenced in the manufacturer's procedure as accessible.

See Table 1 below for results.

**TABLE 1: VT/MT EXAMINATION RESULTS – SUSPECT INDICATIONS**

INDICATION #	CABIN#/ARM SERIAL#	INDICATION / CLUSTER LOCATION	APPROXIMATE LENGTH	ACTION TAKEN	RESULTS
1	Cabin # NA Arm Serial # 026600	Inside section, approximately 10 inches above the lower bend	3"	Grinded/buffed out	VT/MT OK
2	Cabin # NA Arm Serial # 026600	Inside section, near top of arm	26" (total cluster)	Grinded/buffed out	VT/MT OK

Client acknowledges receipt and custody of the report or other work ("Deliverable"). Client agrees that it is responsible for assuring that acceptance standards, specifications and criteria in the Deliverable and Statement of Work ("SOW") are correct. Client acknowledges that Acuren is providing the Deliverable according to the SOW, and not any other standards. Client acknowledges that it is responsible for the failure of any items inspected to meet standards, and for remediation. Client has 15 business days following the date Acuren provides the Deliverable to inspect it, identify deficiencies in writing, and provide written rejection, or else the Deliverable will be deemed accepted. The Deliverable and other services provided by Acuren are governed by a Master Services Agreement ("MSA"). If the parties have not entered into an MSA, then the Deliverable and services are governed by the SOW and the "Acuren Standard Service Terms" ([www.acuren.com/serviceterms](http://www.acuren.com/serviceterms)) in effect when the services were ordered.

CLIENT: Dean Schmitke	CLIENT SIGNATURE ACCEPTED & ACKNOWLEDGED BY	DTR No.: N/A
ACUREN TECHNICIAN: [REDACTED]	2 <sup>nd</sup> Technician	
REVIEWER: Bob Milne, P.Eng.	(Generated Using: CAN-QUA-02F007 R10 - 12/09/2021)	



**TECHNICAL SAFETY BC**

Kicking Horse Mountain - Golden Eagle Express Gondola Inspection

Page 2 of 15

INDICATION #	CABIN#/ARM SERIAL#	INDICATION / CLUSTER LOCATION	APPROXIMATE LENGTH	ACTION TAKEN	RESULTS
3	Cabin # 21 Arm Serial # NA	Inside section, approximately 3" below start of bottom bend	2"	Grinded/buffed out	VT/MT OK
4	Cabin # 21 Arm Serial # NA	Inside section, approximately 4" below start of bottom bend	4"	Grinded/buffed out	VT/MT OK
5	Cabin # 21 Arm Serial # NA	Outside section, approximately 1" below start of bottom bend	2"	Grinded/buffed out	VT/MT OK
6	Cabin # 23 Arm Serial # 026800	Inside section, approximately 2" below start of bottom bend	4"	Grinded/buffed out	VT/MT OK
7	Cabin # 23 Arm Serial # 026800	Inside section, approximately 4" below start of bottom bend	2"	Grinded/buffed out	VT/MT OK

**Limitations:**

Three of the four arms were in position; thus, the top and bottom sections were still connected and not accessible for examination (see pictures below).

These three arms were exposed to elements (intermittent snow)

The fourth arm in the shop had the top section with gussets covered for transportation and for the purposes of this examination not required (see pictures below).

**TECHNICAL SAFETY BC**

Kicking Horse Mountain - Golden Eagle Express Gondola Inspection

Page 3 of 15

*Photo 1:*

Arm serial # 026600.

General overview.



*Photo 2:*

Arm serial # 026600.

Indication 1.

Faint linear indications approximately 10 inches above the lower bend area of interest. These indications were removed with gentle grinding of a flapper disc.



**TECHNICAL SAFETY BC**

Kicking Horse Mountain - Golden Eagle Express Gondola Inspection

Page 4 of 15

*Photo 3:*

Arm serial # 026600.

Indication 2.

Overview of approximately 26 inches of suspect indications near top of arm overview as seen with wet visible magnetic particle examination before grinding.

See photos 4 and 5.



*Photo 4:*

Arm serial # 026600.

Indication 2.

Close-up of approximately 26 inches of suspect indications near top of arm overview as seen with wet visible magnetic particle examination before grinding.



**TECHNICAL SAFETY BC**

Kicking Horse Mountain - Golden Eagle Express Gondola Inspection

Page 5 of 15

*Photo 5:*

Arm serial # 026600.

Indication 2.

Close-up of approximately 26 inches of suspect indications near top of arm overview as seen with wet visible magnetic particle examination before grinding.



*Photo 6:*

Arm serial # 026600.

Indication 2.

Overview of approximately 26 inches of suspect indications near top of arm **removed** after light buffing/grinding.

MT performed on suspect areas did not show any more indications.



**TECHNICAL SAFETY BC**

Kicking Horse Mountain - Golden Eagle Express Gondola Inspection

Page 6 of 15

*Photo 7:*

Cabin # 21, Arm serial # N/A.

General overview as accessible.



*Photo 8:*

Cabin # 21, Arm serial # N/A.

Indication 3.

Close-up of suspect areas seen visually prior to MT approximately 3" below start of bottom bend.



**TECHNICAL SAFETY BC**

Kicking Horse Mountain - Golden Eagle Express Gondola Inspection

Page 7 of 15

*Photo 9:*

Cabin # 21, Arm serial # N/A.

Indications 3 & 4.

Close-up of suspect areas after MT approximately 3" below start of bottom bend.

The top transverse indication runs approximately 2" axially.

The bottom transverse indication runs approximately 4" axially.



*Photo 10:*

Cabin # 21, Arm serial # N/A.

Indications 3 & 4.

Close-up of suspect areas after grinding approximately 3" below start of bottom bend.

The top transverse indication runs approximately 2" axially.

The bottom transverse indication runs approximately 4" axially.



**TECHNICAL SAFETY BC**

Kicking Horse Mountain - Golden Eagle Express Gondola Inspection

Page 8 of 15

*Photo 11:*

Cabin # 21, Arm serial # N/A.

Indications 3 & 4.

Close-up of suspect areas after grinding, then performing follow-up MT approximately 3" below start of bottom bend.

The top transverse indication runs approximately 2" axially.

The bottom transverse indication runs approximately 4" axially.



*Photo 12:*

Cabin # 21, Arm serial # N/A.

Indications 5.

Length approximately 2".

Located on the outside of the arm approximately 1" below the start of the lower bend.



**TECHNICAL SAFETY BC**

Kicking Horse Mountain - Golden Eagle Express Gondola Inspection

Page 9 of 15

*Photo 13:*

Cabin # 21, Arm serial # N/A.

Indications 5.

After grinding indication out with stone.



*Photo 14:*

Cabin # 21, Arm serial # N/A.

Indications 5.

After confirming indication was removed with MTOK.



**TECHNICAL SAFETY BC**

Kicking Horse Mountain - Golden Eagle Express Gondola Inspection

Page 10 of 15

*Photo 15:*

Cabin # 22, serial # 024400.

Overview photo as accessible.



*Photo 16:*

Cabin # 22, serial # 024400.

Typical mechanical marks due to U-bolt clamps at two sections.



**TECHNICAL SAFETY BC**

Kicking Horse Mountain - Golden Eagle Express Gondola Inspection

Page 11 of 15

*Photo 17:*

Cabin # 22, serial # 024400.


Typical section with galvanized coating removed.



*Photo 18:*

Cabin # 22, serial # 024400.

MTOK, no relevant indications were found. No buffing/grinding was performed on this arm.



*Photo 19:*

Cabin # 23, serial # 026800.

Overview photo as accessible.



*Photo 20:*

Cabin # 23, serial # 026800.

Indication 6.

Length approximately 4"

Found on the inside section,  
approximately 2" below start of  
bottom bend



**TECHNICAL SAFETY BC**

Kicking Horse Mountain - Golden Eagle Express Gondola Inspection

Page 13 of 15

*Photo 21:*

Cabin # 23, serial # 026800.

Indication 6.

Length approximately 4".

Found on the inside section, approximately 2" below start of bottom bend.

Indication was removed by grinding stone.

The approximate thickness in the area is between 0.400" – 0.420" and the indication and galvanized coating was removed for remaining 0.380".



*Photo 22:*

Cabin # 23, serial # 026800.

Indication 7.

Length approximately 2".

Found on the inside section, approximately 4" below start of bottom bend.



**TECHNICAL SAFETY BC**

Kicking Horse Mountain - Golden Eagle Express Gondola Inspection

Page 14 of 15

*Photo 23:*

Cabin # 23, serial # 026800.

Indication 7.

Length approximately 2".

Found on the inside section, approximately 4" below start of bottom bend.

Indication was removed by grinding stone.



*Photo 24:*

Cabin # 23, serial # 026800.

Indications 6 & 7.

Both locations were MTOK after grinding the indications out.





ACUREN JOB # 605-J215610  
REPORT # 02

**TECHNICAL SAFETY BC**

Kicking Horse Mountain - Golden Eagle Express Gondola Inspection

Page 15 of 15

**TEST DETAILS: MAGNETIC PARTICLE**

ACCEPTANCE STANDARD:	CSA Z98:19	REVISION:	2024
PROCEDURE/TECHNIQUE:	CAN-MT-14P001	REVISION:	19
TYPE:	Wet Visible	METHOD:	Yoke
PARTICLE BRAND:	Magnaflux	PRODUCT No.:	7HF
PARTICLE COLOUR:	Black	CURRENT:	AC
SUSPENSION:	Oil	MT INSTRUMENT S/N:	3748
CONTRAST PAINT:	Magnaflux	MT INSTRUMENT:	Parker B-300
MAG TIME (SECONDS):	5	DEmag REQUIRED?:	Yes
TECHNIQUE DEMONSTRATED OVER A PAINTED SURFACE?:	Yes	LIFT CHECK BEFORE USE:	Yes
		LIFT WEIGHT S/N:	P16.807
		LIGHTING EQUIPMENT:	Flashlight
		BLACKLIGHT MAKE:	N/A
		LIGHT METER S/N:	11010298
		LIGHT INTENSITY:	> 100 fc (1076 lx)
BATCH NOS. (WHEN REQUIRED):	PARTICLES:	SUSPENSION:	CONTRAST PAINT:
TEST SURFACE CONDITION:	As Coated (Galvanized), as grinded in suspect areas	TEST SURFACE TEMPERATURE:	0°C to 5°C

**TEST DETAILS: VISUAL**

ACCEPTANCE STANDARD:	CSA Z98:19	REVISION:	2024
PROCEDURE/TECHNIQUE:	CAN-VT-14P001	REVISION:	09
METHOD:	Direct	MODEL:	N/A
EQUIPMENT TYPE:	N/A	MANUFACTURER:	N/A
LIGHT SOURCE:	Natural light	ILLUMINATION INTENSITY:	> 100 fc (1076 lx)
ADDITIONAL EQUIPMENT:	N/A	LIGHT METER S/N:	11010298
SUPPLEMENTAL NDT REPORT ATTACHED?:	No	MAGNIFICATION POWER:	N/A
TEST SURFACE CONDITION:	As Coated (Galvanized), as grinded in suspect areas	PROCEDURE DEMONSTRATION REQUIRED?:	No
		CAL. DUE:	Sep 22, 2025



## NONDESTRUCTIVE EXAMINATION

CLIENT: TECHNICAL SAFETY BC  
2889 E 12th Ave suite 600,  
VANCOUVER, BC  
V5M 4T5

Phone: 604.275.3800  
Fax: 604.274.7235

### Acuren Group Inc.

12271 Horseshoe Way  
Richmond, BC, Canada V7A 4V4  
www.acuren.com

A Higher Level of Reliability



PAGE: 1 of 4

DATE: March 18, 2025

ACUREN JOB #: 605-J215610

REPORT #: 03

CONTRACT/PO: N/A

WO: TBD

WORK LOCATION: Guildford & Pipeline Road, Coquitlam

ATTENTION: RYAN HAZLETT  
ryan.hazlett@technnicalsaftybc.com

PROJECT: Gondola Arm Failure

ITEM(S) EXAMINED: Gondola Arm (16)

PART #: See Below MATERIAL: Carbon steel THICKNESS: Various

SCOPE: As directed by the client, perform dry visible magnetic particle inspection of the requested area.

TYPE OF INSPECTION: Magnetic Particle

### RESULT:

As directed by the client, dry visible magnetic particle inspection was performed on Gondola Arm-16 on the selected area. No relevant indications were found, the welds were acceptable at the time of inspection. See the table and photos below.

WELD ID	LENGTH (INCH)	NDE REQUIRED	ITEM(S) EXAMINED	RESULTS
Gondola Arm-016	14	MT	Base Metal	✓

Client acknowledges receipt and custody of the report or other work ("Deliverable"). Client agrees that it is responsible for assuring that acceptance standards, specifications and criteria in the Deliverable and Statement of Work ("SOW") are correct. Client acknowledges that Acuren is providing the Deliverable according to the SOW, and not any other standards. Client acknowledges that it is responsible for the failure of any items inspected to meet standards, and for remediation. Client has 15 business days following the date Acuren provides the Deliverable to inspect it, identify deficiencies in writing, and provide written rejection, or else the Deliverable will be deemed accepted. The Deliverable and other services provided by Acuren are governed by a Master Services Agreement ("MSA"). If the parties have not entered into an MSA, then the Deliverable and services are governed by the SOW and the "Acuren Standard Service Terms" ([www.acuren.com/serviceterms](http://www.acuren.com/serviceterms)) in effect when the services were ordered.

CLIENT: Ryan Hazlett CLIENT SIGNATURE  
ACCEPTED & ACKNOWLEDGED BY  
ACUREN TECHNICIAN: 2<sup>nd</sup> Technician  
REVIEWER: Bob Milne, P.Eng 

TOTAL HOURS	S.T.	O.T.	SHIFT
1 <sup>ST</sup> TECHNICIAN:	See DTR <input checked="" type="checkbox"/> Day <input type="checkbox"/>		
2 <sup>ND</sup> TECHNICIAN:	PM <input type="checkbox"/>		
KILOMETRES:	OTHER CHARGES: YES <input type="checkbox"/> NO <input type="checkbox"/> (IF YES, SEE DAILY OR PROJECT TIME REPORT)		

(Generated Using: CAN-QUA-02F007 R10 - 12/09/2021)

*Photo 1:*

Overview of the Inspected item



*Photo 2:*

Overview of the MT Inspection area.



*Photo 3:*

Overview of the MT inspection area.



*Photo 4:*

Overview of the 8" and 6" length MT area

MT OK





**TECHNICAL SAFETY BC**  
**Gondola Arm Failure**

ACUREN JOB # 605-J215610

REPORT # 03

Page 4 of 4

---

**TEST DETAILS:**

---

ACCEPTANCE STANDARD: Client Information

REVISION: -

PROCEDURE/TECHNIQUE: CAN-MT-14P001

REVISION: 19

TYPE: Dry Visible	METHOD: Yoke
PARTICLE BRAND: Magnaflux	PRODUCT No.: 8A
PARTICLE COLOUR: Red	
SUSPENSION: N/A	
CONTRAST PAINT: N/A	PRODUCT No.: N/A
MAG TIME (SECONDS): >5	DEMAG REQUIRED?: No
TECHNIQUE DEMONSTRATED OVER A PAINTED SURFACE?: N/A	
BATCH NOS. (WHEN REQUIRED): PARTICLES: -	SUSPENSION: -
TEST SURFACE CONDITION: Base Material	TEST SURFACE TEMPERATURE: 10°C to 15°C
	CONTRAST PAINT: -