

SUPPORTING INFORMATION	Incident Date		July 1, 2020
	Location		Prince George
	Regulated industry sector		Electrical - Low voltage electrical system (30V to 750V)
	Impact Damage Injury	Qty injuries	0
		Injury description	None
		Injury rating	None
		Damage description	Fire and smoke damage to recreational vehicle. Most structural damage contained to the area where the fridge was located.
		Damage rating	Moderate
	Inciden	t rating	Moderate
	Incident overview		On the day of the incident, the owner of a Jayco recreational vehicle was preparing for a weekend of camping. They were packing the Recreational vehicle and decided to get some items from the store. The recreational vehicle was plugged into the home exterior receptacle and then they turned on the fridge and left. It was at the store they got a call from a neighbour stating the recreational vehicle was on fire. The fire was quickly extinguished.
INVESTIGATION CONCLUSIONS	Site, system and components		The Jayco recreational vehicle was located in the driveway of the owner's single family dwelling. The unit was purchased with a three way refrigerator, meaning it can operate on propane, 12 Volts DC or 120 volts AC. The fridge is a typical recreational vehicle refrigerator permanently mounted in a vented enclosure. The fire was contained to the area behind the fridge. The recreational vehicle is QAI certified. QAI is a certification agency accredited by the standards council of Canada. This allows QAI to certify that mobile homes meet a minimum standard of safety, outside the limits of the accepted code rules for a province. Both low voltage DC and 120 volt conductors are run through the refrigerator enclosure supplying utility and control functions of the recreational vehicle. Rather than the conductors run in approved manner, and close to the wall they were bundled in a single stack and ty-rapped to each other.
	Failure scenario(s)		The configuration of the conductors running through the refrigerator enclosure caused an non-metallic sheathed cable to rest against the tubing for the cooling system. This tubing is hot and over time the non-metallic conductors would heat up and change the characteristics of the insulating material over the cable and over the individual conductors. This damage, if not addressed, would eventually expose the conductors to contact. The cable is energized only when the recreational vehicle is plugged in. On the day of the incident the owner wanted to cool the fridge down as they went shopping. They plugged in the recreational vehicle energizing the non-metallic cable and as the refrigerator cooled the cable heated up due to it touching the tubing. This process degraded the insulation to the point that a conductor in the cable started arcing against the tubing causing a number of pin holes and releasing the gasses in the cooling system causing an explosion and intense fire for a very brief time. After the gasses vacated the cooling system, the fire was quickly extinguished by a neighbour.











This fire did not burn hot enough to melt copper, and there was one conductor that had been severed. Here is arcing damage to the conductor. This must have been exposed to the bonded tubing of the refrigerator cooling system.















There was no damage to the receptacle or plug for the RV.





This is a picture of the cover for the hot water tank





RV certification Label





This is the data that can be used to find out which factory made the unit





Cover shot of the back of the fridge showing the tubing and the cable "S" image and the arcing damage.