

Incident Summary (Reference #5614113) (Final)

	Incident Date			February 27, 2017
SUPPORTING INFORMATION	Location			Whistler
	Regulated industry sector			Above-Surface Ropeway
			Qty injuries	0
	;	Injury	Injury description	NA
	Impact		Injury rating	None
	= -	Damage	Damage description	NA
		Dai	Damage rating	None
	Incident rating		rating	Insignificant
	Incident overview			Passengers were stranded on a chairlift lift line after it was shut down at the termination of daily operations.
				Incident occurred on a 4 passenger detachable chairlift with uphill and downhill loading.
INVESTIGATION CONCLUSIONS	Site, system and components			The operating contractor has a documented policy ("Lift Guarding Procedure for Last Chair") indicating the method to be used in ensuring passengers are not stranded on a ropeway at the termination of daily operations.
	Failure scenario(s)			Failure to ensure that a carrier occupied by 3 passengers arrived to the unload point prior to shutting the ropeway down at the termination of daily operations.
	Facts and evidence		l evidence	 Incident reports, documents, witness statements, provided by the operating contractor and interviews with ropeway operating personnel provide a sequence of events of the incident: At the termination of ropeway operations the top station attendant called the bottom attendant to indicate that carrier #158 would be the last carrier heading down. Carrier #158 was by occupied staff members. The bottom attendant responded by indicating that carrier #70 would be the last carrier heading up. Both these carrier numbers were indicated in the daily operations log as being the last carrier up #70 and the last carrier down #158 in a "Clearing the Line" section of the log sheet. When carrier #125 arrived to the bottom station the attendant called the top attendant indicating that the last carrier had arrived to the bottom station. Carrier #158 (heading down and occupied by the staff members) and carrier #70 were still approximately 32 carrier lengths away from their respective destined stations. Upon receiving the call from the bottom operator the top attendant shut down the ropeway. In the "Clearing the Line" section of the daily operations log a box for "Re-Confirm chair numbers after stop" was checked as being complete. Both attendants, having finished their shifts, left their respective stations. After approximately 30 minutes 1 of the passengers (staff member) called their supervisor, by mobile phone, indicating that they were stranded on the ropeway lift line. Lift maintenance personnel were notified and the ropeway was restarted and the passenger were brought down to the bottom station. Copy of the lift operations training manual submitted by the operating contractor indicates the methods of ensuring passengers are not stranded on the ropeway after the termination of operations. Specifically mentioning:



Incident Summary (Reference #5614113) (Final)

	 "The last carrier number, plus a description of passengers shall be conveyed by the loading operator to the receiving operator and recorded on the log immediately. To ensure that the last chair reaches the opposite station, a chair number must be recorded from both directions (up and down). "Ensure the last carrier gets to the other end. Call back to confirm. Use the chair number again while re-confirming." It was confirmed that both attendants had written and passed the lift operators exam. It was also confirmed that there are questions in the exam related to the "procedure used in to be sure no one is left on the lift at night" and that both attendants answered those specific questions correctly.
Causes and contributing factors	It is certain that the operating contractor's policies regarding the method of ensuring that passengers are not stranded on the ropeway lift line were not followed, specifically in ensuring the last carrier gets to their respective stations after the termination of operations.

Photos or diagrams (if necessary)